OFFICIAL USE ONLY

IRTIN MARIETTA ENERGY SYSTEMS, INC.

POST OFFICE BOX 2009 OAK RIDGE, TENNESSEE 37831

April 23, 1996

Ms. S. M. Flack ChemRisk 2870 Kalmia Avenue Suite 308 Boulder, Colorado 80301



Dear Ms. Flack:

Document Requested by ChemRisk - Health Studies Agreement

Enclosed are documents requested by E. Choat, a consultant to ChemRisk. These documents have not previously been submitted for review and approval for public release. The Y-12 Plant Classification and Technical Information Offices have reviewed these documents and determined that they contain privileged information as discussed in the Department of Energy (DOE) Order DP 5650.1, "Identification of Defense Programs Official Use Only (OUO) Information." Based on that opinion, these documents are being issued to you as OUO to signify that they contain unclassified sensitive but otherwise uncontrolled information which may be exempt from public release under the Freedom of Information Act. Also enclosed is a copy of DP 5650.1, "Identification of Defense Programs Official Use Only Information," to assist you in the handling of these documents.

We also remind you that even though these lists identify the drawings as being unclassified (U), transmittal of any of the drawings for use in your program will still require review and release by our Classification and Technical Information Offices.

Y/TS-1492 "Drawing List of Buildings 9201-4 and 9204-4 (HVAC Systems by Catalytic),"

Lockheed Martin Energy Systems, Y-12 Plant (April 12, 1996).

Y/TS-1495 "HVAC Drawings of Building 9201-5 (Computer Printout)," Lockheed Martin Energy

Systems, Y-12 Plant (April 17, 1996).

Documents transmitted contain Official Use Only Information. When separated from enclosures, this document does not contain Official Use Only Information.

OFFICIAL USE ONLY

OFFICIAL USE ONLY

Ms S. M. Flack, ChemRisk Page 2 April 23, 1996

If you have any questions, please contact L. L. McCauley at (423) 574-7593 or S. W. Wiley at (423) 576-0263.

Very truly yours,

For R. M. Keyser, Director

Health, Safety, Environment, and Accountability Organization

RMK:djl

Enclosure: As Stated

c/enc: S. W. Wiley (RC)

c: T. R. Butz

C. D. Goins, Jr

F. P. Gustavson

T. W. Joseph, DOE-ORO

R. M. Keyser

L. L. McCauley

S. D. Morris, DOE-ORO

R. J. Spence, DOE-ORO

OFFICIAL USE ONLY

TO:

FROM:

Susan Flack		E. E. C	E. E. Choat			
Company: SFI 1544 North Street Boulder, CO 80304		Environ 672 Rob	Company: Environmental Engineering Consultants 672 Robertsville Road Oak Ridge, TN 37830			
Phone:	303 449 8471	Phone:	423 483 6062			
FAX:	303 939 8318	FAX:	423 482 2605			
e-mail: Echoat@Aol.com		Web Pag http://ww	ge: ww.animedia.com/echoat/			
Date: Octo	Date: October 20, 1999		Pages including this cover page 1			

Message:

I have not found the drawing lists on 9201-4, 9201-5 nor 9204-4 that Steve Wiley is looking for and, I am not certain that I have ever had them in my possession. I do recall looking at drawing lists in Steve's office to identify documents that appeared to be useful. He would then have copies made for my use.

Sorry to be unhelpful.

5.4 COLEX PROCESS DESIGN FEATURES RELATED TO EMPLOYEE HEALTH

5.4.1 Drains, Dams, and Sumps

Process areas within these buildings were designed to contain and collect process losses through leaks and spills in a floor drain system that fed into a series of two collection tanks within each process building. The liquid overflow from the first collection tank fed a second collection tank in series. Mercury collected was routinely removed. Overflow from the second tank went into a sump with a weir outside and adjacent to the building. Overflow from this sump entered the storm sewer system. These systems contributed significantly to reduction of losses to the creek.

5.4.2 Ventilation Systems

In order to help maintain the air at safe air contamination levels, a ventilation exhaust system was used. The system consisted of high-speed fans that provided a ventilation rate of 2,836,000 $\rm ft^3/min$. Both general and spot ventilation systems were provided.

5.5 STANDARD OPERATING PROCEDURES FOR COLEX START-UP

During the operation of the lithium isotope separation cascades at Y-12 during the 1950s and 1960s, many administrative rules and procedures were formulated and put into effect to try to minimize mercury vapor concentrations in the air and contact by the workers. Three procedures pertaining to mercury developed for Colex operations prior to start-up in 1955 are summarized below.

5.5.1 Procedure 1906 - General Operator Duties

Standard Procedure 1906, "General Operator Duties," indicated (Ref. 32) that operations in the Colex plants were continuous and certain responsibilities were thereby assigned to operating personnel. Of interest in this procedure is Item 3, "Keeping Working Conditions Healthful." The procedure pointed out that both the mercury and the lithium hydroxide used in the plant presented some hazard to health because of their toxic and caustic effects, respectively. Important rules and recommendations that applied to Colex areas and their auxiliary buildings were also outlined. Smoking was prohibited in certain process areas, and the carrying of cigarettes or tobacco in such areas was discouraged. Storing or eating food in process areas was not permitted. Before either eating or smoking, operating personnel were required to wash their hands. Safety shoes and personnel were required to wash their hands. company-issue clothing had to be worn in all process areas, and rubber gloves were required in certain other areas and when handling mercury or other process solutions. Operators were responsible for keeping

floors and equipment in process areas clean, and particular emphasis was placed on cleaning up spills of any substance as soon as possible.

Change facilities with separate lockers for work and personal clothing were provided. Shower facilities were available.

5.5.2 Procedure 1859 - Heating and Ventilating System

Standard Procedure 1859 (Ref. 33), entitled "Operating Procedure for Alpha-4 Heating and Ventilating System," gives information on the nature of the process, the nature of materials handled in this building, and extensive ventilation requirements. Such a procedure helped to keep ventilation equipment functioning properly and to lower air contamination levels.

5.5.3 Procedure 1856 - Waste Disposal System

Standard Procedures 1856 (Ref. 34) was entitled "Operating Procedure for Alpha-4 Waste Disposal System." The waste disposal system was used to receive liquid plant waste and, when necessary, to neutralize material before sewering. The system consisted of a waste disposal sump, a system of separators and floor drain sumps for collecting floor wastes and separating the mercury, neutralizing agents, sumps, and sewers. Waste from operations flowed into the waste disposal sump where it was periodically neutralized and sewered. Waste from floor drains flowed into separators and then into tunnel sumps. From these sumps, it was pumped to the waste disposal sump for neutralization disposal. This procedure helped in reducing air contamination by providing instructions on operating the system whereby spilled or leaked mercury could be removed from the operating areas.

5.5.4 Other Procedures

In addition to the above, other procedures were issued that contained specific instructions pertaining to employee health. For example, Procedure 1450, "Operating Procedure for Alpha-4 Solvent Systems," Procedure 1600, "Operating Procedure for Alpha-4 Absorber Systems," and Procedure 1905, "Operating Procedure for Alpha-5 Solvent Systems," contained health-related instructions such as:

- 1. Clean solvent from floors immediately upon spillage.
- 2. Splashing must be avoided.
- 3. Rubber boots must be worn.
- 4. Keep water flowing across the surface of all solvent vessels.

5.6 THE 1955-TO-1956 PROGRAM TO CLEAN UP THE CASCADE AREAS

9201-5 cascades with all of their auxiliary equipment were placed in operation during the first three months of 1955 (Ref. 35). Every effort was made to start the first cascade at the earliest possible date in order to establish the stability of the

Steve W: Happoto mailed old steam plant Roting 81-p (1956) in Hg Files (Fechnical reports 1st I diswers) Joe L. Hart Lake City new data 924 Grave Ave. Thales Wilson Carryville Rt 1 B0x132 Chost - diswings not any good Kills
Here are mod's - not original diswings Davy doesn't have 576-4535 specifically why not night the Manufactured with the K-25 has a survey when we will be survey to the survey of the 2. atalabet 1. conte get in to the front desk? 2. That guy next door has a clearance work with us?
3. PAI guys with clearances? drawing not.



MARTIN MARIETTA ENERGY SYSTEMS, INC.

POST OFFICE BOX 2009 OAK RIDGE, TENNESSEE 37831

March 21, 1996

Ms. S. M. Flack ChemRisk 2870 Kalmia Avenue Suite 308 Boulder, Colorado 80301

Dear Ms. Flack:

Document Requested by ChemRisk - Health Studies Agreement

Per your request, I have provided copies of 57 drawings you have selected from the document entitled "Index of Building Master Plans for Buildings 81-10, 9204-4, 9201-4, and 9201-5 (Y/TS-1472)" directly to E. Choat, a consultant to ChemRisk. These drawings have not previously been submitted for review and approval for public release. The Y-12 Plant Classification and Technical Information Offices have reviewed these drawings and determined that they do not contain classified or controlled information.

Y/TS-1485 "Master Plan Diagrams of Buildings 81-10, 9201-4, 9201-5, 9204-4, and 9204-5," Lockheed Martin Energy Systems, Y-12 Plant (March 13, 1996).

If you have any questions, please contact L. L. McCauley at (423) 574-7593 or S. W. Wiley at (423) 576-0263.

Very truly yours,

gul

R. M. Keyser, Director Health, Safety, Environment, and Accountability Organization

RMK:djl

Enclosure: As Stated

c/enc: A. L. Rothrock, DOE-ORO

S. W. Wiley (RC)

T. R. Butz C:

C. D. Goins, Jr

F. P. Gustavson

T. W. Joseph, DOE-ORO

R. M. Keyser

L. L. McCauley

S. D. Morris, DOE-ORO

R. J. Spence, DOE-ORO

PAUL SMATH EDIS - INIDEX SYSTEM 6- 1535 K25 1007

9201-4 9201-5 9204-2

Phone Interview with Mr. Gene Davy of Y-12 Engineering Records

February 13, 1996

by Susan Flack

Contacts:

Norma Conklin (6-7907) per Jack Lewis at Y-12

Gene Davy (4-1961) per RP at K-25

The Y-12 Engineering Drawing Department is the administrator of the EDIS database which is owned by the Y-12 Engineering Department. The EDIS database is not managed by the Y-12 Records Center Information Management System. The database contains Y-12 engineering drawings by drawing number and has a 26- or 72-character title block field that can be searched for keywords. Database entries for older drawings have only a 26-character title block, so abbreviations may be found in this field for older drawings. The drawing number series can be used to identify older drawings fairly close to the date on which they were The Master Plans for various Y-12 buildings can also be identified using this database.

A suggested approach is to do a building search for all drawings of that building, then narrow the list down to the type of drawing (e.g., HVAC for exhaust fan information). Paul Smith of CT&S can then produce a printout of the list of drawings, including the title block field and drawing series number, which can be reviewed by Y-12 and publicly released to Mr. Ernie Choat. Mr. Choat will review the printout and identify drawings to be pulled, copied (\$1.25 per print) and publicly released for ChemRisk's use in the Dose Reconstruction study. Mr. Davy is willing to provide an estimate of the time required to do the database searches by conducting a preliminary search of the database, based on the table of parameters included in ChemRisk's letter to Steve Wiley dated 2-6-96.

dept on overhead now.

Inyone with a scot. can do sendes

TRM Comments on Lefterto Steve 1-26-96 (that?) do you have angineer that could recognize and guess? could you recommend an expert we could bring in? what we the big holes in the bldg? rough est of no of ofm? we've been told that you've got the best people in the world have it 4-12 we need a "reasonable enging estimate" - can we gown in the bldg. and eyeball it together. d'Illreport to my bosses
gethine (4-12 Enging)
to think we're too dumb to do this Itel write snything you went - 1/0 w can I best help you to help me?

If this just conet be done - then we'll go higher.


Ennest E. Chost 672 Robertsville DR 37830

3014 yrs. ago

483-6062 482-2605 FAX

Started 53 for Juriny Little becomenge, It become consulting position total ofm in Moster Plans

Meeting is Ernie Chost Mortslity Study 1947-1990 - call Tim Joseph for paper copy A 5) roof drawing form installed agripment fan speed - on fan? on special drawing/sketch of fans? Shord 980 + feight = roof grade 2-3M CFC = cert'd for constr (ALE) Contractor sobuilt = modify drawing so it was actually built for speeds (equipment hot) Moster Plan w refs Roof Plan Equipment List MPlan (BIFF 8-10) reed offing or vertly have structure gravings (photo) 1500cfm off the 2 trays? The course in the courser Steam Parts: 1,2+3 #3 had biggerborlers #1,#2 stadio may bestorter send EC the text from Tures report #3 200' stack bothers - ops people? dead induced draft form



height to be 100'.

4. 20 opposed to Hig process buildings (ambient T flue gas),

Steam plant flue gas would be \$300°F.

anto su to bun fuel

Brichis boiler this is

the dosh

then this

is the effluent

is.

refo for Hy in cool = ? (hierarch T)

% Hy emitted 300 st Hy hard 400 for due to condensation

1. 1. 1. 1. 1. * 4 ~ * 1 . (1901) stack 9401-3 9401-1 flue gases 502

flue gases 502

induced au boilers

volume to (when burned gas vicose)

load cooks (165 stm/h) in 1.50k

2200 Velocity constant X 20.25 X (6) ,14 X2200

P.01

FACSIMILE COVER SHEET

To: Susan M. Flack

ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 3/9/96 --

Pages including this cover page -- 2

Monthly Report

Name: E. E. Choat

Month of June 1996

Summary of Activities since your visit of 6/4

- 1. Met with Steve Wiley on June 11 to review drawings and drawing lists.
 - a. Found pretty good lists of 9401-1 and 9401-2.
 - b. Nothing of any help on 9401-3. We need drawings made by the AE who was Burns and McDonnell. Steve has gone back to try to locate.
 - c. Found Wickes Boiler submittal data on boilers, preheaters, & fans. Has good information on gas flows at various loads. I can't copy, but I did make some notes. These must be cleared yet before I can get in hand.
 - d. Steve showed me a set of master plans on 9201-4 --- made in 1970 --- that I had requested. They have not been cleared for release yet. Since this plant was simply shut down when operations ended, I believe these drawings represent all HVAC systems as they existed during the life of the Colex program. I believe these drawings will correlate well with ventilation flow sheets of that time and ventilation study documents. I think it will be possible to locate all exhaust points with good accuracy.

These drawings are very good quality, they are complete, and they are easy to read.

- e. I also looked at a roof plan on 9201-5 that may be helpful in identifying the location of all exhaust fans of Jim Little's report.
- f. Nothing of great help in 9204-4 nor 9201-2. I may have about all I'm going to find.

- 2. June 20, I talked with my boss J. C. Little. He's 84 years old now, lives in North Carolina and is in good health. Among other things, we talked about your study. He remembers it well, but is a bit fuzzy as to details and who wouldn't be after 40 years.
- 3. I have started a report of each of these buildings.

Next Month's Activities

- 1. Correlate & document Master Plan Drawings with Ventilation Study Report.
- 2. Correlate & document 9201-5 drawings with exhaust fans of Little's Study.
- 3. Correlate & document 9204-4 drawings with Baumann report.
- 4. Complete reports on all buildings of Task 1.
- 5. Obtain drawings on Steam Plant & determine stack heights. Bob Schabot (a former steam plant supervisor) & I think that there are two stacks. One is about 200 feet high and the other is 208. We will see.

Needs:

- 1. Clarification of your needs for the steam plants- if any- other than stack heights.
 - a. I believe that 9401-1 & 9401-2 have not burned any coal since the 50's. Are you still concerned about these?
 - b. I believe that 9401-3 burns natural gas a substantial part of the year. When I was in plant, I think they burned gas during the summer and coal during the winter. Too, at one period, they may have used gas about 80% of the time.
 - c. Would it be helpful to your study to establish the history of fuel burned?
- 2. I regret having used all of the hours. I think an additional 50 hours will be needed to complete.

F F Choat

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From:

E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/20/96

Pages including this cover page -- 9

Comment:

This is to transmit the 1st draft of my final report for building 9201-4. Two things are noteworthy.

- 1. This data is based upon drawings that are essentially As-Built. I think that the building is still much as it was in 1956.
- 2. Ventilation systems in this building are about twice as big as 9201-5.
- 3. A report on 9201-5 follows shortly.

Ventilation Systems of Building 9201-4 as Existed in 1956

Building Data

- Building 9201-4 is a large process building. It's overall size is 542 feet x 312 feet. It has 3 floors and a total volume 9,471,300 ft³; It has seven operating bays East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.
- During the time of the Colex Production Plant, the two major steps of process
 operations were identified as "Cascades", & "Absorbers". Cascades occupied all three
 floors of the East & West Crane Bays. Absorbers were located on the third floor of all
 four Control Bays. All building areas were contaminated with Mercury except for the
 Service Area, & Motor Generator (MG) Set Areas.

For this study, a set of simplified building plans have been reconstructed for the purpose of describing characteristics of the building and to illustrate the ventilation systems that were installed in 1956. These plans are included in this report as:

Figure 1 - 1st Floor Plan

Figure 2 - 2nd Floor Plan

Figure 3 - 3rd Floor Plan

Figure 4 -- Section A - A - Building 9201-4

These plans are intended to show the location of various building processes, the location of major exhaust systems, and to provide dimensional information on the structure.

Ventilation

- Initial design was done by an Architect Engineering Company Catalytic
 Construction Company. In general, 100 % outside air was supplied from the
 basement and exhausted via the 3rd floor walls and roof. Construction of this design
 was completed in 1955 but did not provide sufficient ventilation to maintain
 acceptable contamination levels.
- These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Catalytic Construction Company. Because of an increased vaporization of Mercury as temperature increased, more ventilation was provided in summer than in winter. Consequently, design documents and this report often refer to both.

Table 1 is a summarization of the findings of this study regarding the "Winter" Ventilation design for 9201-4. Recorded here are:

- 1. Identities of all process areas of the Colex Production Plant
- 2. Location of all process areas within the building. For example Cascades 9 & 10 occupied all three floors between column lines 4 and 8.
- 3. Room volume of all process compartments
- 4. Fresh air supplied to each compartment
- 5. Air transferred between floors
- 6. Total Room Exhaust it's the sum of air supplied and air transferred from another floor.
- 7. Changes per hour It's a commonly used term to describe ventilation rates. Mathematically, it is equal to cfm x 60 – or cubic feet per hour – divided by the room volume. For this design, the fresh air volumes were used for calculations.

TO 1 303 939 8318

4. A. Contaminated exhaust from the building – it's the air volume exhausted directly to outside. In this design, this air stream was sometimes exhausted via a duct system to the roof. In other instances is was exhausted via propeller fans mounted in the wall at the floor elevation.

It should be noted that the ventilation systems for the Motor Generator (MG) Sets are not included in this table as these areas are not considered to be contaminated. Too, air exhausted from the Maintenance and Service areas are not included in the total

Contaminated Exhaust from the Building. Contaminated Exhaust from the Building.

- exhausted from the Maintenance and Service areas are not included in the total-

-Contaminated-Exhaust from the Building.

Table 1
Winter Ventilation Design for 9201-4

								Contaminated
				Fresh Air	Air From	Room	Chgs.	Exh from
	· · · · · · · · · · · · · · · · · · ·		Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
4-8	Cascade 9 & 10	1	561,000	270510	0	270510	24.6	52000
4-8		2	402,500	181400	218510	399910	27.0	48000
4-8		3	1,209,000	275000	351910	626910	13.6	626910
						0		0
1-4	Chem.Rec., Feed Prep	.1	297,000	93500	0	93500	18.9	93500
1-4	Hang Garden & Inj	2	248,500	129990	0	129990	31.4	129990
1-4	Absorber No. 10	3	311,000	151810	0	151810	29.3	151810
						0		0
8-11	General Stores	1	297,000	27000	0	27000	5.5	5110
8-11	Hang gardens &	2	248,500	34410	21890	56300	8.3	56300
8-11	Absorber No. 9	3	374,000	151810	0	151810	24.4	151810
					1	0		0
11-19	Maintenance	1	642,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0		0
19-22	General Stores	1	297,000	27000	0	27000	5.5	940
19-22	Háng G. & Inj. #9	2	219,800	34410	26060	60470	9.4	60470
19-22	Absorbor # 8	3	374,000	151810	0	151810	24.4	151810
						0		0
22-26	Cascade 7 & 8	1	661,000	270510	0	270510	24.6	52000
22-26		2	402,500	181400	218510	399910	27.0	48000
22-26		3	1,209,000	275000	351910	626910	13.6	626910
	<u></u>			· · · · · · · · · · · · · · · · · · ·		0		D
6 -29	Evaporator	1	297,000	38010	0	38010	7.7	38010
26-29	Hang G. & Inject 7	2	248,000	32000	0	32000	7.7	32000
26-29	Absorber No 7	3	311,000	151810	0	151810	29.3	151810
			9471300	2635180	1188790		16.7	2477380

Table 2 is a summarization of the ventilation design for "Summer" operation.

Table 2 Summer Ventilation Design for 9201-4

				Fresh Air	Air From	Room	Chgs.	Exh from
			Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
4-8	Cascade 9 & 10	1	661,000	297560	0	297560	27.0	48000
4-6	Cascade 9 & 10	2	402,500	199540	249560	449100	29.7	48000
4-8	Cascada 9 & 10	3	1,209,000	591775	401100	992875	29.4	992875
						0	1	0
1-4	Cham.Rec., Feed Prep	1	297,000	154350	0	154350	31.2	154350
1-4	Hang Garden & Inj	2	248,500	189990	0	189990	45.9	189990
1-4	Absorber No. 10	3	311,000	478210	0	478210	92.3	478210
						0		0
8-11	General Stores	1	297,000	29700	0	29700	6.0	5820
8-11	Hang gardens &	2	248,500	37850	24080	61930	9.1	61930
8-11	Absorber No. 9	3	374,000	478210	0	478210	76.7	478210
						0	1	0
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0		0
19-22	General Stores	1	297,000	29700	0	29700	6.0	1040
19-22	Hang G. & Injection #9	2	219,800	37850	28660	66510	10.3	66510
19-22	Absorbor # 8	3	374,000	478210	0	478210	76.7	478210
			***************************************			0	1	0
22-26	Cascade 7 & 8	1	661,000	297560	0	297560	27.0	48000
22-26	Cascade 7 & 6	2	402,500	199540	249560	449100	29.7	48000
22-26	Cascade 7 & 8	3	1,209,000	591775	401100	992875	29.4	992875
	······································					0		0
26-29	Evaporator	1	297,000	97810	0	97810	19.8	97810
26-29	Hang G. & Inject 7	2	248,000	35200	0	35200	8.5	35200
26-29	Absorber No 7	3	311,000	478210	0	478210	92.3	478210
	·····		9471300	4860840	1354060		30.8	4703040

Previous reports of Mercury loss to the atmosphere via the building exhaust systems have been based upon the assumption that ventilation systems of 9201-4 were essentially the same as 9201-5. Since this study has indicated a considerable difference in contaminated air exhausted, a new estimate has been made for Mercury loss to the atmosphere for the period of the 2nd quarter of 1955 through the 1nd quarter of 1958. The results of these calculations are exhibited in Table 3. Assumptions were:

- 1. Winter ventilation rates apply for the 1st & 4th quarters.
- 2. Summer ventilation rates apply for the 2nd & 3rd, quarters.
- 3. Mercury concentrations were as reported in "Wilcox", page 111.

OAK RIDGE HEALTH STUDIES OAK RIDGE DOSE RECONSTRUCTION

INITIAL TASK 2 PROGRESS REPORT INVESTIGATION OF MERCURY RELEASES FROM LITHIUM ENRICHMENT

SEPTEMBER 1995

Table 3 Calculation of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

1		Exhaust		Conc.	T	Efflu	ent	
1	Quarter	Cfm	m³/day	mg/m³	mg/day	grame/day	ibe/day	1bs/qtr
	2	2050740	83630818	0.1	8363082	8363.1	18.44	1659
1	_	2050740	83630818	0.25	2 15+07	20907.7	46.09	4148
	3	1446429	58986532	0.25	1.5E+07	14746.6	32.51	2928
		1446429	58988532	0.12	7078384	7078.4	15.60	1404
	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903
	3	4703040	191793734	0.05	9589687	9589.7	21.14	1903
	 	2477380	101029538	0.04	4041182	4041.2	8.91	802
	-	2477380	101029538	0.04	4041182	4041.2	8.91	802
	2 -	4703040	191793734	0.03	5753812	5753.8	12.68	1142
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401
	1	2477380	101029538	0.02	2020591	2020.6	4.45	401

complete to 1962 (40)

1. Contrary to assumptions of previous studies, the ventilation systems for 9201-4 are not the same as 9201-5. From this study, the total contaminated air exhausted from these buildings was:

<u> </u>	W	inter	Su	mmer
	Cfm	Air Changes	Cfm	Air Changes
9201-5	1684410	10.7	2357755	15.9
9201-4	2477380	16.7	4703040	30.8

2. Mercury lost to the atmosphere appears to be much higher than that reported previously.


3. As observed from the following table, contaminated air exhausted is predominately from the third floor and roof, i.e. about 90%.


Winter Summer


Winter	Summer	
1st Floor	2.6 %	11.6 %
2nd Floor	14.4 %	0 %
3rd Floor	50 %	60.7 %
Roof	33 %	28.1 %


References:

- 1. General Ventilation Study Bldg. 9201-4 design notes
- 2. Building 9201-4 4 Tray Rooms design sketch
- 3. Proposed Cascade Ventilation design sketch
- 4. Proposed Absorber Ventilation design sketch
- 5. McAlister, Don. General Ventilation-Bldg. 9201-4, 8/15/55 design sketch
- 6. EM-708 through EM-729, Master Plan Drawings completed 1970. These are believed to represent As-Built conditions for the Colex Production Project. Since this building has not been modified since shut-down, these drawings should be an accurate record of 9201-4 ventilation systems of 1996 as well.
- 7. Catalytic Construction Company's Ventilation Flow Sheets
- 8. Catalytic Construction Company's Construction Drawings









To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/27/96

Pages including this cover page -- 1

Message:

Yesterday, I received from you 5 ½ pages of industrial Hygiene reports and notes on 9201-2. In the middle of page 6, my FAX ran out of memory and that ended that.

At the time of that FAX -- my computer and printer was off - I was in Steve's office reading the notes that he had copied for you. Among those, there was only one that seemed to be of any help to me - the notes on 9201-2. Steve made a copy for me.

From what I have, there appears to be 8 pages in the document you were sending, and I have all of it.

If there's more, try me again.

My goal for today is to give you a report on 9204-4 before the end of the day.

TO 1 303 939 8318 P.01

FACSIMILE COVER SHEET

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/27/96

Pages including this cover page -- 6

Message:

This is to transmit the 1st draft of my final report for building 9204-4.

To: Susan M. Flack

ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/29/96

Pages including this cover page -- 5

Message:

This is to transmit the 1st draft of my final report for building 9201-2.

August 1, 1996

Susan M. Flack ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Dear Susan:

This is transmit reports of buildings 9201-4, 9201-5, 9204-4, 9201-2, and 81-10. I believe that I have taken care of the comment you gave me on the phone. Call me if not or when there are more.

Sincerely,

Oncument No.	Peachir Iton (Compan		°/ Z
Y/TS-1561	Author's Telephone Ne. 6-0263	Acct. No. 2366000 \$	Date of Request 7/29/96
Unclassified Title: VENTILATION SYST			
9201-5 AS EXISTED IN	1756 (DRAFT)	7 AND
Author(s) _ E.E. CHOAT			
	Progress/Status		☐ Thesis/Term Paper
Oral Presentation (identify meeting, sponsor, local	tion, dete):		
			
Journal Article (Identify Journal):			
Other (Society): To Be Released to	ChemRisk, Phase	II	
Document will be published in proceedings] Yes		
Document will be distributed at meeting No] Y⇔		
Document has patent or invention significance No	Yes (Identify)		
		pleted By Requesting Division)	
TECHNICAL CLASSIFICATION REVIEW (Divisional Classifica	tion Representative)	DOCUMENT REQUEST APPRO	VCD 10 1:
Title(s):		ATO O LA	VEU (DIVISION OF Department)
DOCUMENT: LIMI U CHINON		Signature /	1/29/96
Company	1/29/96		,
V Signature	Dem	Signature	Dom
THE REMAINDER OF THIS FORM T	O BE COMPLETED BY	THE TECHNICAL INFORMA	TION OFFICE
Internal Distribution	DISTRIBUTION		
External Distribution		Distribution: UCN-77218 Y-12 Central Files Y-12 RC	DOE F-1332.18 Document
TID-4500 Category or	Copies to OSTI		Y-12 RC Y-12 RC
ANNOUNCED IN: ERA Atomindex (Available from NTIS M-3679 Catagory	3)	S.W. Wile	у
ANNOUNCE IN AWDR (Available from OSTI)	☐ ANCR	R.M. Key	<u> </u>
istribution Remarks: Unlimited (Chenfless	(e)	·	
	/		
ate Received Dem total	APPROVAL AND RELE	ASE	· · · · · · · · · · · · · · · · · · ·
oto Received Deta Initiated 7/29/96			
Z CLASSIFICATIONS.	- Editor		Date
Halas Hickory find	50 - LV	awed/442	
OCUMENT:	Patent	Office /	Dete
1 mm Huckey St. 1			
Wasses & Co.	 _		Dete
Sigma Sigma			Oate
V-12 Classification Office	6		06.6
(y			
PROVED FOR: Declaration Release	e subject to use of the fo	llowing admonitory markings and	conditions:
Oleofelmer Copyright Petent Caution	Other	ant-	7/2 6,
The visit was the same than	 	Pachilled Inform	tion Office // CO /5/4

To: Susan M. Flack

McLaren Hart 1135 Atlantic Avenue Alalmeda, CA 94501

Phone:

Fax:510 521 1547

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 8/6/96

Pages including this cover page -- 2

Message:

This is to transmit the 1st draft of my final report for Y-12 Steam Plants, Buildings 9401-1, 9401-2 & 9401-3.

Ventilation Systems of Building 9201-5 as Existed in 1956 – (revision 1) by E. E. Choat


Building Data

Building 9201-5 is a large process building. It's overall size is 542 feet x §12 feet. It has 3 floors and a total volume 9,471,300 ft³. It has seven operating bays – East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.

- Figure 1 is a plan of the 3rd floor of the Colex Production Plant 9201-5 as it was in 1956. As seen here, "Absorbers" (a major process step) occupied the entire 3rd floor of three bays. Too "Cascades" occupied the entire area of two very large bays. The same Cascades also occupied the 1st and (3rd) floors as well. This plan is included here to provide dimensional information on the structure, to show the location of various building processes, and the location of major ventilation exhaust points.
 - Figure 2 is a sectional view of the building. It is included here to provide pertinent building elevations, and to further identify the location of building processes.
 - All building areas were contaminated with Mercury except the Service Area, & the Motor Generator Set Area.


Ventilation

- The initial design of the ventilation systems for this building was done by an Architect Engineering Company Catalytic Construction Company. Supervision of this design was done by Union Carbide Plant Engineering personnel. The HVAC Design Department was responsible for review and approval of all Heating, Ventilating, and Air Conditioning (HVAC) plans, and consequently, were intimately familiar with the details of these systems. J. C. Little was then the Head of the HVAC Design Department. At that time I worked in Jim Little's department as an HVAC Design Engineer.
- Construction of this design was completed in 1955, but did not provide sufficient ventilation to maintain acceptable contamination levels.
- These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Union



Z •

Figure 2 Section A - A ---- Building 9201-5



cfins not on drawing

- Carbide, HVAC Design Department personnel. J. C. Little, the was a major influence in these modifications.
- Subsequent to the shutdown of the Colex Production Plant in 9201-5, the building was stripped of all process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflected conditions that existed in 1956.
- For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in 1956. The most significant document of this search is a flow sheet identified as "General Ventilation 9201-5" it has no drawing number. This document:
 - 1. Is a diagram of all ventilation systems of 9201-5 as of 8/12/55.
 - 2. Was drawn by Don McAlister a man who worked for the HVAC Design Department.
 - 3. It shows three designs:

the original Catalytic design

an upgraded ventilation design for winter operation an upgraded ventilation design for summer operation

Note:

In this building, large surface areas of Mercury were exposed to the ambient air. As air temperatures increased from winter time to summer operation, more Mercury vaporized and entered the ambient. Contamination levels, then tended to increase during the summer months. To control the contamination level, higher ventilation rates were planned for summer.

The following table reflects the total ventilation provided by the original design, and for the upgraded design. The increases in ventilation shown here seem to be consistent with operating problems that were experienced and with documented evidence of modifications that were made for improvement.

	Contaminate	d Exhaust	Building Air Change Rate (based on Summer design)
	Winter	Summer	
Initial Design	1308545	1308545	8.3 🗸
Upgraded Design	(1684410) 7		10.7
Upgraded Design		2357755	15.9

r (1526610 FROM

Details of the upgraded design for winter operation are summarized in Table 1. Here all major operations have been located with respect to building column lines and building floors. Too, air supplied and exhausted are given along with volumes of spaces and air change rates.

aulmiet design. XIS

Jan 20,1997 03:04PM

Table 1
Winter Ventilation Rates for 9201-5 Operations

							Contaminated
			Fresh Air	Air From	Room	Chgs.	Exh from
		Room	Supply	Floor Below	Exhaust	per	Building
System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
Cascade 5 & 6	l	661,000	108000	U	108000	9.8	34000
Cascade 5 & 6	2	402,500	184200	74000	258200	27.5	108000
Cascado 5 & 6	3	1,209,000	130200	150200	280400	6.5	280400
		207.000	70000		10000	2.0	10000
Feed Prep		297,000	10000	0	25000	6.0	25000
Chem.Rec.	2	248,500	25000	0		4.8	25000
Extraction & Inject.	3	311,000	25000	U	25000	4.0	25000
St	1	297,000	18000	0	18000	3.6	18000
Storage Hang gardens &Injection	2	248,500	20000	0	20000	4.8	20000
Absorbers 5 & 6	3	374,000	115000	()	115000	18.4	115000
			<u> </u>				
Maintenance	1	842,000	80000	0	80000	5.7	<u> </u>
Service	2	561,500	77800	0	77800	8.3	ļ
Feed Storage	1	297,000	50000	0	50000	10.1	50000
Hang G. & Inj.	2	219,800	71000	0	71000	19.4	71000
Absorbors 1 & 2	3	374,000	120000	o	120000	19.3	120000
Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	108000
Cascades 1&3 and 2&4	2	402,500	96000	0	96000	14.3	120000
Cascades 1&3 and 2&4	3	1,209,000	236400	-24000	236400	11.7	212400
Storage	1	297,000	18000	0	18000	3.6	1200
Hang G. & Inject	2	248,000	40000	16800	56800	9.7	56800
Absorbers No 3&4	_	311,000	151810	0	151810	29.3	151810
Whanthera MA OWA	 	9471300				10.7	1526610
Notes:							

440,400

Details of the upgraded design for winter operation are summarized in Table 1. Here all major operations have been located with respect to building column lines and building floors. (Too), air supplied and exhausted are given along with volumes of spaces and air change rates.

Winter Ventilation Rates for 9201-5 Operations

			۸ ۵ ۵/۱					Contaminat	
			Some 204					ed	ے
				Fresh Air	Air From	Room	Chgs	Exh from	
İ									<u>a</u>
			Room	Supply	Floor	Exhaust	per	Building	
			200022	~	Below		1 0	j j	:
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	$_{ m cfm}$	Z422,40c
4-8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8√	34000	Juzzz
4-8	Cascade 5 & 6	2	402,500	184200	74000 √	258200	27.5/	108000	5'0
4-8	Cascade 5 & 6	3	1,209,000	130200	150200√	280400	6.5	280400)
4-0	Cascado o de o	<u> </u>	<u> </u>			-0-	i	-0-	_
1-4	Storage 1;	1	297,000	10000	0	10000	2.0	10000	} 6050°
1-4	Feed Prep	2	248,500	25000	0	25000	6.0	25000	$ (\theta_0) $
1-4	Chem.Rec.		311,000	25000	0	25000	4.8	25000	(
1-4	Extraction ection	3_	311,000	20000	· · · · · ·	<u> </u>	1.0	-B-	
0.11	Storage	1	297,000	18000	0	18000	3.6	18000	, را
8-11	Hang gardens	$\frac{1}{2}$	248,500	20000	0	20000	4.8	20000	} 153,00°
8-11	Hang gardens &Injection		240,500	20000		20000	4.0	20000	
0.11	Absorbers 5 & 6	3	374,000	115000	0	115000	18.4	115000	ر ا
8-11	Absorbers 5 & 6	3	374,000	113000		<u> </u>	10.1	-B-	
71 70	Maintenance	1	842,000	80000	0	80000	5.7	0	
11-19	Maintenance	$\frac{1}{2}$		77800	0	77800	8.3	D	
11-19	Service	<u>z</u> _	561,500	11800	0	-D	0.5	8	ł
	7 10		207.000	70000		50000	10.1	50000	1
19-22	Feed Storage	1	297,000	50000	0			71000	341,00C
19-22	Hang G. & Inj.	2	219,800	71000	0	71000	19.4		()
19-22	Absorbers 1 & 2	3	374,000	120000	0	120000	19.3	120000	17
						<u>_0</u>		0	
22-26		1	661,000	108000	0	108000	9.8	108000])
	2&4	<u> </u>	100 700	00000		00000	110	-A055010-	140 H
22-26	Cascades 1&3 and	2	402,500	96000	0	96000	14.3	<u>(</u> 3255910	1:77
	2&4	<u> </u>		222122	077070	700010	11.7	CT00010	1 \
22-26	Cascades 1&3 and	3	1,209,000	236400	351910,/	588310	11.7	<u>[5883107</u>	1001
	2&4	 -				2		-0-	۱ " ۱
	<u>~</u>	-	007.000	10000		19000	3.6	1200	2 440,41 69
26-29	Storage	1_	297,000	18000	0	18000		56800	16269281
26-29		2	248,000	40000	16800 ✓	56800	9.7		("
26-29	Absorber No 3&4	3	311,000	151810	0	151810	29.3		1
		↓	9471300	1684410	592910		10.7	1526610	; k
	Notes:	<u></u>	<u> </u>		<u> </u>		<u></u>	100010	<u> </u>
	1. Air Changes bas	ed upo	n fresh air	supplied.				1878520	

310 X95X

258 X58 x

Karikoss

350XS8X

310×95×

258X58X

Q: why used VS. 2,836,000 cfm Presh sin YEX-21 fere?

Details of the upgraded design for summer operation are summarized in Table 2. From this, it may be observed that almost-all-of-the-building-exhaustis from the 3rd floor. In fact, all is exhausted via roof fans except for 539,200 cfm that is exhausted via louvers in the East & West Crane Bays.

Camera Jasign, XI	5			able 2				_	900
Low Joseph	Su	mmer	Ventilation	Rates for	9201-5 Ope	rations			
(Show	Ι	1			1		1	10	1
				<u> </u>				Contaminated	٩
					Air From	Room	Chgs	Exh from	e
			Room	Supply	Fl. Below	Exhaust	per	Building	1
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm	
4-8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8√	34000	1)
4-8	Cascade 5 & 6	2	402,500	184755	74000✓	258755	27.5/		۱۶:
4-8	Cascade 5 & 6	3	1,209,000	263000	222755	485755	13.1	485755	
	0					4		4	?; }
1-4	Storage 1	1	297,000	10000	0	10000	2.0	10000])
1-4	Feed Prep	2_	248,500	25000	0	25000	6.0	25000] {
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000	ادر
	Extraction Tylest	51 ~				ቀ]
8-11	Storage	1	297,000	18000	0	18000	3.6	5000])
8-11	Hang gardens &Injection	2	248,500	20000	13000√	33000	4.8	25600	} } }
8-11	Absorbers 5 & 6	3	374,000	275000	7400 √	282400	44.1/	282400	ر [
						-8			1
11-19	Maintenance	1	842,000	80000	0	80000	5.7	D	1
11-19	Service	2	561,500	77800	0	77800	8.3	0	1
						0		-0	1
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000	1)
19-22	Hang G. & Inj.	2	219,800	76000	0	76000	20.7	76000](
19-22	Absorbers 1 & 2	3	374,000	290000	0	290000	46.5	290000	 } -
						-0-		-0-]
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	88000	
22-26	Cascades 1, 2, 3,4	2	402,500	96000	20000	116000	14.3	120000] [
22-26	Cascades 1, 2, 3,4	3	1,209,000	502000	? <i>(</i> }4000	498000	24.9	498000	1)
						-0-		-0-	1
26-29	Storage	1	297,000	18000	0	18000	3.6	1200	?
26-29		2	248,000	40000	16800	56800	9.7	24000] }
26-29		3	311,000	249000	32800	281,800	48.0	281800])
			9471300	2515555	3827557		15.9	2357,755	1

Table 3 is a tabulation of exhaust fan locations, design air volumes for summer and a calculated percentage of the building total.

Table 3 Fan Locations, Summer Air Volumes, & Per Cent of Total for Building Exhaust Points

						Exit	0
		grade	cfm	%	Orientation	Point	
V	W. Crane bay Roof exh	1061	140000	6%	up	\mathbf{roof}	
1	East Crane Bay Roof Exh	1061	280000	12%	up	roof	
V	Absorbers 3&4	1040	210510	9%	up	roof	
	From Floors Below	1040	138500	6%	up	roof	
V	Absorber 1&2	1040	334875	14%	up	roof	
	From Floors Below	1040	237160	10%	up	roof	
/	Absorbers 5 & 6	1040	211470	9%	up	roof	
	From Floors Below	1040	99040	4%		roof	
/	Extraction	1040	127000	5%	up	roof	141
	777 G 1 37 /2 13	1050	170000	00/	1	11	- 15 13
_	W. Crane bay North wall		179000	8%	horizontal	wall) too
E	8. Crane bay So Wall	1050	179000	8%	horizontal	wall	Somers
	W. Crane bay North wall	1050	90600	4%	horizontal	wall	Slowers
6	8. Crane bay So Wall	1050	90600	4%	horizontal	wall	
6.	D. Claire Bay So Wall	1000	0000	-0%-			
	North Wall - (2nd)Floor	1010	40000	2%	horizontal	wall	
			2357755√	100%√]
	6		٧\$.	_			
	Zink? on	. drzwina	2,836,00	.cəl			
	9/ 4	·	116	k a			

Table 4 contains data that is similar to that shown in Table 3, except it is for "winter" operation.

This percentages that were calculated in both table 3 and table 4 are also included in Figure 2.

Table 4 Fan Locations, Winter Air Volumes, & Per Cent of Total for Building Exhaust Points

	i i			Exit	عرا
grade	cfm	%	Orientation	Point	[
1061	232400	15%	up	Roof	
1061	328000	, 21%	up	Roof	
		L			
1040	115330	8%	up	Roof	
1040	138500	9%	up	Roof	
			-17%		
1040	104590	7%	up	Roof	
1040	237160	16%	up	Roof	
			-22%		
1040	104590	7%	up	Roof	
1040	99040	6%		Roof	
			-13%-		
1040	127000	8%	up	Roof	
]
1050	0	0%	horizontal	Roof	M
1050	0	0%	horizontal	Roof	1/2
					4
1010	40000	3%	horizontal	Roof	1/4
	1526610 🗸	100%√			
	1061 1061 1040 1040 1040 1040 1040 1050 1050	1061 232400 1061 328000 1040 115330 1040 138500 1040 104590 1040 237160 1040 99040 1040 127000 1050 0 1010 40000	1061 232400 15% 1061 328000 21% 1040 115330 8% 1040 138500 9% 1040 104590 7% 1040 237160 16% 1040 104590 7% 1040 99040 6% 1050 0 0% 1050 0 0% 1010 40000 3%	1061 232400 15% up 1061 328000 21% up 1040 115330 8% up 1040 138500 9% up 1040 104590 7% up 1040 237160 16% up 1040 104590 7% up 1040 99040 6% -13% 1040 127000 8% up 1050 0 0% horizontal 1050 0 0% horizontal 1010 40000 3% horizontal	grade cfm % Orientation Point 1061 232400 15% up Roof 1061 328000 21% up Roof 1040 115330 8% up Roof 1040 138500 9% up Roof 1040 104590 7% up Roof 1040 237160 16% up Roof 1040 104590 7% up Roof 1040 99040 6% Roof 1040 127000 8% up Roof 1050 0 0% horizontal Roof 1050 0 0% horizontal Roof

3,836,000 1-

Table 5 is a comparison of the Catalytic Design, the Upgrade Design, and ventilation rates as reported by J.C. Little, March 14, 1956. This comparison would indicate that Little was using "Summer" ventilation rates for his study. In view of a very close agreement of between Little's Report and Flow Sheet Data, this comparison would indicate that both were applicable to the same period of time.

Sum-wintex/s

Table 5 Comparison of Flow Sheet Ventilation Rates with Those Reported by Little

			Exhaust Air Flow Cfm							
			From	Vent. Flow S		From Little				
			Cat. Des.	Winter	Summer	Report				
cols.	Operation	Floor		Upgraded	Upgraded					
1-4	Storage	1		10-	- 10					
1-4	Feed Prep. & Extraction	2	35000	35000	35000	35000				
1-4	Chemical Recovery	3	25000	25000	25000	25000				
				60000	60000					
4-8	Cascades 5 & 6			34,000 422 400						
4-8	All Floors	1,2&3	376400	√ 388000 ?	555755 🗸	545000				
				2600	2600					
8-11	Stores	1		1155600	1315600					
8-11	Injection Pumps 5 & 6	2	0	25600	25600	25600				
8-11	Absorbers 5 & 6	3	99600	130000	290000	292000				
			_							
	Feed Storage	1	0	50000	50000	50000				
19-22	Absorbers & Injection 1A	2	70325	71000	76000	50000				
19-22	Injection Pumps 1 & 2	2	15000	1 50000)?	↑ (5000D?	24000				
19-22	Absorbers 1 & 2	3	107110	120000	290000	292000				
				1 291000	466000	_				
22-24	Cascades 1 & 3					ļ				
22-24	1st Floor		36000	44000	44000	54000				
22-24	2nd Floor		8000	40000	40000	60000				
22-24	3rd & 4th Floor		202000	220200	249000	257000				
		<u> </u>	20830	1648740D	106,000					
24-26	Cascades 2 & 4									
24-26	1st Floor		36000	44000	44000	54000				
24-26	2nd Floor		8000	80000	80000	60000				
24-26	3rd & 4th Floor	<u> </u>	202000	220200	249000	257000				
	Storage	1	54,00		1305110					
26-29	Absorbers 3 & 4	3	88110	131850	281110	292000				
26-29	Injection Pumps 3 & 4	2	0	24000	24000	24000				
	Totals		1308545	1698850	2408465	2396600√				

Table 6 is simply a repetition of Little's arithmetic. Input to this consist of air flow rates and concentration rates from Table 1 of Little's report. Other columns are simply details of the calculation. The resulting lbs/day effluent are the same as reported,—ef-course.

Littlen 1. XIS

Table 6 Validation of Little's Arithmetic

				txhz	lõk		
	building	Exhaust		Conce	entration		
	col. lines	Cfm	m³/day	mg/m³	mg/day	grams/day	lbs/day
Absorbers 1 & 2	19 - 22	¹ 292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 3 & 4	26 - 29	√292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 4& 60	8 - 11	/292000	11907994	0.12	1428959	1428.959	3.15
Absorbers & Injection 1A	19 - 22	√50000	2039040	0.28	570931.2	570.9312	1.26
Injection Pumps 1 & 2	22 - 26	V24000	978739	0.3	293621.8	293.6218	0.65
Injection Pumps 3 & 4	26 - 29	√24000	978739	0.25	244684.8	244.6848	0.54
Injection Pumps 5 & 6	8 - 11	√25600	1043988	0.53	553313.9	553.3139	1.22
Chemical Recovery	1 - 4	√ 25000	1019520	0.19	193708.8	193.7088	0.43
Feed Storage	19 - 22	√ 50000	2039040	0.25	509760	509.76	1.12
Feed Prep. & Extraction	1-4	√35000	1427328	0.1	142732.8	142.7328	0.31
Cascades 1 & 3	22 - 24						
1st Floor		√54000	2202163	0.2	440432.6	440.4326	0.97
2nd Floor		√60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.21	2200940	2200.94	4.85
Cascades 2 & 4	24 - 26						
1st Floor		/54000	2202163	0.21	462454.3	462.4543	1.02
2nd Floor		√60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.18	1886520	1886.52	4.16
Cascades 5 & 6	4-8						
All Floors		√ 545000	22225536	0.13	2889320	2889.32	6.37
		2396600	97735265				38.31

References

- Solvent Losses Through Ventilation Exhaust Systems, Building 9201-5, Little, J. C., March 14, 1956.
- 2. "General Ventilation 9201-5", A Y-12 Drawing, drawn by McAlister 8/12/55.
- 3. Y/EX-24, Mercury at Y-12, (Unclassified version of Y/EX-21), Compiled by The 1983 Mercury Task Force, August 18, 1983.
- 4. Catalytic Construction drawings and design notes. dtes?

uatoat.	l i				Ţ	zble 7 beet1					
اد	.X15				هر	рееп					
hat. '											
Hállo [,			n for Hg Exh	austed to	Atmospher	e from Buildi	ng(9201-5	5)		
			Exhaust u	4							
				1846	Bldg. Avg				.051	Wilcox	
-	Year		Exhaust N	3	Conc.			nt २५५३,5		Report	
	4055	Qtr.		m³/day	mg/m³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr	
	1955	1	1308545	53363512		10672702 8004527	10672.7	23.53	2118	1716 1287	
-		2 3	1308545 1308545	53363512 53363512	0.15	16542689	8004.5 16542.7	17.65 36.47	1588 3282	2573	
		4	1308545	53363512	0.31	11206338	11206.3	24.71	2223	3603	
				162256377	 	7470765	Annual	Totals	9212	9179	9212
			1526610								1483
1526610	1956	1	1684419	68691587	0.12	8242990	8243.0	18.17	1038	1888	1400
7 7		2	2357755	96151135	0.10	9615114	9615.1	21.20 19.08	1908	1716	
ľ		3	2357755	96151135	0.09	8653602 4121495	8653.6 4121.5	9.09	1717 - 818 -	1544 1029	MAI
1526610		4_	-1684410	68691587	0.00	4121495	Annual	Totals	6078	6177	741 5849
1326610									-		
1526610	1957	1	1084410-	68691587	0.04	2747663	2747.7	6.06	545 -	686	494
1506010		2	2357755	96151135	0.04	3846045	3846.0	8.48	763	686	
		3	2357755	96151135	0.03	2884534	2884.5	6.36	572	515	247
		4	-1684410-	68691587	0.02	1373832	1373.8	3.03	273	343 2230	2076
							Annual	Totals	2158		
1526610	1958	1	- 1684410	6 8694587	0.02	1373832	1373.8	3.03	-273	343	247
•		2	2357755	96151135	0.02	1923023	1923.0	4.24	382	343	
-		3	2357755	96151135	0.02	1923023	1923.0	4.24	382	343	201
4610		4	1684410	68691587	0.03	2060748	2060.7	4.54	409	343	37/ 1382
1526610							Annual	Totals	#445	1372	
1526610	1959	1	- 1684410	68691587	0.04	2747663	2747.7	6.06	545 -	515	494
• -		2	471551	19230227	0.05	961511.4	961.5	2.12	191		
		3	471551(4)	19230227	0.04	769209.1	769.2	1.70	153		74
305332		4	-336882 4	/ 13738317	"	412149.5	1)	, 0.91	202		
				12451683	1 Sign	113145	Annual		970		7.19.
3 05332	1960	1	336882(V)			343457.9		0.97 (0.76)	-68-		9 19. 74
ערייע		2	471551 ^(N)	19230227	0.04	769209.1	769.2	1.70	153		
_		3	471551(1)	19230227	0.05	961511.4	961.5	2.12	191		74
305332		4_	336882(0)	1 3738317	0.03	412149.5		0.91	- 82 -		492
	 -						Annual	Totals	493		
		 			d		Total for a	l all vears	20351	19473	
		ļ				<u> </u>	Total lol c	l years	10001	10-110	19992
						200 500	7				i Piac
	Notes) A C	_t:t f_	i 14 0 4 1 1 1 1	373550	رد				19923 19920
			Winter" ventil: Summer" ven								
	2. ASS	concen	trations taken	illialion rales	ılı zılu x 1" renort r	oru quarter na 110 with	minoracorre	ctions by	Susan Fla	ack [
_>	3. ng	en nroc	ess was shut	down ventil:	ation was	reduced to	minimum/as	dictated b	5050		
-7	con	centrat	ion level. It is	estimated that	at the stan	dby ventila	tion was 20%	6 of the de	esign rate	.	
						•			-	-	
	ļ						 	1		<u>_</u>	
	L		l	<u> </u>	<u> </u>			l	<u> </u>	1	I

August 1, 1996

Ventilation Systems of Building 9201-5 as Existed in 1956 by E. E. Choat

Building Data

- Building 9201-5 is a large process building. It's overall size is 542 feet x 312 feet. It has 3 floors and a total volume 9,471,300 ft³. It has seven operating bays East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.
- Figure 1 is a plan of the 3rd floor of the Colex Production Plant 9201-5 as it was in 1956. As seen here, "Absorbers" (a major process step) occupied the entire 3rd floor of three bays. Too, "Cascades" occupied the entire area of two very large bays. The same Cascades also occupied the 1st and 3rd floors as well. This plan is included here to provide dimensional information on the structure, to show the location of various building processes, and the location of major ventilation exhaust points.
- Figure 2 is a sectional view of the building. It is included here to provide pertinent building elevations, and to further identify the location of building processes.
- All building areas were contaminated with Mercury except the Service Area, & the Motor Generator Set Area.

Ventilation

- The initial design of the ventilation systems for this building was done by an Architect Engineering Company Catalytic Construction Company. Supervision of this design was done by Union Carbide Plant Engineering personnel. The HVAC Design Department was responsible for review and approval of all Heating, Ventilating, and Air Conditioning (HVAC) plans, and consequently, were intimately familiar with the details of these systems. J. C. Little was then the Head of the HVAC Design Department. At that time I worked in Jim Little's department as an HVAC Design Engineer.
- Construction of this design was completed in 1955, but did not provide sufficient ventilation to maintain acceptable contamination levels.
- These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Union







Figure 2 Section A - A --- Building 9201-5



- Carbide, HVAC Design Department personnel. J. C. Little, the was a major influence in these modifications.
- Subsequent to the shutdown of the Colex Production Plant in 9201-5,
 the building was stripped of all process equipment so that new and
 different processes could be installed. Ventilation systems were then
 modified as necessary to accommodate the requirements of the new
 process. During these modifications, drawings of the building
 ventilation systems were changed according to the new design, and
 consequently, no longer reflected conditions that existed in 1956.
- For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in 1956. The most significant document of this search is a flow sheet identified as "General Ventilation 9201-5" it has no drawing number. This document:
 - 1. Is a diagram of all ventilation systems of 9201-5 as of 8/12/55.
 - 2. Was drawn by Don McAlister a man who worked for the HVAC Design Department.
 - 3. It shows three designs:

the original Catalytic design an upgraded ventilation design for winter operation an upgraded ventilation design for summer operation

Note:

In this building, large surface areas of Mercury were exposed to the ambient air. As air temperatures increased from winter time to summer operation, more Mercury vaporized and entered the ambient. Contamination levels, then, tended to increase during the summer months. To control the contamination level, higher ventilation rates were planned for summer.

The following table reflects the total ventilation provided by the original design, and for the upgraded design. The increases in ventilation shown here seem to be consistent with operating problems that were experienced and with documented evidence of modifications that were made for improvement.

	Contamina	ted Exhaust	Building Air Change Rate (based on Summer design)
	Winter	Summer	
Initial Design	1308545	1308545	8.3
Upgraded Design	1684410		10.7
Upgraded Design		2357755	15.9

Details of the upgraded design for winter operation are summarized in Table 1. Here all major operations have been located with respect to building column lines and building floors. Too, air supplied and exhausted are given along with volumes of spaces and air change rates.

Table 1
Winter Ventilation Rates for 9201-5 Operations

								Contaminat ed
				Fresh Air	Air From	Room	Chgs	Exh from
			Room	Supply	Floor Below	Exhaust.	per	Building
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
4-8	Cascade 5 & 6	1	661,000	108000	U	108000	9.8	34000
4-8	Cascade 5 & 6	2	402,500	184200	74000	258200	27.5	108000
4-8	Cascade 5 & 6	3	1,209,000	130200	150200	280400	6.5	280400
						0	Ì	0
1-4	Storage	1	297.000	10000	0	10000	2.0	10000
1-4	Feed Prep	2	248,500	25000	0	25000	6.0	25000
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000
1-4	0/10111.1000.		,			0		0
8-11	Storage	1	297,000	18000	0	18000	3.6	18000
8-11	Hang gardens	2	248,500	20000	0	20000	48	20000
8-11	Absorbers 5 & 6	3	374,000	115000	0	115000	18.4	115000
						0		0
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0		0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	71000	0	71000	19.4	
19-22	Absorbers 1 & 2	3	374,000	120000	0	120000	19.3	
10 22	2200010					0		0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	108000
22-26	Cascades 1&3 and 2&4	2	402,500	96000	0	96000	14.3	
22-26	Cascades 1&3 and 2&4	3	1,209,000	236400	351910	588310	11.7	588310
						0		0
26-29	Storage	· 1	297,000	18000	0	18000	3.6	1200
26-29	Hang G. & Inject	2	248,000	40000	16800	56800	9.7	56800
26-29	Absorber No 3&4	3	311,000		U	151810	29.3	
			9471300		592910		10.7	1526610
	Notes:	T				1	J	
	1. Air Changes bas	ed up	n fresh air	supplied.			1	L

б

Details of the upgraded design for summer operation are summarized in Table 2. From this, it may be observed that almost all of the building exhaust is from the 3rd floor. In fact, all is exhausted via roof fans except for 539,200 cfm that is exhausted via louvers in the East & West Crane Bays.

Table 2
Summer Ventilation Rates for 9201-5 Operations

								Contaminated
		-		Fresh Air	Air From	Room	Chgs	Exh from
			Room	Supply	Fl. Below	Exhaust	per	Building
	Suotom	Floor	Volume	cfm	cfm	Cfm	Hour	efm
Col	System Cascade 5 & 6	1	661,000	108000	0	108000	9.8	34000
4-8		2	402,500	184755	74000	258755	27.5	36000
4-8	Cascade 5 & 6	3	1,209,000	263000	222755	485755	13.1	485755
4-8	Cascade 5 & 6	<u> </u>	1,205,000			0		0
	Q4ma	1	297,000	10000	0	10000	2.0	10000
1-4	Storage	2	248,500	25000	0	25000	6.0	25000
1-4	Feed Prep			25000	0	25000	4.8	25000
1-4	Chem.Rec.	3	311,000	20000		0		
		-	002.000	18000	0	18000	3.6	5000
8-11	Storage	1	297,000	. ———	13000	33000	4.8	25600
8-11	Hang gardens &Injection	2	248,500	20000				
8-11	Absorbers 5 & 6	3	374,000	275000	7400	282400	44.1	282400
						0		
11-19	Maintenance	1	842,000	80000	0	80000	5.7	L
11-19	Service	2	561,500	77800	0	77800	8.3	
						0		0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	76000	0	76000	20.7	76000
19-22	Absorbers 1 & 2	3	374,000	290000	0	290000	46.5	290000
						0		0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	88000
22-26	Cascades 1, 2, 3,4	2	402,500	96000	20000	116000	14.3	120000
22-26	Cascades 1, 2, 3,4	3	1,209,000		-4000	498000	24.9	498000
22-20	C	1	1			0		0
26-29	Storage	1	297,000	18000	0	18000	3.6	1200
26-29	Hang G. & Inject		248,000	40000	16800	56800	9.7	24000
26-29	Absorber No 3&4	3	311,000	249000	32800	281800	48.0	281800
20.23	ANDOLDOL 110 DEL	† <u> </u>	9471300				15.9	2357755

Table 3 is a tabulation of exhaust fan locations, design air volumes for summer and a calculated percentage of the building total.

Table 3
Fan Locations, Summer Air Volumes, & Per Cent of Total for Building Exhaust Points

					Exit
	grade	cfm	%	Orientation	Point
W. Crane bay Roof exh	1061	140000	6%	up	roof
East Crane Bay Roof Exh	1061	280000	12%	up	roof
Absorbers 3&4	1040	210510	9%	up	roof
From Floors Below	1040	138500	6%	up	roof
Absorber 1&2	1040	334875	14%	up	roof
From Floors Below	1040	237160	10%	up	roof
Absorbers 5 & 6	1040	211470	9%	up	roof
From Floors Below	1040	99040	4%		roof
Extraction	1040	127000	5%	up	roof
W. Crane bay North wall	1050	179000	8%	horizontal	wall
S. Crane bay So Wall	1050	179000	8%	horizontal	wall
W. Crane bay North wall	1050	90600	4%	horizontal	wall
S. Crane bay So Wall	1050	90600	4%	horizontal	wall
North Wall 2nd Floor	1010	40000	0% 2%	horizontal	wall
		2357755	100%		

Table 4 contains data that is similar to that shown in Table 3, except it is for "winter" operation.

This percentages that were calculated in both table 3 and table 4 are also included in Figure 2 .

Table 4
Fan Locations, Winter Air Volumes, & Per Cent of Total for Building Exhaust Points

					Exit
	grade	cfm	%	Orientation	Point
W. Crane bay Roof exh	1061	232400	15%	up	Roof
East Crane Bay Roof Exh	1061	328000	21%	up	Roof
vast Orane 2d) 20			_		
Absorbers 3&4	1040	115330	8%	up	Roof
From Floors Below	1040	138500	9%	up	Roof
LIOII LIOOIS DEION				17%	
Absorber 1&2	1040	104590	7%	up	Roof
From Floors Below	1040	237160	16%	up	Roof
From Floors Delow				22%	
Absorbers 5 & 6	1040	104590	7%	up	Roof
From Floors Below	1040	99040	6%		Roof
From Floors Below	102			13%	
Extraction	1040	127000	8%	up	Roof
DAG ACHON	1				
W. Crane bay North wall	1050	0	0%	horizontal	
S. Crane bay So Wall	1050	0	0%	horizontal	Roof
D. Claric Sty	1				
North Wall 2nd Floor	1010	40000	3%	horizontal	Roof
TACTOR ALCOT	1	1526610	100%		

Table 5 is a comparison of the Catalytic Design, the Upgrade Design, and ventilation rates as reported by J.C. Little, March 14, 1956. This comparison would indicate that Little was using "Summer" ventilation rates for his study. In view of a very close agreement of between Little's Report and Flow Sheet Data, this comparison would indicate that both were applicable to the same period of time.

Table 5
Comparison of Flow Sheet Ventilation Rates with Those Reported by Little

		1	Exhaust Air Flow Cfm					
			From	Vent. Flow S	Sheet	From Little		
			Cat. Des.	Winter	Summer	Report		
cols.	Operation	Floor						
1-4	Storage	1						
1.4	Feed Prep. & Extraction	2	35000	35000	35000	35000		
1-4	Chemical Recovery	3	25000	25000	25000	25000		
4-8	Cascades 5 & 6							
1-8	All Floors	1,2&3	376400	388000	555755	545000		
8-11	Stores	1						
8-11	Injection Pumps 5 & 6	2	0	25600	25600	25600		
8-11	Absorbers 5 & 6	3	99600	130000	290000	292000		
19-22	Feed Storage	1	0	50000	50000	50000		
19-22	Absorbers & Injection 1A	2	70325	71000	76000	50000		
19-22	Injection Pumps 1 & 2	2	15000	50000	50000	24000		
19-22	Absorbers 1 & 2	3	107110	120000	290000	292000		
22-24	Cascades 1 & 3							
22-24	1st Floor		36000	44000	44000	54000		
22-24	2nd Floor	3	, 8000	40000	-40000	60000		
22-24	3rd & 4th Floor		202000	220200	249000	257000		
24-26	Cascades 2 & 4							
24-26	let Floor		36000	44000	44000	54000		
24-26	2nd Floor		8000	80000	80000	60000		
24-26	3rd & 4th Floor		202000	220200	249000	257000		
26-29	Absorbers 3 & 4	3	88110	131850	281110	292000		
26-29	Injection Pumps 3 & 4	2	0	24000	24000	24000		
	Totals		1308545	1698850	2408465	2396600		

Table 6 is simply a repetition of Little's arithmetic. Input to this consist of air flow rates and concontration rates from Table 1 of Little's report. Other columns are simply details of the calculation. The resulting lbs/day effluent are the same as reported - of course.

Table 6 Validation of Little's Arithmetic

	building	Exhaust		Concentration			
	col. lines		m ^{.y} day		mg/day	grama/day	lbs/day
		292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 1 & 2	19 - 22			0.18	2143439	2143.439	4.73
Absorbers 3 & 4	26 - 29	292000	11907994			1428.959	3.15
Absorbers 4 & 5	8 - 11	292000	11907994	0.12	1428959		
Absorbers & Injection 1A	19 - 22	50000	2039040	0.28	570931.2	570.9312	1.26
	22 22	0.4000	070720	0.3	293621.8	293,6218	0.65
Injection Pumps 1 & 2	22 - 26	24000	978739			244.6848	0.54
Injection Pumps 3 & 4	26 - 29	24000	978739	0.25	244684.8	<u> </u>	
Injection Pumps 5 & 6	8 - 11	25600	1043988	0.53	553313.9	553.3139	1.22
C1 : -1 D	1 - 4	25000	1019520	0.19	193708.8	193.7088	0.43
Chemical Recovery	19 - 22	50000	2039040	0.25	509760	509.76	1.12
Feed Storage			1427328	0.1	142732.8		0.31
Feed Prep. & Extraction	1-4	35000	1427328	0.1	142/02.0	142.1020	1 0.02
Cascades 1 & 3	22 - 24						
1st Floor		54000	2202163	6.2	440432.6	440.4326	0.97
2nd Floor		60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.21	2200940	2200.94	4.85
Cascades 2 & 4	24 - 26	<u> </u>		-	 		
1st Floor		54000	2202163	0.21	462454.3	462.4543	1.02
	+	60000	2446848	0.26	636180.5	636.1805	1.40
2nd Floor	 	257000			1886520		4.16
3rd & 4th Floor		201000	10400000	1 00	1	1	
Cascades 5 & 6	1-8						
All Floors		545000	22225536	0.13	2889320	2889.32	6.37
		2396600	97735265	5			38.31

References

- 1. Solvent Losses Through Ventilation Exhaust Systems, Building 9201-5, Little, J. C., March 14, 1956.
- 2. "General Ventilation 9201-5", A Y-12 Drawing, drawn by McAlister 8/12/55.
- 3. Y/EX-24, Mercury at Y-12, (Unclassified version of Y/EX-21), Compiled by The 1083 Mercury Task Force, August 18, 1983.
- 4. Catalytic Construction drawings and design notes.

Ventilation Systems of Building 9201-5 as Existed in 1956 by

by E. E. Choat

Building Data

- Building 9201-5 is a large process building. It's overall size is 542 feet x 312 feet. It has 3 floors and a total volume 9,471,300 ft³. It has seven operating bays East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.
- Figure 1 is a plan of the 3rd floor of the Colex Production Plant 9201-5 as it was in 1956. As seen here, "Absorbers" (a major process step) occupied the entire 3rd floor of three bays. Too, "Cascades" occupied the entire area of two very large bays. The same Cascades also occupied the 1st and 3rd floors as well. This plan is included here to provide dimensional information on the structure, to show the location of various building processes, and the location of major ventilation exhaust points.
- Figure 2 is a sectional view of the building. It is included here to provide pertinent building elevations, and to further identify the location of building processes.
- All building areas were contaminated with Mercury except the Service Area, & the Motor Generator Set Area.

Ventilation

- The initial design of the ventilation systems for this building was done by an Architect Engineering Company Catalytic Construction Company. Supervision of this design was done by Union Carbide Plant Engineering personnel. The HVAC Design Department was responsible for review and approval of all Heating, Ventilating, and Air Conditioning (HVAC) plans, and consequently, were intimately familiar with the details of these systems. J. C. Little was then the Head of the HVAC Design Department. At that time I worked in Jim Little's department as an HVAC Design Engineer.
- Construction of this design was completed in 1955, but did not provide sufficient ventilation to maintain acceptable contamination levels.
- These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Union





Figure 2 Section A - A ---- Building 9201-5



- Carbide, HVAC Design Department personnel. J. C. Little, the was a major influence in these modifications.
- Subsequent to the shutdown of the Colex Production Plant in 9201-5, the building was stripped of all process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflected conditions that existed in 1956.
- For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in 1956. The most significant document of this search is a flow sheet identified as "General Ventilation 9201-5" it has no drawing number. This document:
 - 1. Is a diagram of all ventilation systems of 9201-5 as of 8/12/55.
 - 2. Was drawn by Don McAlister a man who worked for the HVAC Design Department.
 - 3. It shows three designs:

the original Catalytic design an upgraded ventilation design for winter operation an upgraded ventilation design for summer operation

Note:

In this building, large surface areas of Mercury were exposed to the ambient air. As air temperatures increased from winter time to summer operation, more Mercury vaporized and entered the ambient. Contamination levels, then, tended to increase during the summer months. To control the contamination level, higher ventilation rates were planned for summer.

The following table reflects the total ventilation provided by the original design, and for the upgraded design. The increases in ventilation shown here seem to be consistent with operating problems that were experienced and with documented evidence of modifications that were made for improvement.

	Contamina	ted Exhaust	Building Air Change Rate (based on Summer design)			
	Winter	Summer				
Initial Design	1308545	1308545	8.3			
Upgraded Design	1684410		10.7			
Upgraded Design		2357755	15.9			

Details of the upgraded design for winter operation are summarized in Table 1. Here all major operations have been located with respect to building column lines and building floors. Too, air supplied and exhausted are given along with volumes of spaces and air change rates.

Table 1
Winter Ventilation Rates for 9201-5 Operations

								Contaminat ed
				Fresh Air	Air From	Room	Chgs	Exh from
			Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
4-8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8	34000
4-8	Cascade 5 & 6	2	402,500	184200	74000	258200	27.5	108000
4-8	Cascade 5 & 6	3	1,209,000	130200	150200	280400	6.5	280400
						0		0
1-4	Storage	1	297,000	10000	0	10000	2.0	10000
1-4	Feed Prep	2	248,500	25000	0	25000	6.0	25000
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000
	<u> </u>		·			0		0
8-11	Storage	1	297,000	18000	0	18000	3.6	18000
8-11	Hang gardens &Injection	2	248,500	20000	0	20000	4.8	20000
8-11	Absorbers 5 & 6	3	374,000	115000	0	115000	18.4	115000
						0		0
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0	<u> </u>	0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	71000	0	71000	19.4	71000
19-22	Absorbers 1 & 2	3	374,000	120000	0	120000	19.3	120000
						0		0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	108000
22-26	Cascades 1&3 and 2&4	2	402,500	96000	0	96000	14.3	-255910
22-26	Cascades 1&3 and 2&4	3	1,209,000	236400	351910	588310	11.7	588310
						0		0
26-29	Storage	1	297,000	18000	0	18000	3.6	1200
26-29	Hang G. & Inject	2	248,000	40000	16800	56800	9.7	56800
26-29	Absorber No 3&4	3	311,000	151810	0	151810	29.3	151810
			9471300	1684410	592910		10.7	1526610
	Notes:							
	1. Air Changes bas	ed upo	n fresh air	supplied.				

Details of the upgraded design for summer operation are summarized in Table 2. From this, it may be observed that almost all of the building exhaust is from the 3rd floor. In fact, all is exhausted via roof fans except for 539,200 cfm that is exhausted via louvers in the East & West Crane Bays.

Table 2 Summer Ventilation Rates for 9201-5 Operations

								Contaminated
			-	Fresh Air	Air From	Room	Chgs	Exh from
			Room	Supply	Fl. Below	Exhaust	per	Building
Col	System	Floor	Volume	$_{ m cfm}$	$_{ m cfm}$	\mathbf{Cfm}	Hour	cfm
4-8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8	34000
4-8	Cascade 5 & 6	2	402,500	184755	74000	258755	27.5	36000
4-8	Cascade 5 & 6	3	1,209,000	263000	222755	485755	13.1	485755
						0		0
1-4	Storage	1	297,000	10000	0	10000	2.0	10000
1-4	Feed Prep	2	248,500	25000	0	25000	6.0	25000
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000
				-		0		
8-11	Storage	1	297,000	18000	0	18000	3.6	5000
8-11	Hang gardens	2	248,500	20000	13000	33000	4.8	25600
	&Injection				7 400	000400	144	000400
8-11	Absorbers 5 & 6	3	374,000	275000	7400	282400	44.1	282400
			0.40.000	00000		0		
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						50000	101	0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	76000	0	76000	20.7	76000
19-22	Absorbers 1 & 2	3	374,000	290000	0	290000	46.5	290000
			227 222	100000		0	100	0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	88000
22-26	Cascades 1, 2, 3,4	2	402,500	96000	20000	116000	14.3	120000
22-26	Cascades 1, 2, 3,4	3	1,209,000	502000	-4000	498000	24.9	498000
						0		0
26-29	Storage	1	297,000	18000	0	18000	3.6	1200
26-29	Hang G. & Inject	2	248,000	40000	16800	56800	9.7	24000
26-29	Absorber No 3&4	3	311,000	249000	32800	281800	48.0	281800
			9471300	2515555	382755		15.9	2357755

From Tables 1 & 2 and also from Figure 2, building exhaust is distributed as follows:

10110 W.S.	Exhaust Volume	% via Roof at Elevation 1061'	% via Roof at Elevation 1040'	% via Walls at Elevation 1050
Summer	2357755	37	61	2
Winter	1526610	25	64	1

Table 3 is a comparison of the Catalytic Design, the Upgrade Design, and ventilation rates as reported by J.C. Little, March 14, 1956. This comparison would indicate that Little was using "Summer" ventilation rates for his study. In view of a very close agreement of between Little's Report and Flow Sheet Data, this comparison would indicate that both were applicable to the same period of time.

 ${\bf Table~3} \\ {\bf Comparison~of~Flow~Sheet~Ventilation~Rates~with~Those~Reported~by~Little}$

				Exhaust Air		
			From	Vent. Flow S	Sheet	From Little
			Cat. Des.	Winter	Summer	Report
cols.	Operation	Floor			<u>.</u> ,	
1-4	Storage	1				
1-4	Feed Prep. & Extraction	2	35000	35000	35000	35000
1-4	Chemical Recovery	3	25000	25000	25000	25000
4-8	Cascades 5 & 6				-	
4-8	All Floors	1,2&3	376400	388000	555755	545000
8-11	Stores	1				
8-11	Injection Pumps 5 & 6	2	0	25600	25600	25600
8-11	Absorbers 5 & 6	3	99600	130000	290000	292000
19-22	Feed Storage	1	0	50000	50000	50000
19-22	Absorbers & Injection 1A	2	70325	71000	76000	50000
19-22	Injection Pumps 1 & 2	2	15000	50000	50000	24000
19-22	Absorbers 1 & 2	3	107110	120000	290000	292000
22-24	Cascades 1 & 3					
22-24	1st Floor		36000	44000	44000	54000
22-24	2nd Floor		8000	40000	40000	60000
22-24	3rd & 4th Floor	-	202000	220200	249000	257000
24-26	Cascades 2 & 4					
24-26	1st Floor		36000	44000	44000	54000
24-26	2nd Floor		8000	80000	80000	60000
24-26	3rd & 4th Floor		202000	220200	249000	257000
26-29	Absorbers 3 & 4	3	88110	131850	281110	292000
26-29	Injection Pumps 3 & 4	2	0	24000	24000	24000
	Totals		1308545	1698850	2408465	2396600

Table 4 is simply a repetition of Little's arithmetic. Input to this consist of air flow rates and concentration rates from Table 1 of Little's report. Other columns are simply details of the calculation. The resulting lbs/day effluent are the same as reported — of course.

Table 4 Validation of Little's Arithmetic

	building	Exhaust		Conce	entration		
	col. lines	Cfm	m³/day	mg/m³	mg/day	grams/day	lbs/day
Absorbers 1 & 2	19 - 22	292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 3 & 4	26 - 29	292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 4 & 5	8 - 11	292000	11907994	0.12	1428959	1428.959	3.15
Absorbers & Injection 1A	19 - 22	50000	2039040	0.28	570931.2	570.9312	1.26
Injection Pumps 1 & 2	22 - 26	24000	978739	0.3	293621.8	293.6218	0.65
Injection Pumps 3 & 4	26 - 29	24000	978739	0.25	244684.8	244.6848	0.54
Injection Pumps 5 & 6	8 - 11	25600	1043988	0.53	553313.9	553.3139	1.22
							<u> </u>
Chemical Recovery	1 - 4	25000	1019520	0.19	193708.8	193.7088	0.43
Feed Storage	19 - 22	50000	2039040	0.25	509760	509.76	1.12
Feed Prep. & Extraction	1 - 4	35000	1427328	0.1	142732.8	142.7328	0.31
Cascades 1 & 3	22 - 24		<u> </u>				
1st Floor		54000	2202163	0.2	440432.6		0.97
2nd Floor		60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.21	2200940	2200.94	4.85
				<u> </u>			<u> </u>
Cascades 2 & 4	24 - 26		ļ			<u> </u>	1.00
1st Floor		54000	2202163	0.21	462454.3		1.02
2nd Floor		60000	2446848	0.26	636180.5	-	1.40
3rd & 4th Floor		257000	10480666	0.18	1886520	1886.52	4.16
	<u> </u>	<u> </u>		<u> </u>	<u> </u>		
Cascades 5 & 6	4-8		<u> </u>		0000000	2000.63	0.05
All Floors		545000			2889320	2889.32	6.37
		2396600	97735265		<u> </u>		38.31

References

- Solvent Losses Through Ventilation Exhaust Systems, Building 9201-5, Little, J. C., March 14, 1956.
- 2. "General Ventilation 9201-5", A Y-12 Drawing, drawn by McAlister 8/12/55.
- 3. Y/EX-24, Mercury at Y-12, (Unclassified version of Y/EX-21), Compiled by The 1083 Mercury Task Force, August 18, 1983.
- 4. Catalytic Construction drawings and design notes.

TO 1 303 939 8318 / -5\ P.01

FACSIMILE COVER SHEET

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/23/96

Pages including this cover page -- 9

Comment:

This is to transmit the 1st draft of my final report for building 9201-5.

E. E. Choat

97-9990 out 1206

for a down sind

grand

Summer

July 23, 1996

Ventilation Systems of Building 9201-5 as Existed in 1956 by E. E. Choat

Building Data

- Building 9201-5 is a large process building. It's overall size is 542 feet x 312 feet. It has 3 floors and a total volume 9,471,300 ft³. It has seven operating bays East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.
- Figure 1 is a plan of the 3rd floor of the Colex Production Plant 9201-5 as it was in 1956. As seen here, "Absorbers" (a major process step) occupied the entire 3rd floor of three bays. Too, "Cascades" occupied the entire area of two very large bays. The same Cascades also occupied the 1st and 3rd floors as well. This plan is included here to provide dimensional information on the structure, to show the location of various building processes, and the location of major ventilation exhaust points.
- Figure 2 is a sectional view of the building. It is included here to provide pertinent building elevations, and to further identify the location of building processes.
- All building areas were contaminated with Mercury except the Service Area, & the Motor Generator Set Area.

Ventilation

- The initial design of the ventilation systems for this building was done by an Architect Engineering Company Catalytic Construction Company. Supervision of this design was done by Union Carbide Plant Engineering personnel. The HVAC Design Department was responsible for review and approval of all Heating, Ventilating, and Air Conditioning (HVAC) plans, and consequently, were intimately familiar with the details of these systems. J. C. Little was then the Head of the HVAC Design Department. At that time I worked in Jim Little's department as an HVAC Design Engineer.
- Construction of this design was completed in 1955, but did not provide sufficient ventilation to maintain acceptable contamination levels.
- These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Union Carbide, HVAC Design Department personnel. J. C. Little, the was a major influence in these modifications.
- Subsequent to the shutdown of the Colex Production Plant in 9201-5, the building
 was stripped of all process equipment so that new and different processes could be
 installed. Ventilation systems were then modified as necessary to accommodate the
 requirements of the new process. During these modifications, drawings of the
 building ventilation systems were changed according to the new design, and
 consequently, no longer reflected conditions that existed in 1956.
- For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in 1956. The most significant document of this search is a

- flow sheet identified as "General Ventilation 9201-5" it has no drawing number.
 This document:
 - 1. Is a diagram of all ventilation systems of 9201-5 as of 8/12/55.
 - Was drawn by Don McAlister a man who worked for the HVAC Design Department.
 - 3. It shows three designs:

the original Catalytic design an upgraded ventilation design for winter operation an upgraded ventilation design for summer operation Note:

In this building, large surface areas of Mercury were exposed to the ambient air. As air temperatures increased from winter time to summer operation, more Mercury vaporized and entered the ambient. Contamination levels, then, tended to increase during the summer months. To control the contamination level, higher ventilation rates were planned for summer.

The following table reflects the total ventilation provided by the original design, and for the upgraded design. The increases in ventilation shown here seem to be consistent with operating problems that were experienced and with documented evidence of modifications that were made for improvement.

	Contaminate	d Exhaust	Building Air Change Rate (based on Summer design)
	Winter	Summer	
Initial Design	1308545	1308545	8.3
Upgraded Design	1684410		10.7
Upgraded Design		2357755	15.9

Details of the upgraded design for winter operation are summarized in Table 1. Here all major operations have been located with respect to building column lines and building floors. Too, air supplied and exhausted are given along with volumes of spaces and air change rates.

Details of the upgraded design for summer operation are summarized in Table 2. From this, it may be observed that almost all of the building exhaust is from the 3rd floor. In fact, all is exhausted via roof fans except for 539,200 cfm that is exhausted via louvers in the East & West Crane Bays,

Table 3 is a comparison of the Catalytic Design, the Upgrade Design, and ventilation rates as reported by J.C. Little, March 14, 1956. This comparison would indicate that Little was using "Summer" ventilation rates for his study. In view of a very close agreement of between Little's Report and Flow Sheet Data, this comparison would indicate that both were applicable to the same period of time.

Table 1 Winter Ventilation Rates for 9201-5 Operations

								Contamina ed
				Fresh Air	Air From	Room	Chge	Exh from
			Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm	cſm	Cfm	Hour	cfm
4-8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8	34000
4.8	Cascade 5 & 6	2	402,500	184200	74000	258200	27.5	108000
4-8	Cascade 5 & 6	3	1,209,000	130200	150200	280400	6.5	280400
						0		0
1-4	Storage	1	297,000	10000	0	10000	2.0	10000
1-4	Feed Prep	2	248,500	25000	0	25000	6.0	25000
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000
						0		0
8-11	Storage	1	297,000	18000	0	18000	3.6	18000
8-11	Hang gardens &Injection	2	248,500	20000	0	20000	4.8	20000
8-11	Absorbers 5 & 6	3	374,000	115000	0	115000	18.4	115000
						0		0
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0	<u> </u>	0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	71000	0	71000	19.4	71000
19-22	Absorbers 1 & 2	3	374,000	120000	0	120000	19.3	120000
						0		0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	108000
22-26	Cascades 1&3 and 2&4	2	402,500	96000	0	96000	14.3	-255910
22-26	Cascades 1&3 and 2&4	3	1,209,000	236400	351910	588310	11.7	588310
						0		0
26-29	Storage	1	297,000	18000	0	18000	3.6	1200
26-29	Hang G. & Inject	2	248,000	40000	16800	56800	9.7	56800
26-29	Absorber No 3&4	3	311,000	151810	0 _	151810	29.3	151810
			9471300	1684410	592910		10.7	1526610
	Notes:							<u> </u>
	1. Air Changes bas	ed upo	n fresh air	aupplied.			<u> </u>	

Table 2
Summer Ventilation Rates for 9201-5 Operations

								Contaminat ed
				Fresh Air	Air From	Room	Chga	Exh from
	i k		Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm.	cfm	Cfm	Hour	cfm
4.8	Cascade 5 & 6	1	661,000	108000	0	108000	9.8	34000
4-8	Cascade 5 & 6	2	402,500	184755	74000	258755	27.5	36000
4-8	Cascade 5 & 6	3	1,209,000	263000	222755	485755	13.1	485755
						0		0
1-4	Storage	1	297,000	10000	0	10000	2.0	10000
1.4	Feed Prep	2	248,500	25000	0	25000	6.0	25000
1-4	Chem.Rec.	3	311,000	25000	0	25000	4.8	25000
				•		0		
8-11	Storage	1	297,000	18000	0	18000	3.6	5000
8-11	Hang gardens &Injection	2	248,500	20000	13000	33000	4.8	25600
8-11	Absorbers 5 & 6	3	374,000	275000	7400	282400	44.1	282400
						0		
11-19	Maintenance	1	842,000	80000	0	80000	5.7	
11-19	Service	2	561,500	77800	0	77800	8.3	
						0		0
19-22	Feed Storage	1	297,000	50000	0	50000	10.1	50000
19-22	Hang G. & Inj.	2	219,800	76000	U	76000	20.7	76000
19-22	Absorbers 1 & 2	3	374,000	290000	0	290000	46.5	290000
						0		0
22-26	Cascades 1&3 and 2&4	1	661,000	108000	0	108000	9.8	88000
22-26	Cascades 1&3 and 2&4	2	402,500	96000	20000	116000	14.3	120000
22-26	Cascados 1&3 and 2&4	3	1,209,000	502000	-1000	498000	24.9	498000
						0		0
26-29	Storage	1	297,000	18000	0	18000	3.6	1200
26-29		2	248,000	40000	16800	56800	9.7	24000
26-29	Absorber No 3&4	3	311,000	249000	32800	281800	48.0	281800
			9471300	2515555	382755		15.9	2357755

Table 3
Comparison of Flow Sheet Ventilation Rates with Those Reported by Little

			Exhaust Air Flow Cfm				
			From	Sheet	From Little		
			Cat. Des.	Winter	Summer	Report	
cols.	Operation	Floor					
	Storage	1					
	Feed Prep. & Extraction	2	35000	35000	35000	35000	
1.4	Chemical Recovery	3	25000	25000	25000	25000	
4-8	Cascades 5 & 6						
4-8	All Floors	1,2&3	376400	388000	555755	545000	
8-11	Stores	1					
8-11	Injection Pumps 5 & 6	2	0	25600	25600	25600	
8-11	Absorbers 5 & 6	3	99600	130000	290000	292000	
19-22	Feed Storage	1	0	50000	50000	50000	
	Absorbers & Injection 1A	2	70325	71000	76000	50000	
	Injection Pumps 1 & 2	2	15000	50000	50000	24000	
19-22	Absorbers 1 & 2	3	107110	120000	290000	292000	
22-24	Cascades 1 & 3						
22-24	1st Floor		36000	44000	44000	54000	
22-24	2nd Floor		8000	40000	40000	60000	
22-24	3rd & 4th Floor	ļ <u></u>	202000	220200	249000	257000	
24-26	Cascades 2 & 4						
24-26	1st Floor		36000	44000	44000	54000	
24-26	2nd Floor		8000	80000	80000	60000	
24-26	3rd & 4th Floor		202000	220200	249000	257000	
26-29	Absorbers 3 & 4	3	88110	131850	281110	292000	
26-29		2	0	24000	24000	24000	
	Totals		1308545	1698850	2408465	2396600	

					·		
Injection Pumps 1 & 2	22 - 26	24000	978739	0.3	293621.8	293.6218	0.65
Injection Pumps 3 & 4	26 - 29	24000	978739	0.25	244684.8	244.6848	0.54
Injection Pumps 5 & 6	8-11	25600	1043988	0.53	553313.9	553.3139	1.22
Chemical Recovery	1 - 4	25000	1019520	0.19	193708.8	193.7088	0.43
Feed Storage	19 - 22	50000	2039040	0.25	509760	509.76	1.12
Feed Prep. & Extraction	1-4	35000	1427328	0.1	142732.8	142.7328	0.31
Cascades 1 & 3	22 - 24						
1st Floor		54000	2202163	0.2	440432.6	440.4326	0.97
2nd Floor		60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.21	2200940	2200.94	4.85
Cascades 2 & 4	24 - 26						
1st Floor	-	54000	2202163	0.21	462454.3	462.4543	1.02
2nd Floor	 	60000	2446848	0.26	636180.5	636.1805	1.40
3rd & 4th Floor		257000	10480666	0.18	1886520	1886.52	4.16
Cascades 5 & 6	4-8				2000000	2000 80	6.07
All Floors	_	545000	22225536	0.13	2889320	2889.32	6.37
		2396600	97735265	<u></u>	1		38.31

References

 Solvent Losses Through Ventilation Exhaust Systems, Building 9201-5, Little, J. C., March 14, 1956.

2. "General Ventilation - 9201-5", A Y-12 Drawing, - drawn by McAlister - 8/12/55.

3. Y/EX-24, Mercury at Y-12. (Unclassified version of Y/EX-21), Compiled by The 1083 Mercury Task Force, August 18, 1983.

4. Catalytic Construction drawings and design notes.


Table 4 is simply a repetition of Little's arithmetic. Input to this consist of air flow rates and concentration rates from Table 1 of Little's report. Other columns are simply details of the calculation. The resulting lbs/day effluent are the same as reported – of course.


Table 4
Validation of Little's Arithmetic

	building	Exhaust		Conce	entration		
	col. lines		m³/day	mg/m³	mg/day	grame/day	lbaday
Absorbers 1 & 2	19 - 22	292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 3 & 4	26 - 29	292000	11907994	0.18	2143439	2143.439	4.73
Absorbers 4 & 5	8 - 11	292000	11907994	0.12	1428959	1428.959	3.15
Absorbers & Injection 1A	19 - 22	50000	2039040	0.28	570931.2	570.9312	1.26
					<u> </u>		
Injection Pumps 1 & 2	22 - 26	24000	978739	0.3	293621.8	293.6218	0.65
Injection Pumps 3 & 4	26 - 29	24000	978739	0.25	244684.8		0.54
Injection Pumps 5 & 6	8-11	25600	1043988	0.53	553313.9	553.3139	1.22
Chemical Recovery	1 - 4	25000	1019520	0.19	193708.8		0.43
Feed Storage	19 - 22	50000	2039040	0.25	509760	509.76	1.12
Feed Prep. & Extraction	1-4	35000	1427328	0.1	142732.8	142.7328	0.31
Cascades 1 & 3	22 - 24			<u> </u>			
1st Floor		54000	2202163	0.2	440432.6		0.97
2nd Floor		60000	2446848	0.26	636180.5		1.40
3rd & 4th Floor		257000	10480666	0.21	2200940	2200.94	4.85
			<u> </u>				
Cascades 2 & 4	24 - 26						
1st Floor		54000	2202163		462454.3		1.02
2nd Floor		60000	2446848	0.26	636180.5		1.40
3rd & 4th Floor		257000	10480660	0.18	1886520	1886.52	4.16
Cascades 5 & 6	4.8					2000 50	0.07
All Floors		545000		_	2889320	2889.32	6.37
		2396600	9773526	<u>il</u>			38.31

References

- Solvent Losses Through Ventilation Exhaust Systems, Building 9201-5, Little, J. C., March 14, 1956.
- 2. "General Ventilation 9201-5", A Y-12 Drawing, drawn by McAlister 8/12/55.
- Y/EX-24, Mercury at Y-12, (Unclassified version of Y/EX-21), Compiled by The 1083
 Mercury Task Force, August 18, 1983.
- 4. Catalytic Construction drawings and design notes.





3

Figure 2 Section A · A ···· Building 9201-5

		Roof grade 1060.95∜	Roof grade 1040' -	3rd floor grade 1019	2nd floor grade998'	First floor grade973'
Lines				Extraction	Chemical Recovery	Feed Prep
Column Lines	East Crane Bay		Cascades 5 & 6		Cascades 5 & 6	
,	∞ ——			Absorber Banks 5 & 6	Pump Injection	
					Control Room & Maintanence	Utilities
	6 -	:		Absorber Banks 1 & 2	Absorber 1.A Pump Injection	Feed Storage
Sour	- 22	West Crane Bay		Cascades 2 & 4	Cascades 2 & 4 Cascades 1 & 3	
Column	28 - S			Absorber Bants 3 & 4	Inpection & Storage	Scarge

Ventilation Systems of Building 9201-4 as Existed in 1956

by E. E. Choat

Building Data

543

- Building 9201-4 is a large process building. It's overall size is 542 feet x 312 feet. It has 3 floors and a total volume 9,471,300 ft³. It has seven operating bays East Crane Bay, West Crane Bay, 4 Control Bays, & 1 Service Bay.
 - During the time of the Colex Production Plant, the two major steps of process operations were identified as "Cascades", & "Absorbers".
 Cascades occupied all three floors of the East & West Crane Bays.
 Absorbers were located on the third floor of all four Control Bays. All building areas were contaminated with Mercury except for the Service Area, & Motor Generator (MG) Set Areas.

For this study, a set of simplified building plans have been reconstructed for the purpose of describing characteristics of the building and to illustrate the ventilation systems that were installed in 1956. These plans are included in this report as:

Figure $1 - 1^{st}$ Floor Plan

Figure $2-2^{nd}$ Floor Plan

Figure 3 – 3rd Floor Plan

Figure 4 -- Section A - A - Building 9201-4


These plans are intended to show the location of various building processes, the location of major exhaust systems, and to provide dimensional information on the structure.


Ventilation


• Initial design was done by an Architect Engineering Company – Catalytic Construction Company. In general, 100 % outside air was supplied from the basement and exhausted via the 3rd floor walls and roof. Construction of this design was completed in 1955 but did not provide sufficient ventilation to maintain acceptable contamination levels.


These systems were then modified and upgraded in 1956 in an effort to reduce contamination levels. The design was done by Catalytic Construction Company. Because of an increased vaporization of Mercury as temperature increased, more ventilation was provided in

The state of the s









summer than in winter. Consequently, design documents and this report often refer to both.

Table 1 is a summarization of the findings of this study regarding the "Winter" Ventilation design for 9201-4. Recorded here are:

1. Identities of all process areas of the Colex Production Plant

Table 1
Winter Ventilation Design for 9201-4

									Contaminated
	-				Fresh Air	Air From	Room	Chgs.	Exh from
				Room	Supply	Floor Below	Exhaust	per	Building
16x95x22' 14' 41'	Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
12x00/x22'	4-8	Cascade 9 & 10	1	661,000	270510	0	270510	24.6	52000
111	4-8		2	402,500	181400	218510	399910	27.0	48000
19	4-8		3	1,209,000	275000	351910	626910	13.6	626910
41				-			-0-		مهم
,	1-4	Chem.Rec., Feed Prep	1	297,000	93500	0	93500	18.9	93500
58 x 58 x 20'	1-4	Hang Garden & Inj 10	2	248,500	129990	Ó	129990	31.4	129990
16 21	1-4	Absorber No. 10	3	311,000	151,810	0	151810	29.3	151810
21	-						18		-0
50XS8X 14	8-11	General Stores	1	297,000	27000	0	27000	5.5	5110
00, 5	8-11	Hang gardens &ブツ	2	248,500	34410	21890	56300	8.3	56300
12	8-11	Absorber No. 9	3	374,000	151810	0	151810	24.4	151810
18	 • • •		_				4		مه
410 - V 10	11-19	Maintenance	1	842,000	80000	0	80000	5.7	0
x12-0x30	11-19	Service	2	561,500	77800	0	77800	8.3	0
10							18		18
~ 4/04 14	19-22	General Stores	1	297,000	27,000	0	27000	5.5	940
50×58× 14	19-22	Hang G. & Inj. #98	2	219,800	34410	26060	60470	9.4	60470
18	19-22	Absorber #8	3	374,000	151810	0	151810	24.4	151810
10							مهر		18
10 4954 22	22-26	Cascade 7 & 8	1	661,000	270510	0	270510	24.6	52000
	22-26		2	402,500	181400	218510	399910	27.0	48000
14 4 \	22-26		3	1,209,000	275000	351910	626910	13.6	626910
41							D		مور
50VCQX 20	26 -29	Evaporator	1	297,000	38010	0	38010	7.7	38010
158 XS8 X 20	26-29		2	248,000	32000	0	32000	7.7	32000
17 21	26-29		3	311,000	151810	0	151810	29.3	151810
01	 		1	9471300	2635180	1,188790		16.7	2,477380 2,836,000

2. Location of all process areas within the building. For example - Cascades 9 & 10 occupied all three floors between column lines 4 & 8.

- 3. Room volume of all process compartments
- 4. Fresh air supplied to each compartment
- 5. Air transferred between floors
- 6. Total Room Exhaust it's the sum of air supplied and air transferred from another floor.

2. En

7. Changes per hour – It's a commonly used term to describe ventilation rates. Mathematically, it is equal to cfm x 60 – or cubic feet per hour – divided by the room volume. For this design, the fresh air volumes were used for calculations (i.e., in the first was not included)

8. Contaminated exhaust from the building – it's the air volume exhausted directly to outside. In this design, this air stream was sometimes exhausted via a duct system to the roof. In other instances is was exhausted via propeller fans mounted in the wall at the floor elevation.

It should be noted that the ventilation systems for the Motor Generator (MG) Sets are not included in this table as these areas are not considered to be contaminated. Too air exhausted from the Maintenance and Service areas are not included in the total Contaminated Exhaust from the Building.

Table 2 is a summarization of the ventilation design for "Summer" operation.

Table 2 Summer Ventilation Design for 9201-4

		Т		Fresh Air	Air From	Room	Chgs.	Exh from
			Room	Supply	Floor Below	Exhaust	per	Building
Col	System	Floor	Volume	cfm	cfm	Cfm	Hour	cfm
4-8	Cascade 9 & 10	1	661,000	297560	0	297560	27.0	48000
4-8	Cascade 9 & 10	2	402,500	199540	249560 🗸	449100	29.7	48000
4-8	Cascade 9 & 10	3	1,209,000	591775	401100 🗸	992875	29.4	992875
						<u>_B_</u>		-0-
1-4	Chem.Rec., Feed Prep	1	297,000	154350	0	154350	31.2	154350
1-4	Hang Garden & Inj	2	248,500	189990	0	189990	45.9	189990
1-4	Absorber No. 10	3	311,000	478210	0	478210	92.3	478210
•••						-0-		سهر
8-11	General Stores *	1	297,000	29700	0	29700	6.0	5620
8-11	Hang gardens &	2	248,500	37850	24080	61930	9.1	61930
8-11	Absorber No. 9	3	374,000	478210	0	478210	76.7	478210
								-0-
11-19	Maintenance	1	842,000	80000	0	80000	5.7	0
11-19	Service	2	561,500	77800	0	77800	8.3	6
						-0"		-8-
19-22	General Stores	1	297,000	29700	0	29700	6.0	1040
19-22	<u> </u>	2	219,800	37850	28660	66510	10.3	66510
19-22		3	374,000	478210	0	478210	76.7	478210
						-8	T i	-0-
22-26	Cascade 7 & 8	1	661,000	297560	0	297560	27.0	48000
22-26		2	402,500	199540	249560	449100	29.7	48000
22-26		3	1,209,000	591775	401100	992875	29.4	992875
		 				Ð		æ
26-29	Evaporator	1	297,000	97810	0	97810	19.8	97810
26-29		2	248,000	35200	0	35200	8.5	35200
26-29		3	311,000	478210	0	478210	92.3	478210
	7	†	9471300	4860840	1354060		30.8	4703040

2,836,000 cfm

∕o.K·

1,526,610

Observations

1. Contrary to assumptions of previous studies, the ventilation systems for 9201-4 are not the same as 9201-5. From this study, the total contaminated air exhausted from these buildings was:

	Win	ter	Sum	mer
	Cfm	Air	Cfm	Air
	1	Changes		Changes
9201-5	(16 8 4410*)	10.7	2357755	15.9
9201-4	2477380	16.7	4703040√	30.8

Previous reports of Mercury loss to the atmosphere via the building exhaust systems has been based upon the assumption that ventilation systems of 9201-4 were essentially the same as 9201-5. Since this study has indicated a considerable difference in contaminated air exhausted, a new estimate has been made for Mercury loss to the atmosphere for the period of the 2nd quarter of 1955 through the 4th quarter of 1962. The results of these calculations are exhibited in Table 3. Assumptions were:

- 1. Winter ventilation rates apply for the 1st & 4th quarters.
- 2. Summer ventilation rates apply for the 2nd & 3rd. quarters.
- 3. Mercury concentrations were as reported in "Wilcox", page 111. For comparison, losses reported in the "Wilcox" report are printed alongside these calculations. Since actual exhaust air flows in 9201-4 were much higher than previously presumed, this calculation indicates that the total loss may

have been 32382 y 18447/bs.

Joseph 333262 165, nother than

Tables 4 is a summary of all contaminated air exhaust systems of 9201-4 for "summer" operation. This is a listing of exhaust fans, fan sizes, fan capacity in cfm, outlet velocities, orientation, and elevations.

in cfm, outlet veloci				_					
•								1+	Lag.
Α 7	D:12	ling F	rhouet	Table -	4 Summarr	_ for S	Summar (13/	
A	Бици	inig is:	xiiausi	Бувіеш і	Jummary	- 101 K	Jummer -	<i>y</i>	
		Fan	Area	Cfm	-fpm	dir	ection	Total	Z
Exhaust Location	No		sq. ft.	Each	Velocity	4	elev	cfm	
Cascade Roof Exh.	8	54	15.90	35000	2200	up	(105	280000	6%
Tray Exhaust	4			107200	2200	up	105\$	428800	9%
Roof Exhausters	4			26000	2200	up	105	104000	2%
From 1 & 2nd Floor	8			+	2200	up	105	590240	13%
Roof Total		-						1403040	30%
South Wall- Absorbers	15	72	28.27	70200	2483	horiz	1020	105300	22%
South Wall - Cascades	6	108	63.62	143000	2248	horiz O	1020	858000	18%
South Wall Total								1911000	41%
North Wall- Absorbers	5	72	28.27	70200	2483	horiz O	1020	351000	7%
North Wall - Cascades	6	108	63.62	143000	2248	horiz	1020	858000	18%
North Wall Total						-		1,209000	26%
2nd Floor East	4	42	9.62	22500	2339	horiz	1000	90000	2%
1st Floor East	2	60	19.64	45000	2292	horiz Q	980	90000	2%
1st Floor Total								180000	4%
Total of All Exhaust								4703040	100%
	<u> </u>				-		Sel Vot	V ₀ Y	

Table 5 is a scenario of winter operation of ventilation exhaust systems in 9201-4. Here exhaust air volumes were reduced by turning off certain fans. In table 5, the number of fans has been reduced as compared to those given in Table 4 to simulate the winter operation.

A Building Exhaust System Summary – for Winter

	_	in.	1						
	·	Fan	Area	Cfm	Am	in La	m) st	Total	%
Exhaust Location	No	Dia.	sq. ft.	Each	Velocity	direction	^elev	cfm	
Cascade Roof Exh	8	54	15.90	35000	220 D	up	105	280000	1
Tray Exhaust	4	•	-	107200	2200	up	105¢	428800	17
Roof Exhausters	4			26000	2200	up	1056	104000	4
From 1 & 2nd Floor					2200	up	105	591380	24
Roof Total								1404180	57%
South Wall- Absorbers	4/15	72	28.27	70200	2483	horiz	1020	280800	11
South Wall - Cascades	2/6	108	63.62	143000	2248	horiz	1020	286000	12
S.Well Total								566800	23%
North Wall- Absorbers	2/5	72	28.27	70200	2483	horiz	1020	140400	6
North Wall - Cascades	2/6	108	63.62	143000	2248	horiz	1020	286000	-11
N, WILL TOTAL								426400	17%
2nd Floor East	2/4	42	9.62	22500	2339	horiz	1000	40000	2%
7									7
1st Floor East	1/2	60	19.64	45000	2292	horiz	980	40000	2%
Total of All Exhaust	- ^						· · · · · · · · · · · · · · · · · · ·	2477380	100%
	<u> </u>			<u> </u>	1,	,	~	VOK	

As seen in Tables 4 & 5, contaminated building exhaust was predominantly from the roof fans and through the walls at the 3rd floor level. In summary:

		Summer		Win	ter
	Cfm	elevation\	%	cfm	ゃ
Roof	1403040	1056	30	1404180	57%
South Wall 3rd Floor	1911000	1020	41	566800	23%
North Walls – 3rd Floor.	1209000	1020	26	426400	17%
East Wall - 2nd Floor	90000	1000	2	40000	2%
East Wall – 1st Floor	90000	980	2	40000	2%

References:

1. General Ventilation Study – Bldg. 9201-4 – design notes

more dates?

- 2. Building 9201-4-4 Tray Rooms design sketch
- 3. Proposed Cascade Ventilation design sketch
- 4. Proposed Absorber Ventilation design sketch
- 5. McAlister, Don, General Ventilation- Bldg. 9201-4, 8/15/55 design sketch
- 6. EM-708 through EM-729, Master Plan Drawings completed 1970. These are believed to represent As-Built conditions for the Colex Production Project. Since this building has not been modified since shut-down, these drawings should be an accurate record of 9201-4 ventilation systems of 1996 as well.
- 7. Catalytic Construction Company's Ventilation Flow Sheets
- 8. Catalytic Construction Company's Construction Drawings

Q: No differences for Sunamer vs. Winter?

Ventilation Systems of Building 9204-4 as Existed in 1953

> by E. E. Choat

Building Data

Figure 1 is a partial plan of the 2nd floor and a sectional view of building 9204-4 that is believed to be the building space occupied by the Elex Production Plant during the early 1950's. Elex occupied essentially all of the space between column lines 1 - 43, and F - J. It represents an area of 34,226 ft² and a building volume of 1,745,550 ft³.

Subsequent to the shutdown of the Elex Production Plant, the building was stripped of all process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflected conditions that existed in 1952 - 55.

For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in early fifties.

Phase X Ventilation

The initial design for this plant was done by the Vitro Corporation, and provided for 554,400 cfm of exhaust. This volume of air in the space occupied by the Elex Plant resulted in an air change rate of 19 changes per hour.

Building exhaust is thought to have been by three modes as follows:

1. Nine (9) Roof Ventilators --- 194,400 cfm

2. Two (2) Exhaust Stacks --- 120,000 cfm 🗸


3. Six (6) Propeller Fans – mounted in the walls – 240,000 cfm

The location of these exhaust points is illustrated in Section B - B of Figure 1. They were also shown on Vitro drawing 50-K2-10. This drawing has been superseded by subsequent design changes and is now identified as Catalytic drawing B-32147. Master Plans of this building, completed in 1985, show these fans as still existing at that time.


Except for the two fans that exhausted to stacks, the sizes, air volume capacity, and outlet are summarized in Table 1. The two unidentified fans are believed to have been 2 centrifugal fans located on the 1st floor fan room on the North side of the building. These fans exhausted to stacks which extended up the outside wall to an elevation above the roof?

William Pere .

Figure 1
Plan and Sectional View of Elex Production Plant --- Building 92**9**4-4



Partial Plan of 2nd Floor Building 9204-4 -- grade 1010



Elevation B-B

Sec

Table 1
Exhaust Fans Provided for Elex Production Plant – Phase 1

Outlet Outlet Fan Air Velocity Volume size Area -Cfm Inches ft^2 Fpm 7.07 ✓ 2829 20000 Roof Ventilator 36 10 7.07 2829 Reference: 20000 36 Roof Ventilator 11 Calalytic drawing B-32147. Roof Ventilator 24800 36 7.07 3508 12 Issue date 11/6/53. Includes Roof Ventilator 20000 36 7.07 2829 13 as built work under contract 40011. 7.07 3508 Roof Ventilator 24800 36 14 Supersedes Vitro Dwg. 50-K2-10. 7.07 2829 20000 15 Roof Ventilator 36 7.07 Roof Ventilator 24800 36 3508 16 7.07 2829 36 Roof Ventilator 20000 17 7.07 2829 Roof Ventilator 20000 36 18 Believed to be systems cited W. 36.00 1667 Exh. to Stack 72×72 60000 Brumann report to W. K. Whitson. 60000 72×72 36.00 1667 Exh. to Stack 10/28/53. K-10905-1 Prop Fan - wall 40000 60 19.64 2037 K-10905-2 Prop Fan - wall 40000 60 19.64 2037 2037 40000 19.64 K-10905-3 Prop Fan - wall 60 See Vitro dwg. 86-K2-5 40000 60 19.64 2037 K-10905-4 Prop Fan - wall CFC 1953 - Jasny 19.64 2037 K-10905-5 Prop Fan - wall 40000 60 2037 K-10905-6 Prop Fan - wall 40000 60 19.64 554400 A total Exhaust of 554400 cfm correlates well with 538;000 predicted from Brumann 953 report. 6/2/96

1061, nb 1061, nb

E. E. Choat

43h

The magnitude of exhaust ventilation provided in the initial design may also be extracted from W. Brumann's report to W. K. Whitson¹. In this report, air sampling was done for 2 exhaust systems having a capacity of 60000 cfm. At the concentrations reported for the North Plant, this volume of air would result in 0.86 pounds of mercury per day being delivered to the environment. But, the report stated that 3.8 pounds was lost. Therefore, 60000 must have been only a part of the total air exhausted. The total air volume required to deliver 3.8 pounds to atmosphere at the concentrations given, is 264,167 cfm. This calculation along with air flows and concentrations from the Brumann report is shown in Table 2.

1 W. Brumann, Industrial Hygiene Section, to W. K. Whitson, 10/28/53.

Table 2
Estimated Elex Exhaust from Brumann Report

		ľ	ગેશ્ક કિ	<u>Exhaus</u>					. `
	Exhaust		Conc	entration		14/28/53	8.6168		
Sample	Cfm	m³/day	mg/m³	mg/day	grams/day				
1	7500	305856	0.14	42819.84	42.81984	0.09			
2	7500	305856	0.14	42819.84	42.81984	0.09			
3	7500	305856	0.12	36702.72	36.70272	0.08			
4	7500	305856	0.15	45878.4	45.8784	0.10			
5	7500	305856	0.22	67288.32	67.28832	0.15			
6	7500	305856	0.2	61171.2	61.1712	0.13			
7	7500	305856	0.15	45878.4	45.8784	0.10			١,
8	7500	305856	0.16	48936.96	48.93696	0.11			(
Total	60000	2446848		391495.7	391.4957	0.86			
Average Con		Poportod :	- 16						
Total Reporte				rth/Diant —	 -2~ hē\	For this to	<u>ll</u> otal loss, air	flow	
		higher. The				ורטו נוווא נו	Cfm =	264167	$ _{\nu}$
must be v	J.07.00000	1	Cii, Oiii	1 00000 0	1	10/28/53			
Plant Total	265000	10806912	0.16	1729106	1729.106	3.81	agrees with	report	İ
	200000	10000012	1438/23		1720.100	0.01	agrees man	Торогс	ĺ
Sample 9	7500	305856	0.22	67288.32	67.28832	0.15			
10	7500	305856	0.22	67288.32	67.28832	0.15			ĺ
11	7500	305856	0.21	64229.76	64.22976	0.14	-		
12	7500	305856	0.21	64229.76	64.22976	0.14			
13	7500	305856	0.19	58112.64	58.11264	0.13			١
14	7500	305856	0.17	51995.52	51.99552	0.11	-		l
15	7500	305856	0.16	48936.96	48.93696	0.11			ĺ
16	7500	305856	0.18	55054.08	55.05408	0.12	-		ĺ
	60000	000000	0.10	00001.00	00.00 100	1.05			
		5 1 - 1	0.00		ļ		1		
Average Cor Total Report	ed Solven	t Loss from	= .0.20 the(So	 ufb≀Plant =	4:8:lbs.)	For this t	l otal loss, air	flow	ł
, ,		igher. Then					Cfm =	274286	V
must be		40.7808	, U		10-3	453.5			ľ
Plant Total	265000			2161382	2161	4.76	agrees with	report	
							500,450 /		
Total Buildin	g Exhaust	t is estimate	d to be	= 274,286	+ 264167	=	538453√		ł
5/8/96 Today	 / I talked wit	l h Bill Whitson.	 le is 82	 now-and-net	well. He thinks	that the	<u> </u>		1
1		in 1954 were			м.	1			1
	<u> </u>	T				-			1
5/14/96 Talk	ed to Glenn	Kitchings dr	aftsman	on B-4 master	plans. He is n	ow-working	at Downtown H	ardware. e	•
I									-

In the same manner, total air flow from the South Plant was calculated as being 274,286 cfm. The sum of North plant exhaust and South plant exhaust

Hotherbes that the well fors proposed in 1954 were installed.

7

is equal to 538,453 cfm which is only 3% less than values shown on the drawings. \checkmark

Phase II Ventilation

Additional ventilation of the Elex Plant is believed to have been installed in the later months of 1954. In a letter -- to Mr. R. C. Armstrong, USAEC from J. P. Murray, Y-12 Plant Superintendent - of 7/15/54, it was noted that contamination levels were too high. This letter also recommended 500000 cfm of additional ventilation. This was to be accomplished with additional propeller fans installed in walls around the cascade.

I believe that this proposal was implemented for the following reasons:
(W.K. Whitson and Glenn Kitchings)

- 1. I have talked to two people, who were employees in the 9204-4 building during the time of Elex, and they both think that this plan was implemented.
- 2. Also, Martin Maritta drawings H2E002078MP & H2E002079MP show 16 fans installed in the walls along columns F & J. These drawings are from the "Master Plan" series, dated 5/8/85. Six of these fans are the same as those shown in the original design by Vitro. The other 10 are believed to be those referenced in the Armstrong letter. These ten fans of a moderate size could have easily provided the 500000 cfm cited. I believe this air volume to be near that installed, as it was noted that the fans were "on hand" in Y-12.

With an additional exhaust of 500000 cfm, the air change rate during the summer operation of the Elex Production Plant would have been 36 changes per hour.

References

74. W. Brumenn, Industrial Hyggiene: Section, to W.K. Whitson, 10/28/53.

3. J.P. Murray, 4-12 Plant Manager, to R.C. Aumstrong, USAEC, 9/12/54.

3. J.P. Murray, 4-12 Plant Manager, to R.C. Aumstrong, USAEC, 9/12/54.

3. W.K. Whitson, personal communication with E.E. Choat, 5/14/96.

4. Glenn Kitchings, personal communication with E.E. Choat, 5/14/96.

4. Without dissing 50-K2-10 1 Date= ?

Carping South

Carping So-K2-10 1 Date= ?

Cathytic Construction dissing & B-32147

Cathytic Construction dissing & B-32147

Date= 11-6-53

Martin Manatta master plan dissing series, 5-8-85.

1563 AG 1564 or or of the stack libs site 1565 or of the stack libs site 1665 or of the stack libs s	Slag vernu	Didy Vermiation was increased 50 % in summer stating in 1950.							·	
1983 40 45 d only 108 stack 108 st				ž	10.01	70				
1953 3.0 45 d only 380.7 NRRestrict 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1953 4.7 1954 4.7 1954 4.7 1954 4.7 1954 4.7 1954 4.7 1955 4.7	E GE		Ibs stack -	IDS all	IDS HZ gas	nesn sai				
953 20 45 d only \$80.7 NR-Review of the second of the se						for mod				
953 42 90 d 761.4 1/22.1 693.0 761.4 1142.1 1 11	953 30	45 d only	380.7		,					
Total Tota				_]						
Total Total Total E60.0 Total E60.0 Total E64.0 Total E64.0 Total E65.0 Total E65.	953 4Q		761.4							
Sept 40 7614 814 820.0 7616 820.0 7616 7616 820.0 7616 820.	Tota	-					1142.1			
1982 1982 1983 1985	954 10		761.4							
1987 1987 1987 1988 1988 1987 1988 1988 1987 1988	954 2Q		761.4							
10 10 10 10 10 10 10 10	954 30		761.4							
1965 10 10 10 10 10 10 10 1	954 40		761.4							
965 102 967 A verific incid 1142,1 551.8 630.3 1142.1 968 502 verific incid 1142.1 551.8 630.3 1142.1 968 503 verific incid 1142.1 551.8 630.3 1142.1 968 504 verific incid 1142.1 551.1 551.1 551.1 968 504 stripping bddg NA 51.8 NA 51.8 51.8 968 10 stripping done NA NR NA 0.0 1689.7 1987 NA NR NA 0.0 1689.7 1987 NA NR NA 0.0 1689.7 1988 20	Tota									
September 142.1 511.6 630.3 1142.1 511.6 630.3 1142.1 512.1 512.0 1142.0 1142.0	955 10		761 4				2000			
1955 AG Vertila fried 142.1 557.1 545.0 142.1 142.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 1557.1 142.1 14	2000	4	7 (777							
Second State	2202	4	1142.1							
256 10 267 267 492.2 761.4 3807.0	922 3Q		1142.1							
Total Tota	955 4Q		761.4							
256 10 10 10 10 10 10 10 10	Tota									
SEG 202 stripping bldg NA 4265 NA A	956 1Q		761.4							
1956 30 stripping bldg NA 511.8 NA 511.8 NA 510.8 Sec 40 stripping bldg NA NR NA 0.0 1699.7 Sec 40 stripping done NA NR NA 0.0 1699.7 Sec 4.0 stripping done NA NR NA 0.0 Sec 4.0	956 2Q	stripping bldg								
1957 Total NA	356 30	stripping bldg								
Total	356 40	stripping done								
1957 NA NR NA 0.0	Total						-			
1957 NA NR NA 0.0 NA NR NA NA NR NA NA NA NA NA NA NA NA NA NA NA NA NA										
1988 10 1998	195,		AN				0.0			
958 1Q B-4 extract NR 0.0 Process Process NR 0.0 Process										
558 2Q 767.7 767.7 767.7 767.7 558 3Q 511.8 511.8 511.8 6	358 1Q	B-4 extract		AN.		0.0				
179.5 179.	358 2Q			7.797		7.797				
179.5 179.5 179.5 179.5 179.5 179.5 170.6 170.	358 3Q			511.8	-	511.8				
Total 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.2 134.2 170.6 170.	958 4Q			179.5		179.5				
359 1Q B-4 extract 134.6 134.6 134.6 134.6 134.6 134.6 134.6 134.2 1341	Tota	-					1459.0			
341.2 341.2 341.2 341.2 341.2 341.2 359.2 369.2 269.	359 1Q	乚		134.6	100	134.6				
170.6 170.	359 20	┞		341.2		341.2				
Total avg 269.2 915.6	959 30			170,6		170.6				
Total avg avg 12069.0	959 4C			269.2		269.2				
avg avg avg avg avg avg avg avg avg avg	Tota	-								
Total 5839.4 585.3 12069.0 lotes: * based on 8.46 lb/d in exhuast air measured in October 1953. -# 1953-30-lbs-were_estimated-by-using the-avg-lbs-released-per-qtr-for-pre-1855 and-post-1955 winters 173-lbs-x (45d / 90d), or 0.5) = 86 NA = not applicable (H2 gas emissions during process operations only)					avg					
lotes: * based on 8.46 lb/d in exhuast air measured in October 1953. # 1953 3Q-lbs were estimated by using the avg-lbs released per-qtr-for-pre-1955 and post-1955 winters 173-lbs x (46d / 99d), or 0.5) = 86. NA = not applicable (H2 gas emissions during process operations only)	Tota			5839.4						
lotes: * based on 8.46 lb/d in exhuast air measured in October 1953. ## 1953-3Q-lise were estimated-by-using the avg-lbs-released-per-qtr-for-pre-1955 and-post-1955 winters 172-lbs x (46d / 90d), or 0.5) = 86. NA = not applicable (HZ gas emissions during process operations only)										
NA = not applicable (H2 gas emissions during process operations only)	lotes: *	based on 8.46	lb/d in exhua	ist air measure	d in October	1953.	-	1 227	(FOC) FOC)	00 = 00
NA = not applicable (nz gas emissions during process operations only)	# 3	M-sq-mc-ccn	ste estimated	by using the a	vg-lbs-releas	or per que tor pre	1800 DUB COR	Soo winters 170-11	* (400 1 200) A	13) 00:
	Z	= not applicable	e (nz gas en	ilssions auring	brocess oper	alloris offiy)				

Year	Quarter	Exhaust		Hg Conc	Effluent					
		cfm	m3/day	mg/m3	mg/m3 mg/day	g/day	lbs/day	lbs/qtr	lbs/yr	Comments
1953	-									
	2									
45 d only	က			10.				4.641		
	4	554,400	22609345.8	90'0	1356560.75	1356,561	1.356561	122.1		
							_		122.1	364.5
1954	-	554,400	- 1	0.04				81.4		
	2	554,400	- 1	0.1		_		203.5		
_	ဗ	554,400	1					142.4		
	4	554,400	22609345.8	90'0	1356560.75		1.356561	122.1		
			. 1						549.4	
1955	-	554,400		80'0				162.8		
	2	1,054,000		90'0	li	"	5.686949	511.8		
	3	1,054,000		20'0	3008870.01	3008.87	6.634774	597.1		
	4	554,400	22609345.8	90'0	1356560.75	1356,561	2.991314	269.2		
									1541.0	
1956	1	554,400		20'0		_		314.1		
	2	1,054,000	_				4.739124	426.5		
	ဂ	1,054,000	42983857.3	90.06	2579031.44	2579.031	5.686949	511.8		
	4	554,400	22609345.8	NR				0.0		dismantling;stripping complete
									1252.4	
1957	-	554,400		NR.						
	7	1,054,000		NR						
	က	1,054,000	١	NR.						
	4	554,400	22609345.8	NR						
			- 1						0.0	
1958	-	554,400	- 1	AN.						
	2	1,054,000		0.09		1		7.797		B-4 extract ops
	က	1,054,000		90.0	~	1		511.8		
	4	554,400	22609345.8	0.04	904373.83	904.3738	1.994209	179.5		
									1459.0	
1929	-	554,400	- 1	0.03		678.2804		134.6		
	7	1,054,000	- 1	0.04	_		3.791299	341.2		
	က	1,054,000		0.02			1.89565	170.6		
	4	554,400	22609345.8	0.06	1356560.75	1356.561	2.991314	269.2		
									915.7	
1960	-			S. S.						
	2									
	က									
	4									
							TOTALS	5839.6	5839.6	
									i	

I'm going to type this out and ask if you concur, or can think of a better resolution to a dilema I have. I need to give Samer an answer asap. THX!

Beta-4 Building

- 1. The Elex process produced mercury-contaminated hydrogen gas from the decomposition of the amalgam. The Hg Task Force cited a study of the building exhaust in Oct 1953 that estimated 8.46 lb Hg released per day. I have reviewed the handwritten calculations of this study and concur with the 8.46 lb. The process operated for 32 months (from August 1953 to March 1956) and assuming 7d/wk 24 h/d, this is 8300 lbs. (Hg Task Force). We initially spread this out over 3 yr @ 2767 lb per yr.
- 2. The Colex process water-scrubbed their hydrogen gas to remove the Hg (conc after scrub=0.02 mg/m3 >>> 10 lb of Hg released for all 8 yrs of Colex- this is nothing). Also note that I have read that Colex produced a lot less hydrogen gas from their process (decomposition reduced efficiency of the process and was undesirable). I have no data on the volume of gas or Hg content of the gas from the Elex process.
- 3. Ernie says that the building ventilation for the 6 summer months was doubled starting in 1955. I have a combination of weekly and monthly and quarterly average Hg building air concentrations for 1954-56. I don't think this Hg contaminated hydrogen was floating around the building floor areas (for safety reasons), but I know it was vented in the building exhaust and therefore would be included in the 8.46 lbs. To test that theory, I calculated the lbs using the air concs and Ernie's ventilation rates (for 1954-56) and it is much lower than the 8.46 lb/d. The mean + 1SD of the quarterly avgs for 1954-56 is 3.3 +/- 2.1 lbs/d.
- 4. I thought the other day that I would use both the exhaust and the building air, but that is double counting all Hg emissions other than the hydrogen vent gas.

If I apply the 8.40lbs/d measured in Oct 1953 to 1954-56, I'm ignoring the 50% increase in ventilation for 1955 and 1956.

I don't want to just use the indoor air concs because they wouldn't reflect the hydrogen gas.

	lbs in stack lbs	s in indoor air	lbs in H2 gas
1953 45	dv /380.7		381-86 avg45d= 295(45d)
1953 4th	u(*) . \ /	122.1	761-122= 639
1954 10	7761.4	81.4	761-81= 680
1954 20	761.4	203.5	761-204= 557
1954 3Q	2045.6 761.4	142.4	761-142= 619
1954 4Q	761.4	122.1	761- 91= 680
1955 1Q	/ 761.4	.08 -NR (173) 1625	
1955 2Q	s / 1142.1	[511.8]	1142-512= [630]
1955 3Q	s 3801, \\\ \frac{1142.1}{1142.1}	[597.1]	1142-597= [545]
1955 4Q	761.4	269.2	761-269= 492
1956 1Q		314.1	761-314= 447
1956 2Q	S stripping bldg (426	5.5) [426.5]	0
1956 3Q	S stripping bldg(511	1.8) [511.8]	0
1957		NR -O-	0
1958	B4 extract(1459)) → 1459	?
1959	B4 extract(916)	→> 916	?

NOTES:

1. S= summer ventilation= 50% increase

12069

- 2. The lbs Hg released per quarter based on indoor air for the pre-1955 and post-1955 winter ventilation conditions is 173+/-92 (Mean +1SD). The post-1955 summer is 512+/-70. (If I don't separate summer and winter after 1955 change, it's 300+/-200, so that makes sense.)
- 3. The lbs Hg in the H2 gas is 588+/-74. (looks fairly constant)
- 5. I assumed no hydrogen gas during stripping.
- 6. I adjusted the 1953 3rdQ to 45 d (started on 8-18-53).

There is another operation for which Hg air concs are available in Beta 4 building in 1957 and 1958 called Beta 4 extract. These are in Solvent Air Monthly reports from the top IH guy Leo LaFrance. I haven't found anyone alive who knows what this was. I included these even though the Hg Task Force report says nothing about this operation—(total of 12069 = 17% of all Hg emissions from all bldgs for all yrs).

Confession: This reminds me of something about building air concentration data. For a lot (or all) of the data, avgs were reported for certain process areas of a building (purpose was to id problem areas). I sometimes have seen no. of samples data that show more samples were taken in some areas than in others. I did not (due to available time and \$, or to lack of data) average individual daily values to get a true monthly avg. I used avgs of area avgs that were not equally weighted. Unavoidable. If more data were taken in problem areas this would bias the avg air conc high. Ernie said that there were spot ventilation add-ons in problem areas that were not shown on drawings, so I thought maybe this would bias the ventilation rates a little low and tip the scale back.

were

						_				
Year	Quarter	Exhaust		Hg Conc Effluent	Effluent					
		cfm	m3/day	mg/m3	mg/m3 mg/day	g/day	lbs/day	lbs/atr	lbs/yr	Comments
1953	-									
نے ا							stack Hg			
-	11) 3						8.46			
	4	554,400	554,400 22609346	90.0	0.06 1356560.75	1356.561	1.356561	122.1		
										122.1 vs. 761.4 USED
1954	-	554,400	554,400 22609346	0.04			0.904374			
		554.400	554,400 22609346	0.1	2260934.58	2260.935				
	6	554.400	554,400 22609346	0.07	7	1582.654		142.4		
	4	554.400	554,400 22609346	000		904.3738	0.904374	4:18	المهمي	
	100									508.7 vs. 3045.6 USED
1955	1955 ** 1	554.400	554.400 22609346	OS (NR				4:401:4	1628	
	2	1 054,000	054,000 42983857		2579031.44	2579.031	5.686949			
	6		054,000 42983857	0.07	0.07 3008870.01	3008.87	6.634774			
	4		554,400 22609346		0.06 1356560.75	1356.561	2.991314	269.2		
									2139.6	21 <u>39.6</u>]vs. 3045.6
1956	7	554.400	554.400 22609346	0.07	1582654.21	1582.654	3.489866	314.1		vs. 761.4
		1.054.000	42983857		2149192.86	ـــــ	4.739124	426.5		vs. 761.4
	1 (**	1 054 000	054,000 42983857	0.06	2579031.44	_	5.686949	511.8		vs. 761.4
	4		554,400 22609346					0.0		dismantling;stripping complete
									1252.4	1252.4 vs. 2284.2
1957	-	554,400	554,400 22609346	NR						
	2	1,054,000	42983857							
	က	1,054,000	,054,000 42983857	NR						
	4	554,400	554,400 22609346							
									0.0	
1958		554,400	554,400 22609346	I NR						
	2	1,054,000	,054,000 42983857		3868547.15		_			B-4 extract ops)
	က	1,054,000	,054,000 42983857				-			
	4	554,400	554,400 22609346	0.04	904373.83	904.3738	1.994209	179.5		
					1				1459.0	
1959	1	554,400	554,400 22609346						10	
		1,054,000	1 42983857		↽		വ		01	
	က	1,054,000	,054,000 42983857	_	859677.15		1.89565		70	
	4	554,400	22609346	90.0	1356560.75	1356.561	2.991314	1 269.2		
									915.7	
1960				NR	0.1					
	2									
	ဗ									
	4									
									_	
										2

9204-4	bs/dr lbs/vr Comments		EU10-0[1]	0 14 1953		761.4 761.4		16/4	# 176	17/4	21:12 2016	9.7.7.0C 1.101.		(6):4	511.8			4828.0 +367.8 A.A.O.O.		426.5	(-641-6) WWW	dismantling;	1636-6-stripping complete				4			/6/./ b-4 extract ops		2000 1400°	t	`	341.2	170.6		449.65 845.65					000	Æ	ļ
Calculation of Pounds of Mercury Exhausted to Atmosphere per Quarter from Building 9204-4	ll velday	(appeal)			₩.	8.56		94.8	277.0	3,00		8:-18	71.6		2579.031	3008.87	-		3008.87 6.634774	2149.193	2579.031									3868.547	2579.031	29 1719.354 3.791299		1289.516	29 1719.354 3.791299	859.6771	44 2579,031 5,686949							TOTALS	
ited to Atmosphere pe	Hg Conc Effluent	mg/ms mg/day			, , ,	30. AMR .05	•	AK OF		TO TOWN	1	英。			0.06	0.07	7 0.06 2579031.44		7 0 07 3008870.01	0.05		NR.		NR NR				NA NA	NR.		7 0.06 2579031.44	_			_	57 0.02 859677.15		25	QN	\INI					
nds of Mercury Exhaus	\neg	ctm m3/day			是有多	/ 554,400 22609346		C JURANOS	000000000000000000000000000000000000000	2000	\$5.4400	× 224483	≫		1,054,000 42983857	1,054,000 42983857	1.054.000.42983857		4 054 000 42983857	1,054,000,42083857	1 054 000 42983857	4 PE4 PDD 42983857	1,004,000	73858061 000 1301	300000 000 1-10 1	1,054,000 4283837	1,054,000 423655	1,054,000 4298385/	11,054,000 42983857	1,054,000 42983857	1,054,000 4298385	1.054.000 42983857		1.054.000 42983857	1 054 000 42983857	1 054 000 42983857	1,087,000,47983857	1,000,400,1							
Calculation of Pour	Year Quarter		1953		က	4		105/		7	9	4	<u> </u>	1955			4		4056	0081	4 6	0 5	t	4067		7 0	2	4	/ 1958 \ 1	2	3	4		1959				1		1960	2	_ν	4		_
					Q.ia.	P. C.									ついせくとく	\ ا ا			3	MACA																			`	<u>১</u>		ナ	•	7000	

Page 1 of 1

July 27, 1996

Ventilation Systems of Building 9204-4 as Existed in 1953 by E. E. Choat

Building Data

Figure 1 is a partial plan of the 2nd floor and a sectional view of building 9204-4 that is believed to be the building space occupied by the Elex Production Plant during the early 1950's. Elex occupied essentially all of the space between column lines 1 - 43, and F - J. It represents an area of 34,226 ft2 and a building volume of 1,745,550 ft³.

Subsequent to the shutdown of the Elex Production Plant, the building was stripped of all process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflected conditions that existed in 1952 - 55.

For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in early fifties.

Phase I Ventilation

The initial design for this plant was done by the Vitro Corporation, and provided for 554,400 cfm of exhaust. This volume of air in the space occupied by the Elex Plant resulted in an air change rate of 19 changes per hour.


Building exhaust is thought to have been by three modes as follows:

- 1. Nine (9) Roof Ventilators --- 194,400 cfm
- 2. Two (2) Exhaust Stacks --- 120,000 cfm
- 3. Six (6) Propeller Fans mounted in the walls 240,000 cfm

The location of these exhaust points is illustrated in Section B - B of Figure 1. They were also shown on Vitro drawing 50-K2-10. This drawing has been superseded by subsequent design changes and is now identified as Catalytic drawing B-32147. Master Plans of this building, completed in 1985, show these fans as still existing at that time.

Except for the two fans that exhausted to stacks, the sizes, air volume capacity, and outlet are summarized in Table 1. The two unidentified fans are believed to have been 2 contrifugal fans located on the 1st floor fan room on the North side of the building. These fans exhausted to stacks which extended up the outside wall to an elevation above the roof.

contributed to the 120,000 cfm?



Elevation B-8

Table 1
Exhaust Fans Provided for Elex Production Plant - Phase 1

		Air	Fan	Outlet	Outlet			
		Volume	aize	Area -	Velocity			
		Cfm	Inches	ft²	Fpm			
10	Roof Ventilator	20000	36	7.07	2829			
	Roof Ventilator	20000	36	7.07	2829	Reference:		
	Roof Ventilator	24800	36	7.07	3508	-	wing B-32147	
	Roof Ventilator	20000	36	7.07	2829		/6/53. Includo	
	Roof Ventilator	24800	36	7.07	3508	}	under contra	
	Roof Ventilator	20000	36	7.07	2829	Supersedes	Vitro Dwg. 50-	NZ-1U.
16	Roof Ventilator	24800	36	7.07	3508			 _
17	Roof Ventilator	20000	36	7.07	2829			ļ
18	Roof Ventilator	20000	36	7.07	2829			<u> </u>
	Exh. to Stack	60000	72 x 72	36.00	1667	1	o systems cita	
	Exh. to Stack	60000	72 x 72	36.00	1667		part to W. K.	Whitson,
K-10905-1	Prop Fan - wall	40000	60	19.64	2037	10/28/53.		
	Prop Fan - wall		GO	19.64	2037			
	Prop Fan - wall		60	19.64	2037			<u> </u>
	Prop Fan - wall		60	19.64	2037	See Vitro dy		1
	Prop Fan - wall		60	19.64	2037	CFC 1953 -	Jasny	
	Prop Fan - wall		60	19.64	2037			
	l	554400						
								<u> </u>
		1					fm correlat	
17 18 K-10905-1 K-10905-2 K-10905-4 K-10905-5				well wi	th 538,00	predicted	from Brun	ann
6/2/96				report.				
	ıt.			T		<u> </u>	•	

The magnitude of exhaust ventilation provided in the initial design may also be extracted from W. Brumann's report to W. K. Whitson¹. In this report, air sampling was done for 2 exhaust systems having a capacity of 60000 cfm. At the concentrations reported for the North Plant, this volume of air would result in 0.86 pounds of mercury per day being delivered to the environment. But, the report stated that 3.8 pounds was lost. Therefore, 60000 must have been only a part of the total air exhausted. The total air volume required to deliver 3.8 pounds to atmosphere at the concentrations given, is 264,167 cfm. This calculation along with air flows and concentrations from the Brumann report is shown in Table 2.

¹ W. Brumann, Industrial Hygiene Section, to W. K. Whitson, 10/28/53.

4

 ${\bf Table~2} \\ {\bf Estimated~Elex~Exhaust~from~Brumann~Report~^1}$

Γ		Exhaust	-	Conc	entration				
Į.	Sample		m³/day	mg/m³	mg/day	grams/day	lbs/day		
f	1	7500	305856	0.14	42819.84	42.81984	0.09		
}	2	7500	305856	0.14	42819.84	42.81984	0.09		
ŀ	3	7500	305856	0.12	36702.72	36.70272	0.08		
t	4	7500	305856	0.15	45878.4	45.8784	0.10		
ŀ	5	7500	305856	0.22	67288.32	67.28832	0.15		
ļ	6	7500	305856	0.2	61171.2	61.1712	0.13		
	7	7500	305856	0.15	45878.4	45.8784	0.10		
•	8	7500	305856	0.16	48936.96	48.93696	0.11		
		60000	2446848		391495.7	391.4957	0.86		
			D - 4.4	16					
	Average Cor Total Report	ed Solven	t Loss from	the No	rth Plant = :	3.8 lbs.	For this to	otal loss, air	flow
	must be	3.8/.86309	higher. Th	en, Cfn	n = 60000°3	8.8/0.86309		Cfm =	264167
4.									
ethory.	Plant Total	265000	10806912	0.16	1729106	1729.106	3.81	agrees with	report
4.									
	9	7500	305856	0.22	67288.32	1			
	10	7500	305856	0.22	67288.32			<u> </u>	
	11	7500	305856	0.21	64229.76				
	12	7500	305856	0.21	64229.76			ļ	
	13	7500	305856	0.19	58112.64	1	A		
	14	7500	305856	0.17	51995.52			ļ	
	15	7500	305856	0.16	48936.96				
	16	7500	305856	0.18	55054.08	55.05408			
		60000				<u> </u>	1.05		
				<u> </u>			<u> </u>		
	Average Co	ncentratio	n Reported	= .0.20	Diana -	4 9 iba	For this	total loss, air	flow
	Total Repor	ted Solver	it Loss from	i the Sc	on Plant =	4.0 105.	FOI IIIS	Cfm =	274286
	must be	4.8/1.05	nigher. Ther	n, Cim =	= 60000 4.6	371 Ua.	-	Cini	217200
ch ~	Plant Total	265000	10806912	0.2	2161382	2161	4.76	agrees with	report
South		1							
_	Total Buildir	ng Exhaus	t is estimate	ed to be	= 274,286	+ 264167	=	538453	
	5/8/96 — Toda	u talked w	ith Bill Whitson	1. He is 8	2 now and not	well. He think	s that the	<u></u>	I
			d in 1954 were				T	T	
	***************************************	1	T	1	1	T			
	- Total 195	had to Glass	Kitchings - 0	Iraiteman	on B-4 maste	r plans He is	now working	at Downtown I	lardware.

In the same manner, total air flow from the South Plant was calculated as being 274,286 cfm. The sum of North plant exhaust and South plant exhaust

TOTAL P.01

is equal to 538,453 cfm which is only 3% less than values shown on the drawings.

Phase II Ventilation

Additional ventilation of the Elex Plant is believed to have been installed in the later months of 1954. In a letter -- to Mr. R. C. Armstrong, USAEC from J. P. Murray, Y-12 Plant Superintendent -- of 7/15/54, it was noted that contamination levels were too high. This letter also recommended 500,000 cfm of additional ventilation. This was to be accomplished with additional propeller fans installed in walls around the cascade.

I believe that this proposal was implemented for the following reasons:

- 1. I have talked to two people who were employees in the 9204-4 building during the time of Elex, and they both think that this plan was implemented.
- 2. Also, Martin Maritta drawings H2E002078MP & H2E002079MP show 16 fans installed in the walls along columns F & J. These drawings are from the "Master Plan" series, dated 5/8/85. Six of these fans are the same as those shown in the original design by Vitro. The other 10 are believed to be those referenced in the Armstrong letter. These ten fans of a moderate size could have easily provided the 500000 cfm cited. I believe this air volume to be near that installed, as it was noted that the fans were "on hand" in Y-12.

With an additional exhaust of 500000 cfm, the air change rate during the summer operation of the Elex Production Plant would have been 36 changes per hour.

538453 500000 1038453 cfm ony winter?
36 oùchonges/he

Ventilation Systems of Building 9201-2 as Existed in 1955

by E. E. Choat

Building Data

Building 9201-2 was built in the early 40's to house a portion of the electromagnetic process. It was shut down about 1947 but was not stripped of it's contents. At the time of the Colex Pilot Plant - which occupied only a small portion of the building - a major portion of the previous process was still in place.

hoped fore

Figure 1 is a key plan of building 9201-2 and a sectional elevation of that building. It is provided here to show the location of the Colex Pilot Plant that existed there in the early 50's. As shown here, two (2) Absorber Trays were located along column line "d" between column lines "15" & "20". Floor area occupied by this equipment was approximately 20 x 90 feet or 1800 ft2. These two trays are shown on drawing E-HV-20238. A third tray was reported in an Industrial Hygiene Report of 12/19/54. I assume it was in the same vicinity and occupied about 1200 ft2.


Other components of the Plant - consisting of columns, pumps, etc. - were installed along the east end of the building, between column lines "d" & "k". It occupied a floor area of approximately 4000 ft² on three floors.

The total building volume that was occupied by the Colex Pilot Plant is estimated to be 525,000 ft³.

Supporting services, - such as Maintenance, Development Offices, Engineering Offices, & DC power supply were located in adjacent areas. A major portion of the building was unoccupied but did house the remnants of the former process.

monum seponation Subsequent to the shutdown of the Colex Pilot Plant, the building was stripped of the Colex process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflect conditions that existed in 1952 - 55.

For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in early fifties. Also factored into this study is the personal opinion of one of the design engineers (E. E. Choat) who was a part of the engineering team for the Colex Pilot Plant project.



Elevation A - A

Process Ventilation

413

Process ventilation for this plant consisted of an exhaust system from each of the Absorber Trays. The details of one of these are shown on E-HV-20238, "Absorber Tray Ventilation", 1955. An air volume of 1500 cfm was exhausted by this system to 6 feet above the roof south of column line "d". The elevation of this roof is 967 feet above sea level.

1955

A portion of the exhaust system for the second tray is also shown on E-HV-20238. However, it does not show the volume of air exhausted nor the point of exit. Since it does have slightly larger ducts, the exhaust volume is estimated to be 2000 cfm. It too, was probably exhausted above the roof at an elevation of 967.

1958

The third tray is assumed to have been a slight variation of the trays 1 & 2, and to have a comparable exhaust system - i.e. 2000 cfm exhausted to the low roof south of column line "d".

12/54

General Ventilation

General ventilation for the Colex Pilot Plant was almost non-existent. It consisted of systems that were installed for the previous process and that were still operable. These systems were not equipped with heating coils as the previous process was a terrific heat generator --- no heating was required. Too, supply was introduced toward the center of the building as needed by the previous process. It was not very effective in ventilating the area occupied by the Colex Pilot Plant. Supply air could have been as much as 64000 cfm in summer. It was probably half of this in winter.

1970

General exhaust for the building was via roof ventilators located on the high roof (elevation 1004). An unknown number of these fans were operable and running during the Colex Pilot Plant operation. It is estimated that 2 fans were operated in summer and that only one was used in winter. Then, building general exhaust would be 32000 cfm in winter and 64000 cfm in summer.

Based upon the foregoing assumptions, air change rates for this plant is estimated to be 8 changes per hour for summer and 4 changes per hour for winter operation.

Also based upon the foregoing assumptions, Mercury introduced into the atmosphere from the Colex Pilot Plant is estimated to be 1.19 pounds per day during the summer and 0.63 pounds per day during the winter. Calculations for these values are shown in Table 1 and 2 that follow.

Table 1
Calculated Mercury Loss to Atmosphere for Summer Operation

	Calculate				PHOTO 101		F
lev		CLY	ን-)	12-19-54	(2)		
		Exhaust	40.781	x Conce	entration	453.5	
	5500	Cfm	m³/day	mg/m³	mg/day 19	grams/day	
913	Tray Exhaust	4500	183544	0.18	33032.45	33.03245	0.07.09
1001	General Ventilation	64000	2609971	0.194	506334.4	506.3344	1.12
ω.	Total	68500	2793485		539366.9	539.3669	149121

Table 2
Calculated Mercury Loss to Atmosphere for Winter Operation

	いる	Ò	12-19-54	_ (>_		
	Exhaust		Conce	entration (3)		
5500	Cfm	m³/day	mg/m³	mg/day	grams/day	lbs/day
Tray Exhaust	4500	183514	0.18	33032.45	_33.03245	_0.07.09
General Ventilation	32000	1304986	0.194	253167.2	253.1672	0.56
Total	36500	1488499		286199.7	286.1997	0.63,65

 $x = 58.5 \frac{1b}{gth}$ for 2 gths.

References:

- 1. "Absorber Tray Ventilation", a Union Carbide drawing number E-HV-20238, 1955.
- 2. Key Plans <u>H&V</u> Flow, a Union Carbide drawing number E-M-318 and others in this series. A list is given on this document, 1970.
- 3. Weekly Solvent Work Sheets, 1954.

IH Report 12-19-54

	2																					basement exhaust off	= (42.3)														
	bs/yr Comments		-		8791	3				2,00.5			(/ 115.3 /)				3.4			amased	65.8 - 25.6 =				784 5	2:5				48.0				00	2.00
	lbs/qtr lbs	20.7	19.9	1,1,1	4.7	#/1/	32.28	0.79	59.	 	769				23.6	33.3	16.6	2.9	σ			Ĭ			61.0					33.3							1
	lbs/day										0 554397		0.295408		0.262585			3 0.065646	097000		0.246398		0.20200			9 0.985594		1		A 369598						 	
	g/day										251 4180	1			119.0824	167.6126	83.80629		\perp	1_	111./41/	4	119.0824	74.42651	i	3 446.9669				7 167 6126	-	-					
Effluent	ng/day										20 024 440 06	4055/R 00	0.07 133967 71		119082.41	· -	83806.29	L.	l L		~	08.0/800	119082.41	74426.51						467647 67	74426 54	L					
Hg Conc	mg/m3 mg/day	0.0	0.09	0.09	11.0	7111	0.0	10.00	平26.4		ļ	0.03		800	0.08	90.0	0.03					(0.08	0.05	\$		R					0.02	NR.				
	m3/day								1488530		1488530	2/93543	4 400520	1400330	1488530			1488530	H	- 1	2793543	- 1	. 1		-1	2793543			- 1	- 1	- 1	1488530					
Voar Quarter Exhaust	\Box	21,500	0000	00839	36,500		36500	008X9/	36,500		36,500	68,500	005,50	36,300	36 500	68,500	68 500	36,500		36,500	68,500	68,500	36,500	36 500	68 500	68,500	36,500		36,500	68,500	68,500	36,500					
Ouarter		•	- 2	3	4		-	7 0	7		4	2		4	-	-	1 (0	4		-	2	က	4	-	-	1 (c)	4		-	7	6	4	,	-	4 60	4	

age 1

Ventilation Systems of Building 81 - 10 as Existed in 1955 bv E. E. Choat

Building Data

ABuilding 81 - 10, Solvent (Mercury) Salvage Facility, consisted of: a Gas Fired Furnace, Drum Unloading Devices, Conveyor, Crusher, & Cutter. These were mounted on a platform which may have been covered with a roof. An equipment plan of this facility is shown on drawings F4A-18002, F4Aand dist collected from spills 18003 and F4A-18004.

The Furnace was approximately 5 feet in diameter and 16 feet tall. It was mounted vertically beneath a platform and was heated via gas fired burners. Various materials - such as waste insulation which were contaminated with Mercury were introduced into the top, heated to a high temperature to vaporize the mercury and thus separate it from the solid materials. Solids who will were then removed from the bottom

The furnace was equipped with a cooling coil to cool hot flue gases to condense and separate the mercury from the gas, as a liquid.

The manufacturer's drawings of this furnace, along with information on the burners exist in the Y-12 plant files. These materials are "copyrighted" and are₁available on a read-only basis.

therefore I have not found any information regarding any ventilation that was provided for this facility. It seems possible that the only ventilation that existed was that provided by the wind blowing through the shed.

a 1957 letter refers to various measurements of the book of mercury from the appropriate studge burser. Any and written calculation refers to a 14 in character and 2 1300 Afm volume flow rate.

References

State Montportuer's dissings of furnose

States (AHR) for Bldg.

2. 81-10 demolition report is plates (Incheological & Historical Review (AHR) for Bldg.

4. logohets with handwritten disneter and volume flow rate

Y/HG-0169

Sludge Burner stack loss of solvent.

Morefead to Whitson letter 6/18/57

3. Stripping Plan for 81-10 by F.V. Tilson 9-22-83 draft, Y/TS-1610.

August 6, 1996

Y-12 Steam Plants Buildings 9401-1, 9401-2, & 9401-3 by E. E. Choat

Joocfm?

Building Data

Building 9401-1 & 9401-2 were relatively small, coal fired boiler plants, constructed in the 1940's to provide steam for processes and for heating buildings in Y-12. As recalled, they consisted of two boilers each which were equipped with traveling grate stokers. They were superseded by the construction of building 9401-3 in the mid 50's and were shut down. Subsequently, both buildings were converted to other uses.

Each of these buildings had a smoke stack, which has been removed subsequent to shut-down of the plants. Drawings have not been located that show sizes and heights of these. From my personal recollection of these, I would estimate that the height of these was about 100 feet. Platon and I got I and good I have been located, but they do not show the introduction. Building 9401-3 consists of 4 boilers having a full-load capacity of 250,000 pounds of steam per hour each — or a total of 1,000,000 pounds per hour. Initially, it was a pulverized coal fired plant, but was converted to use natural gas shortly after start up. The operating choice of fuel was made on the relative prices and the availability of gas. As I recall, the plant burned gas during summer months and coal in winter. Most likely, this practice varied from year to year.

This plant has two stacks that transport products of combustion to a an emission point that is 190 feet above grade. The west stack is 12.5 feet in diameter. The east stack is 15 feet in diameter. The top elevation of both is 1161 feet above sea level.

Effluents

Mercury emissions from these plants would vary widely depending upon fuel being used, the quantity of fuel, and mercury content of the fuel. I believe that plant operating records probably exist which would contain dated fuel usage and steam output. However, I do not recall having ever seen either a coal for natural gas analysis that tested for mercury.

References

1. photos of strn plants, 1-17-57

2. steam plants report Historical Bldg. assessment of the Osla Ridge

2. Steam plants report Historical Bldg. assessment of the Osla Ridge

4-12 Plant by Thomason & assoc., May 1996, A-256, A-405, A-494.

TOTAL P.02 PAGE.002

423 482 2605

July 28, 1996

Ventilation Systems of Building 9201-2 as Existed in 1955

bv E. E. Choat

Building Data
Building Control Building 9201-2 was built in the early 40's to house a portion of the electromagnetic process. It was shut down about 1947 but was not stripped of it's contents. At the time of the Colex Pilot Plant - which occupied only a small portion of the building - a major portion of the previous process was still in place.

Figure 1 is a key plan of building 9201-2 and a sectional elevation of that building. It is provided here to show the location of the Colex Pilot Plant that existed there in the early 50's. As shown here, two (2) Absorber Trays were located along column line "d" between column lines "15" & "20". Floor area occupied by this equipment was approximately 20 x 90 feet or 1800 ft2. These two trays are shown on drawing E-HV-20238. A third tray was reported in an Industrial Hygiene Report of 12/19/54. I assume it was in the same vicinity and occupied about 1200 ft2.

Other components of the Plant - consisting of columns, pumps, etc. - were installed along the east end of the building, between column lines "d" & "k". It occupied a floor area of approximately 4000 ft² on three floors.


The total building volume that was occupied by the Colex Pilot Plant is estimated to be 525,000 ft³.


Supporting services, - such as Maintenance, Development Offices, Engineering Offices, & DC power supply were located in adjacent areas. Λ major portion of the building was unoccupied but did house the remnants of the former process.

Subsequent to the shutdown of the Colex Pilot Plant, the building was stripped of the Colex process equipment so that new and different processes could be installed. Ventilation systems were then modified as necessary to accommodate the requirements of the new process. During these modifications, drawings of the building ventilation systems were changed according to the new design, and consequently, no longer reflect conditions that existed in 1952 - 55.

For this study, it has been necessary to search through existing drawings and documentation for sufficient information to reconstruct a model of the ventilation systems which existed in early fifties. Also factored into this study

professional is the personal opinion of one of the design engineers (E. E. Choat) who was a part of the engineering team for the Colex Pilot Plant project.





Elevation A - A

Process Ventilation

Process ventilation for this plant consisted of an exhaust system from each of the Absorber Trays. The details of one of these are shown on E-HV-20238, "Absorber Tray Ventilation", 1955. An air volume of 1500 cfm was exhausted by this system to 6 feet above the roof south of column line "d". The elevation of this roof is 967 feet above sea level.

A portion of the exhaust system for the second tray is also shown on E-HV-20238. However, it does not show the volume of air exhausted nor the point of exit. Since it does have slightly larger ducts, the exhaust volume is estimated to be 2000 cfm. It too, was probably exhausted above the roof at an elevation of 967.

The third tray is assumed to have been a slight variation of the trays 1 & 2, and to have a comparable exhaust system - i.e. 2000 cfm exhausted to the low roof south of column line "d".

General Ventilation

General ventilation for the Colex Pilot Plant was almost non-existent. It consisted of systems that were installed for the previous process and that were still operable. These systems were not equipped with heating coils as the previous process was a terrific heat generator --- no heating was required. Too, supply was introduced toward the center of the building as needed by the previous process. It was not very effective in ventilating the area occupied by the Colex Pilot Plant. Supply air could have been as much as 64000 cfm in summer. It was probably half of this in winter.

General exhaust for the building was via roof ventilators located on the high roof (elevation 1004). An unknown number of these fans were operable and running during the Colex Pilot Plant operation. It is estimated that 2 fans were operated in summer and that only one was used in winter. Then, building general exhaust would be 32000 cfm in winter and 64000 cfm in summer.

Based upon the foregoing assumptions, air change rates for this plant is estimated to be 8 changes per hour for summer and 4 changes per hour for winter operation.

Also based upon the foregoing assumptions, Mercury introduced into the atmosphere from the Colex Pilot Plant is estimated to be 1.19 pounds per day during the summer and 0.63 pounds per day during the winter. Calculations for these values are shown in Table 1 and 2 that follow.

By to per the state of the stat

Jest Col

4

Table 1 Calculated Mcrcury Loss to Atmosphere for Summer Operation

	Exhaust		Conce	ntration		<u></u>	
	Cſm	m³/day	mg/m³	mg/day	grams/day	ibs/day	
Tray Exhaust	4500	183514	0.18	33032.45	33.03245	0.07	
General Ventilation		2609971	0.194	506334.4	506.3344	1.12	
Total	68500	2793485		539366.9	539.3669	1.19	


Table 2 Calculated Mercury Loss to Atmosphere for Winter Operation

Exhaust		Conce	intration		
	m³/day	mg/m ³	mg/day	grams/day	lbs/day
	183514	0.18	33032.45	33.03245	0.07
		0.194	253167.2	253.1672	0.56
			286199.7	286.1997	0.63
	Cfm 4500 32000 36500	Cfm m³/day 4500 183514 32000 1304986	Cfm m³/day mg/m³ 4500 163514 0.18 32000 1304986 0.194	Cfm m³/day mg/m³ mg/day 4500 183514 0.18 33032.45 32000 1304986 0.194 253167.2	Cfm m³/day mg/m³ mg/day grams/day 4500 183514 0.18 33032.45 33.03245 32000 1304986 0.194 253167.2 253.1672

References:


- 1. "Absorber Tray Ventilation", a Union Carbide drawing number E-HV-20238, 1955.
- 2. Key Plans H&V Flow, a Union Carbide drawing number E-M-318 and others in this series. A list is given on this document., 1970.
- 3. Weekly Solvent Work Sheets, 1954.


 IH Report 12-19-54





Z **4**

Figure 2 Section A - A ---- Building 9201-5










Z 🗲



To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From:

E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 7/23/96-8-9-96 Pages including this cover page -- 11

Responses to your questions of 8/8/96 FAX.

1. A good average value for release velocities would be 2200 fpm.

2. I can understand why you did not understand 2%. I didn't do a very good job of writing that.

There made a second attempt to describe exhaust points in the form of two additional tables in the report. For these tables --- table 3 & 4 - shown the location of all exhaust fans, air volumes associated with these and percentages. You will note that these are somewhat different than other tables having design values. It's because some of these fans sit on a roof that is adjacent to the space that is being exhausted.

Also, I have written percentages on figure 2 that may be compared directly with tables 3 & 4/I believe that this format will read a lot easier for you.

These changes make it necessary to revise the report. Accordingly, I am sending via FAX along with this cover sheet.

- 3. For buildings 9201-4, 9201-5, and 9204-4 Air flows given in this report should be with plus or minus 3 %. For 9201-2, values given are a reasonable guess: 1090
 - \checkmark 4. My best wild guess (wag) for the gas temperature leaving the furnace would be 200 degrees F.

To:

Ernie Choat

Fax #:

423-482-2605

Subject:

Questions on Ventilation Parame

Date:

August 8, 1996

Pages:

1, including this cover sheet.

Post-it [™] Fax Note 7671	Date 9-11-96 # of pages > 2
To Samer Sururi	From Susan Flack
Co./Dept. Mc L/H	co. INHES
Phone # 714-	Phone # 303-449-847/
Fax# 714-156-8460	Fax #

COMMENTS:

Ernie-

From our meeting with the air dispersion modelers, we have the following questions:

release
1. We need a velocity, or the size of the area of which (i.e., fan diameter) for Buildings 9201-5 and 9201-2 (Alpha 5 and Alpha 2) for the model. A guesstimate would be fine.

- 2. In your report for 9201-5 we cannot get 2% for 539,200 / 2,357,755. Please explain.
- 3. What would you estimate the error to be on the cfm flow rates (i.e., \pm we're thinking of an estimate based on professional judgement, not a quantitative error analysis.
- 4. What would you guess as a temperature for the air coming out of the mercury recovery furnace in 81-10?

If you want to just type up something and fax it to my house I'll be there this evening (Thursday). Thanks!

Susan

From the desk of...

Susan Flack Sr. Associate MHES- ChemRisk 2870 Kalmia Ave., Suite 308 Boulder, CO 80301-5915

> 303-449-8471 Fax: 303-939-8318

-	CALL
	Wiley - exhaust velocity?
cht pk	Jug/typical Loads (165 stm/hr) 2. flow notes > 1983? 2. flow notes > 1983? 1. — of the Hatt
•	20g/typical When burned cool vs. gas
8-21	2. flow notes >1983? Hypertent of ool?
	P. — of the HgTF not says,"
	2-19
revue text	ten Send ju personnement pretting for Nicolas for unc. estimate.
Send Somer	
	North Storm 9201-4
	100° 9304-4
2. 1	vised s'sheet 9201-2
	8)-10 rea
	old Hg wonehouse 9720-26
	old Hig wonebouse 9720-26 under Bldg. old flookemptying sies 750 9103
	serzp yard
	9202
	9733-1
	9733=2
CA	U EEC
	1. Q's from mtg. 2. 9201-4 vertilistion cut in half note.
	± 3%, 9201-2±%

61.	height
Bang	height nelepse
emissi	milesse)
To fond	
OI ON	velocities ?
	CARROLL STAND
a	
	539 1200
	539,200 72,357,755 72%
	A-4
Sue	O.K.
-	org. Stw
Tout	209,300
The Market	
Silvery	
voung report	B-4
	^ ~
	diemeter or velocity?
	dieneter or velocity.
*	81-10
	1 3 51-10
	O.K. (Temp?)
	Sterm

Q.C.

To: Susan M. Flack

ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Doublett, CO 0000

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 8/19/96

Pages including this cover page -- 2

Mossago:

This is to transmit revision to table 3, Building 9201-4 report.

Except for the correction of two errors, I have not changed ventilation rates. As shown, the 1st and 4th quarter rates are 52.7% of the "Summer" rate – which is as designed.

Are you thinking that the note on page 111 of Wilcox report means that the building was operated at ½ of the "winter" rate? That would be approximately ¼ of the "Summer" design rate.

I interrupted the note to mean that operation was in accordance with the design. If you disagree, I will divided by two and recalculate.



The following information represents revised estimates of air losses by quarter in Building 9201-4.

Comment	<u>Yr</u>	Qtr.	Hg building avg. (mg/m ³)	Estimate of Hg exhausted (1b)
Operation begins	55	2	.10	858
		3	.25	2,144
		4	.25	2,144
				-,-,-
New ventilation system complete*	56	1	.12	2,059
		2	.05	858
		2 3	.05	858
		4	.04	686
	57	1	.04	686
		2	.03	515
		3	.03	515
		4	.02	343
•				
	58	1 2 3	.02	343
•		2	.03	515
			.04	686
		4	.02	343
Exhaust makes out to helf dumina	1 50		00	050
Exhaust rates cut in half during first and fourth quarters	59	1 2 3 4	.03	258
first and fourth quarters		2	.03	515
			.03 .02	515
•		4	•02	172
	60	1	.02	172
	00	2	.03	515
,		2 3	.03	515
		4	.02	172
		•	•••	172
19	961	1	.02	172
		2	.02	343
		2 3	.02	172
		4	.02	343
				3 .5
19	962	1	.02	172
			.02	343
		2 3	.02	343
Operation ends		4	.02	172
TOTAL				18,447

^{*}It is estimated that the ventilation system work in Building 9201-4 lagged a quarter behind that of Building 9201-5.

SECRET

Sheet1

L L							•		Wilcox
Year		Exhaust		Conc.		Efflue	nt		Repor
	Qtr.	Cfm	m³/day	mg/m ³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qt
1955	1	1308545	53363512	0.20	10672702	10672 7	23.53	2118	1716
1300	2	1308545	53363512	0.15	8004527	8004.5	17.65	1588	1287
1	3	1308545	53363512	0.31	16542689	16542.7	36.47	3282	2573
ŀ	4	1308545	53363512	0.21	11206338	11206.3	24.71	2223	3603
1	-	10005-10	00000012			Annual	Totals	9212	9179
1956	1	1684410	68691587	0.12	8242990	8243.0	18.17	1636	1888
1000	2	2357755	96151135	0.10	9615114	9615.1	21.20	1908	1716
1	3	2357755	98151135	0.09	8653602	8653.6	19.08	1717	1544
-	4	1684410	68691587	0.06	4121495	4121.5	9.09	818	1029
· ·		1007710	00001007	0.00	1121100	Annual	Totals	6078	6177
	ï	1684410	68691587	0.04	2747663	2747.7	6.06	545	686
1957	2	2357755	96151135	0.04	3846045	3846.0	8.48	763	686
	3	2357755	96151135	0.03	2884534	2884.5	6.36	572	515
	4	1684410	68691587	0.02	1373832	1373.8	3.03	273	343
-		1004410	00001001	0.02	10.0002	Annual	Totals	2153	2230
1958	1	1684410	68691587	0.02	1373832	1373.8	3 03	273	343
	2	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	3	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	4	1684410	68691587	0.03	2060748	2060.7	4.54	409	343
	-	1007710	00007007	5.00		Annual	Totals	1445	1372
1959	1	1684410	68691587	0.04	2747663	2747.7	6.06	545	515
1203	2	471551	19230227	0.05	961511.4	961.5	2.12	191	1
	3	471551	19230227	0.04	769209.1	1	1.70	153	1
	4	336882	13738317	0.03	412149.5		0.91	82	1 .
		000002	.0.000	1	1	Annual	Totals	970	
1960	1-1-	336882	13738317	0.03	343457.9	343.5	0.76	68	1
1000	2	471551	19230227	0.04	769209.1	769.2	1.70	153	1
	3	471551	19230227	0.05	961511.4	961.5	2.12	191	1
	4	336882	13738317	0.03	412149.5	412.1	0.91	82	1
· · •- •••						Annual	Totals	493	-
							<u> </u>	00000	1
						Total for a	all years	20896	1947
		ļ.	ĺ	1				Y	ļ
Notes		 	.					20351	
1. Ass	sumes '	Winter" ventil	ation rates fo	r 1st & 4tl	n quarter.				
2. A s s	sumes "	'Summer'' ven	tilation rates	for 2nd &	3rd quarter				
3. Hg	concer	ntrations taker	from "Wilcox	c" report,	pg 110, with	n minor corre	ctions by	Susan Fl	ack.
I. Wh	en prod	ess was shut	down, ventile	ation was	reduced to	minimum as	dictated i	Dy onine mate	
		ion fount It in	actimated the	ar rna etai	マペカン ソムわけごろ	マロロロ いっそ ソロリ	/a DI IDP (I	usian faté	•
con	icentral	tion level. It is	esumated in	7r (1 10.9)(1)	idby, verible	MON WOS LO	o or the d	cagniaic	
con	icentral	uon level. It is	esumated in	3L (11 0 . 3\A)	idby, veridia	MOI WES EO	o or are d	caigii iaic	

Page 1

		Calculation	on for Hg Exh	austed to	Atmospher	e from Buildi	ng 9201-	5	
								-	Wilcox
Year		Exhaust		Conc.		Effluent			Report
1 Cai	Qtr.		m³/day	mg/m ³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr
1955		Cfm m³/day 1308545 5336351		0.20	10672702	10672.7	23.53	2118	1716
1900	2	1308545	53363512		8004527	8004.5	17.65	1588	1287
	3	1308545	53363512			16542.7	36.47	3282	2573
	4	1308545	53363512	0.31	16542689 11206338	11206.3	24.71	2223	3603
	- 4 -	1300040	00000012	0.21	11200330	Annual	Totals	9212	9179
						Aiiliuai	Totals	9212	3173
1956	1	1684410	68691587	0.12	8242990	8243.0	18.17	1636	1888
	2	2357755	96151135	0.10	9615114	9615.1	21.20	1908	1716
	3	2357755			8653.6	19.08	1717	1544	
	4	1684410	68691587	0.06	4121495	4121.5	9.09	818	1029
						Annual	Totals	6078	6177
1957	1	1684410	68691587	0.04	2747663	2747.7	6.06	545	686
1001	2	2357755	96151135	0.04	3846045	3846.0	8.48	763	686
	3	2357755	96151135	0.03	2884534	2884.5	6.36	572	515
	4	1684410	68691587	0.02	1373832	1373.8	3.03	273	343
		1007710	00001007	0.02		Annual	Totals	2153	2230
1958	1	1684410	68691587	0.02	1373832	1373.8	3.03	273	343
	2	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	3	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	4	1684410	68691587	0.03	2060748	2060.7	4.54	409	343
						Annual	Totals	1445	1372
1959	1	1684410	68691587	0.04	2747663 2747.7 6.06 54				515
	2	471551	19230227	0.05	961511.4	961.5	2.12	191	
	3	471551	19230227	0.04	769209.1	769.2	1.70	153	
	4	336882	13738317	0.03	412149.5	412.1	0.91	82	
						Annual	Totals	970	
1960	1	336882	13738317	0.03	343457.9	343.5	0.76	68	
	2	471551	19230227	0.04	769209.1		1.70	153	
	3	471551	19230227	0.05	961511.4		2.12	191	
	4	336882	13738317	0.03	412149.5		0.91	82	
						Annuai	Totals	493	
	 					Total for a	l ali vears	20896	19473
							,		
	 	 		 	<u></u>				<u> </u>

Notes:

- 1. Assumes "Winter" ventilation rates for 1st & 4th quarter.
- 2. Assumes "Summer" ventilation rates for 2nd & 3rd quarter.
- 3. Hg concentrations taken from "Wilcox" report, pg 110, with minor corrections by Susan Flack.
- 4. When process was shut down, ventilation was reduced to minimum as dictated by concentration level. It is estimated that the standby ventilation was 20% of the design rate.

(Refers to pp. 107-111 in Y/EX-21/del	Nev.
---------------------------------------	------

	·/		4							*	
Year/	A5 air conc	Žii	ttle air	Little lbs	days in 1/4	A5 Lbs		A5 Yr Total	A4 air conc	A4 Lbs	A4 Yr Total
		7									
1955	0.20		0.12	11.25	91.5	1716		9264	· sed	0	7463
1	0.15		0.12	11.25	91.5	1287			0.13		
	0.31		0.12	11.25	91.5	2659	*		0.26	2230 *	
	0.21		0.12	22.5	91.5	3603			0.26 0.24 0.12		
1956	0.12		0.12	22.5	91.5	2059	*	6348	0.12	2059	4461
	0.10	П	0.12	22.5	91.5	1716			0.05	858	
	0.09		0.12	22,5	91.5	1544			0.05	858	
	0.06		0.12	22.5	91.5	1029			0.04	686	
1957	0.04		0.12	22.5	91.5	686		2230	0.04	686	2059
	0.04	Г	0.12	22.5	91.5	686			0.03	515	
	0.03		0.12	22.5	91.5				0.03	515	
	0.02		0.12	22.5	91.5	343	Γ		0.02	343	
1958	0.02		0.12	22.5	91.5	343		1544	0.02	343	1887
	0.02		0.12	22.5	91.5	343	Г		0.03	515	
	0.02		0.12	22.5	91.5				0.04	686	
	0.03		0.12	22.5	91.5	515	*		0.02	343	
1959			0.12	22.5	91.5	686	*	2745	0.03	515	1887
	0.05		0.12	22.5	91.5	858			0.03	515	
	0.04		0.12	22.5	91.5		*		0.03	515	
	0.03		0.12	22.5			*		0.02		
1960	0.03	\Box	0.12	22.5	91.5	429	*	2488	0.02	343	1716
	0.04		0.12	22.5	91.5	686	*		0.03	515	
	0.05	1	0.12	22.5	91.5	858	*		0.03	515	
	0.03	₩_	0.12	22.5	91.5	515	*		0.02	343	
1961		/-	0.12	22.5	91.5	0	П		0.02	343	1373
			0.12	22.5	91.5	0			0.02	343	
i			0.12	22.5	91.5				0.02	343	
		Т	0.12	22.5					0.02		
1962		T	0.12	22.5					0.02	343	1373
		1	0.12	22.5	91.5	0			0.02	343	
	 		0.12	22.5	91.5	0	T		0.02		
,			0.12	22.5	91.5	0			0.02	343	
	/	Π									TOTAL
	1	Π				24619		24619		22217	22217
	1/	1				19473				18447	
I	/	Τ				-21%				17%	
7		1				-26				-20	
		1						46837			
/		Т							Y/EX-21		
17		Т					Γ	-19%	error		

* EEC cfm results frot included in these lbs. numbers.

(1) Could you revise Table 3 in 9201-4 report and fax/mail to me?

(2) Could you make a table like Table 3 in 9201-4 report (attached)

for 9201-5 showing lbs./quarter in effluent?

Hy

Qaairadd.xls (S)



				1						
Year		Little air	Little lbs	days in 1/4	A5 Lbs		A5 Yr Total		A4 Lbs	A4 Yr Total
	YEXAI							YEX-21		
1955	0.20	0.12	11.25	91.5	1716		9264		0	7463
	0.15	0.12	11.25	91.5	1287			0.13	1115	
	. 30 0.31	0.12	11.25	91.5	2659			0.26	2230	
	0.21 کاپی	0.12	22.5	91.5	3603			0.24	4118(*	
1956	.[] 0.12	0.12	22.5	91.5	2059	0	6348	0.12	2059	4461
	0.10	0.12	22.5	91.5	1716			0.05	858	
	0.09	0.12	22,5	91.5	1544			0.05	858	
	0.06	0.12	22.5	91.5	1029			0.04	686	
1957	0.04	0.12	22.5	91.5	686		2230	0.04	686	2059
	0.04	0.12	22.5	91.5	686	Г		0.03	515	
	0.03	0.12	22.5	91.5	515			0.03	515	
	0.02	0.12	22.5	91.5	343			0.02	343	
1958	0.02	0.12	22.5	91.5	343		1544	0.02	343	1887
	0.02	0.12	22,5	91.5	343			0.03	515	
	0.02	0.12	22.5	91.5	343	<u>ر</u> -	n	0.04	686	
	0.03 ده	0.12	22.5	91.5	515	*	* 1	0.02	343	
1959	opende 30.04	0.12	22.5	91.5	686	1-17	2745	0.03	515	1887
42	C T 0.05	0.12	22.5	91.5	858	1	-	0.03	515	
	MM . 0.04		22.5	91.5	686			0.03	515	
	0.03	0.12	22.5	91.5	515	7		0.02	343	
1960	0.03	.075 0.12	22.5	91.5	429	7	1 2488	30.02	343	1716
	0.04	0.12	22.5	91.5	686	1	o l	-0230.03	515	
	0.05	0.12	22.5	91.5	858			0.03	515	
	V 0.03	0.12	22.5	91.5	515	驭	*	0.02	343	
1961		0.12	22.5	/91.5	7 0	7-6		0.02	343	1373
		/ 0.12	22.5	91.5	/ 0			0.02	343	
		0.12	22.5	91.5	0	П		0.02	343	
		0.12	22.5	0 91.5	10	17		0.02	343	
1962		0.12	22.5	91.5	0			0.02	343	1373
		0.12	22.5	91.5	0			0.02	343	
		\ 0.12	22.5	91.5	(0			0.02	343	
		\ 0.12	22.5	91.5	V			0.02	343	
										TOTAL
				TOTALS Y/EX-21	24619		24619	TOTALS	22217	22217
				Y/EX-21	19473	V		Y/EX-21	18447	
					-26%				-20%	
								1	 	T
Ï								conc changes		
							37920	Y/EX-21		
							-24%	error difference		
Notes						\blacksquare				7
* = aiı	conc(revised)f	rom Y/EX-2	1/del rev		/ 20351	10		vent and conc	82028	83262
					(-4%	1	21%	changes	-79%	1/42%

Movement between the state of

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471 Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062 Fax:423 482 2605

Date: 9/7/96 Pages including this cover page --3

This is to transmit:

1. Revision 2 of Table 3 of building 9201-4 report.

2. Revision 1 to "Calculation for Hg Exhausted to Atmosphere from building 9201-5."

3. Provide roof elevations --- building 9204-4 --- figure 1 of Report.

Elevation of the lowest roof is 1028' 6"

Elevation of 2nd lowest roor is 1048' 9 7/8"

✓ • High Roof is 1061' 3 ¾"

I should revise this drawing to show stacks and these elevations but have already blown all of my hours. In fact, I have now 39 hours past the limit – 20 hours in July and 19 hours in August.

To: Susan M. Flack

ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 9/7/96

Pages including this cover page -- 3

This is to transmit:

1. Revision 2 of Table 3 of building 9201-4 report.

- 2. Revision 1 to "Calculation for Hg Exhausted to Atmosphere from building 9201-5."
- 3. Provide roof elevations --- building 9204-4 --- figure 1 of Report.
 - Elevation of the lowest roof is 1028' 6"
 - Elevation of 2nd lowest roor is 1048' 9 7/8"
 - High Roof is 1061' 3 %"

I should revise this drawing to show stacks and these elevations but have already blown all of my hours. In fact, I have now 39 hours past the limit - 20 hours in July and 19 hours in August.

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 9/7/96

Pages including this cover page --3

This is to transmit:

1. Revised Table 3 of building 9201-4 report.

2. Calculation for Hg Exhausted to Atmosphere from building 9201-5.

9

Table 3

Calculation of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

					_	F.0.			Wilcox	
Year		Exhaust	Exhaust	Conc.	ļ.,,	Efflue		4 ho/ote	Report	
1955	Qtr.	Cfm	m³/day	mg/m³	mg/day	grams/day	ibs/day	1bs/qtr	1bs/qtr	
	2	2050740	83630818	0.1	8363082	8363.1	18.44	1659	858	
	3	2050740	83630818	0.25	2.1E+07	20907.7	46.09	4148	2144	
	4	1446429	58986532	0.25	1.5E+07	14746.6	32.51	2926	2144	
							Totals	8733	5146	
1956	1	1446429	58986532	0.12	7078384		15.60	1404	2059	
	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858	
	3	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858	
	4	2477380	101029538	0.04	4041182	4041.2	8.91	802	686	
	L						Totals	6012	4461	
1957	1 1	2477380	101029538	0.04	4041182		8.91	802	686	
	2	4703040	191793734	0.03	5753812		12.68	1142	515	
	3	4703040	191793734	0.03	5753812		12.68	1142	515	
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343	
	.1		<u> </u>				Totals	3487	2059	
1958	Τ 1	2477380	101029538	0.02	2020591	2020.6	4.45	401	343	
1000	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515	
	3	4703040	191793734	0 04	7671749	7671.7	16.91	1522	686	
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343	Į
				-			Totals	3466	1887	!
1959	1 1	2477380	101029538	0.03	3030886	3030.9	6.68	601	258	
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515	
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515	
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172	
							Totals	3286	1460	İ
1960	1	2477380	58986532	0.02	117973		2.60	234	172	
	2	4703040	191793734	0.03	5753812		12.68	1142	515	1
	3	4703040	191793734	0.03	575381	2 5753.8	12.68	1142	515	1
	4	2477380	101029538	0.02	202059	1 2020.6	4.45	401	172	1
						· · · · · · · · · · · · · · · · · · ·	Totals	2919	1374]
1961	1 1	2477380	101029538	0.02			4.45	401	172]
	2	4703040	191793734	0.02			8.46	761	343	1
	3	4703040	191793734	0.02			8.46	761	172	4
	4	2477380	101029538	0.02	202059	1 2020.6	4.45	401	343	4
٠	1	1	<u> </u>				Totals	2324	1030	16
1962	21 1	2477380	101029538	0.02	202059			(401)		401-234
	2	4703040	191793734	0.02	383587			761	343	167
-	3	4703040	191793734	0.02				761	343	4
	4	2477380	10102953	0.02	202059	2020.6		401	172	-{
							Totals	2324	1030	1
					Totals	for all	years	32382	18447	1
								28	4	_
							7	32-50	う	
								305		
							7	レン		

TOTAL P.02

So you can see that cfms E. Choat used.

- O In Table 3, (9201-4), the numbers for sin conc. we not changed, but it appears that the cale's changed compared to the previous version you sert me. (see both Table 3"old" and Table 3" new" attacked).
- D In Skeet I and Table 3"rew", my totals for sel years do not agree with your numbers.

 Help!

Post-it [™] Fax Note 7671	Date 9-10-96 # of pages > 4
To Fring Choat	From Susan Flack
Co./Dept.	Co.
Phone #	Phone # 303-449-8471
Fax# 423-482-2605	Fax #

Have not heard back yet (9-11-96 4 pm).

Table 3

Calculation of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

	Wilcox		***							
	Report			Efflue		Conc.		Exhaust		Year
lbs/yr	1bs/qtr	1bs/qtr	lbs/day	grams/day	mg/day	mg/m³	m³/day	Cfm	Qtr.	1955
	858	1659	18.44	8363.1	8363082	01.13	83630818	2050740	2	-
_	2144	4148	46.09	20907.7	2.1E+07	925.2	83630818	2050740	3	
8733	2144	2926	32.51	14746.6	1.5E+07	025.2	58986532	1446429	4	
	2059	1404	15.60	7078.4	7078384	0.12	58986532	1446429	1	1956
	858	1903	21.14	9589.7	9589687	0.05	191793734	4703040	2	
	858	1903	21.14	9589.7	9589687	0.05	191793734	4703040	3	
6012	686	802	8.91	4041.2	4041182	0.04	101029538	2477380	4	
	686	802	8.91	4041.2	4041182	0.04	101029538	2477380	1	1957
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	2	
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	3	
3487	343	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	
	343	401	4.45	2020.6	2020591	0.02	101029538	2477380	1	1958
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	2	
	686	1522	16.91	7671.7	7671749	0.04	191793734	4703040	3	
3466	343	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	
	258	601	6.68	3030.9	3030886	0.03	101029538	2477380	1	1959
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	2	
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	3	
3286	172	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	
	172	234	2.60	1179.7	1179731	0.02	58986532	1446429	1	1960
	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	2	
000	515	1142	12.68	5753.8	5753812	0.03	191793734	4703040	3	
2919	172	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	
	172	401	4.45	2020.6	2020591	0.02	101029538	2477380	1	1961
	343	761	8.46	3835.9	3835875	0.02	191793734	4703040	2	
	172	761	8.46	3835.9	3835875	0.02	191793734	4703040	3	
2324	343	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	1962
]	172	234	2.60	1179.7	1179731	0.02	58986532	1446429	1	
]	343	761	8.46	3835.9	3835875	0.02	191793734	4703040	2	
]	343	761	8.46	3835.9	3835875	0.02	191793734	4703040	3	-
2157	172	401	4.45	2020.6	2020591	0.02	101029538	2477380	4	
]	18447	32382	Totals							

2324-2157

See to

y

Table 3 Calculation of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

			 			F40			Wilcox
Year		Exhaust	Exhaust	Conc.		Efflue		41	Report
1955	Qtr.	Cfm	m³/day	mg/m ³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr
	2	2050740	83630818	8.1.13		10872.0	23.97	2157	858
	3	2050740	83630818		2174401	21744.0	47.94	4314	2144
	4	1446429	58986532	0.25	1415677	14156.8	31.21	2809	2144
							Totals	9280	5146
1956	1	1446429	58986532	0.12	7078384	7078.4	15.60	1404	2059
	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	3	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	4	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
المود د		1					Totals	6012	4461
1957	1	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
							Totals	3487	2059
1958	1	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.04	7671749	7671.7	16.91	1522	686
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
l	L	<u> </u>	<u> </u>				Totals	3466	1887
1959	1	2477380	101029538	0.03	3030886	3030.9	6.68	601	258
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
		<u> </u>					Totals	3286	1460
1960	1	2477380	58986532	0.02	1179731		2.60	234	172
	2	4703040	191793734	0.03	5753812		12.68	1142	515
	3	4703040	191793734	0.03	5753812		12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
L							Totals	(2919)	1374
1961	1	2477380	101029538	0.02	2020591		4.45	401	172
	2	4703040	191793734	0 02	3835875		8.46	761	343
	3	4703040	191793734	0.02	3835875		8.46	761	172
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
L	<u></u>						Totals	2324	1030
1962	1	2477380	101029538	0.02	2020591		4.45	401	172
	2	4703040	191793734	0.02	383587		8.46	761	343
	3	4703040	191793734	- I	383587		8.46	761	343
	4	2477380	101029538	0.02	202059:	2020.6	4.45	401	172
							Totals	2324	1030

/33098

for all

Totals

Table 3
Calculation of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

									Wilcox
Year		Exhaust	Exhaust	Conc.		Efflue	ent		Report
1955	Qtr.	Cfm	m³/day	mg/m³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr
	2	2050740	83630818	0.1	1087201	10872.0	23.97	2157	858
	3	2050740	83630818	0.25	2174401	21744.0	47.94	4314	2144
	4	1446429	58986532	0.25	1415677	14156.8	31.21	2809	2144
<u>1</u>							Totals	9280	5146
1956	1	1446429	58986532	0.12	7078384	7078.4	15.60	1404	2059
.555	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	3	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	4	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
<u></u>	L	<u> </u>					Totals	6012	4461
1957	1 1	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
				-	-		Totals	3487	2059
1958	1	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
1,000	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
 	3	4703040	191793734	0.04	7671749	7671.7	16.91	1522	686
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
		.'					Totals	3466	1887
1959	1	2477380	101029538	0.03	3030886	L	6.68	601	258
	2	4703040	191793734	0.03	5753812		12.68	1142	515
	3	4703040	191793734	0.03	5753812		12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
		<u> </u>					Totals	3286	1460
1960	1 1	2477380	58986532	0.02	1179731	1179.7	2.60	234	172
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812		12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
		<u> </u>		_			Totals	2919	1374
1961	1	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
	2	4703040	191793734	0.02	3835875	3835.9	8.46	761	343
	3	4703040	191793734	0.02	3835875		8.46	761	172
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
							Totals	2324	1030
1962	1 1	2477380	101029538	0.02	2020591	·	4.45	401	172
	2	4703040	191793734	0.02	3835875		8.46	761	343
	3	4703040	191793734	0.02	3835875		8.46	761	343
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
<u> </u>							Totals	2324	1030
					Totals	for all	years	32382	18447

Table 3

	Table 3 Calculations of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-									
hatostel.	de	Calc	ulations of Pou	ınds of Mercu	ry per Qı	om 9201-4	ļ.			
هٔ ادبر	XI>	Calo	PA	inds of Mercu	•		₁₁ 53.	59 god	_	Wilcox
1091,			No.1	1153 / A						Report
1/1.	Year		Exhaust	350	Conc.		Effluer		4 ho/gir	1bs/qtr
	' ·	Qtr.	Cfm	m³/day	mg/m ³ ,	mg/day	grams/day		1bs/qtr	858
	1955	2	2050740	83630818	0.13	10872006	10872.0	23.97	2157	2144
	1.000	3	2050740	83630818	0.26	21744013	21744.0	47.94	4314	2144
		4	1446429	58986532	0.24	14156768	14156.8	31.21	2809	5146
			1	/					9280	
	4050		1446429	58986532	0.12	7078384	7078.4	15.60	1404	2059
	1956	1	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	1	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	1	3	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
		4	2411300	10102000					6012	4461
				101000500	0.04	4041182	4041.2	8.91	802	686
	1957	1_1_	2477380	101029538	0.04	5753812	5753.8	12.68	1142	515
		2	4703040	191793734	0.03	5753812		12.68	1142	515
		3	4703040	191793734	0.03	2020591	2020.6	4.45	401	343
		4	2477380	101029538	0.02	2020001	2020.0		3486	2059
	-	L					0000.6	4.45	401	343
	1958	1	2477380	101029538	0.02	2020591		12.68	1142	515
		2	4703040	191793734	0.03	5753812		16.91	1522	686
	l l	3	4703040	191793734	0.04	7671749		4.45	401	343
		4	2477380	101029538	0.02	2020591	2020.6	4.45	3466	1887
	ł									
	1959	1	2477380	101029538	0.03	3030886		6.68	601	258
, - · · · ·	1909	2	4703040	191793734	0.03	5753812		12.68	1142	515
	ì	3	4703040	191793734	0.03	5753812		12.68	1142	515 172
		4	2477380	101029538	0.02	2020591	2020.6	4.45	401	1460
		├ ──	-						3286	
	100	+-	2477380	101029538	/0.02	202059	1 2020.6	4.45	401	, 172
•	1960		4703040	191793734		D4 5753812		12.68	1142	, 515
	1	3	4703040	191793734				12.68	1142	515
,	l.		2477380	101029538		-/1		4.45	401	172
	1	4		10102000	1				3085	1374
			<u> </u>	404000505	0.02	202059	1 2020.6	4.45	401	172
	196		2477380	101029538				8.46	761	343
		2	4703040	191793734	4			8.46	761	172
,		3	4703040	191793734				4.45	401	343
		4	2477380	101029538	0.02		-		2324	1030
					+==	000050	1 2020.6	4.45	401	172
	196	2 1	2477380	10102953				8.46	761	343
	<u> </u>	2							761	343
		3							401	172
	Ì	4	2477380	10102953	8 0.02	2 202059	2020.0		2324	1030
								7-1-1-		1
	N	otes:				o Ath auarte	~	Totals	33262	10447

Notes:

- 1. Assumes "Winter" ventilation rates for 1st & 4th quarter.
- 2. Assumes "Summer" ventilation rates for 2nd & 4th quarter.
- 3. Hg concentrations taken from "Wilcox" report, page 111.

Calculations of Pounds of Mercury per Quarter Exhausted to Atmosphere from 9201-4

Year		Exhaust		Conc.	T	Efflue	ent		Wilcox Report
	Qtr.	Cfm	m ³ /day	mg/m³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr
1955	2	2050740	83630818	0.13	10872006	10872.0	23.97	2157	858
	3	2050740	83630818	0.26	21744013	21744.0	47.94	4314	2144
	4	1446429	58986532	0.24	14156768	14156.8	31.21	2809	2144
								9280	5146
1956	1	1446429	58986532	0.12	7078384	7078.4	15.60	1404	2059
	2	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	3	4703040	191793734	0.05	9589687	9589.7	21.14	1903	858
	4	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
								6012	4461
1957	1	2477380	101029538	0.04	4041182	4041.2	8.91	802	686
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.03	2020591	2020.6	4.45	401	343
	-	2.17.000	10.1025000	0.02	2020001	2020.0	7.70	3486	2059
958	4	2477380	101020520	0.02	2020504	2020.6	4 45		
900	2		101029538	0.02	2020591	2020.6	4.45	401	343
	3	4703040 4703040	191793734 191793734	0.03	5753812 7671749	5753.8 7671.7	12.68	1142	515
ĺ	4			0.04			16.91	1522	686
i	4	2477380	101029538	0.02	2020591	2020.6	4.45	401 3466	343 1887
1959	1	2477380	101029538	0.03	3030886	3030.9	6.68	601	258
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020 6	4.45	401 3286	172 1460
1960	1	2477380	101029538	0.02	2020591	2020 6	4.45	401	172
	2	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	3	4703040	191793734	0.03	5753812	5753.8	12.68	1142	515
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
								3085	1374
1961	1	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
	2	4703040	191793734	0.02	3835875	3835.9	8.46	761	343
	3	4703040	191793734	0.02	3835875	3835.9	8.46	761	172
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	343
			ļ					2324	1030
1982	1	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
	2	4703040	191793734	0.02	3835875	3835.9	8.46	761	343
	3	4703040	191793734	0.02	3835875	3835.9	8.46	761	343
	4	2477380	101029538	0.02	2020591	2020.6	4.45	401	172
NO. TA-								2324	1030
Note			tilation rates f	4_4 & 4	41. a		Totals	33262	18447

[1. Assumes "Winter" ventilation rates for 1st & 4th quarter.

2. Assumes "Summer" ventilation rates for 2nd & 4th quarter.

3. Hg concentrations taken from "Wilcox" report, page 111.

9

		Calculation	on for Hg Exh	austed to	Atmospher	e from Buildi	ng 9201-t	5	
]					•		,		
Year		Exhaust		Cono	· 	FERM			Wilcox
. Tear	O 1-		3,,,	Conc.		Efflue			Report
4055	Qtr.	Cfm	m³/day	mg/m ³	mg/day	grams/day	lbs/day	1bs/qtr	1bs/qtr
1955	1	1308545	53363512	0.20	10672702	10672.7	23.53	2118	1716
	2	1308545	53363512	0.15	8004527	8004.5	17.65	1588	1287
		1308545	53363512	0.31	16542689	16542.7	36.47	3282	2573
!	4	1308545	53363512	0.21	11206338	11206.3	24.71	2223	3603
						Annual	Totals	9212	9179
1956	1	1684410	68691587	0.12	8242990	8243.0	18.17	1636	1888
	2	2357755	96151135	0 10	9615114	9615.1	21.20	1908	1716
Ì	3	2357755	96151135	0.09	8653602	8653.6	19.08	1717	1544
	4	1684410	68691587	0.06	4121495	4121.5	9.09	818	1029
						Annuai	Totals	6078	6177
1957	1	1684410	68691587	0.04	2747663	2747.7	6.06	545	686
	2	2357755	96151135	0.04	3846045	3846.0	8.48	763	686
	3	2357755	96151135	0.03	2884534	2884.5	6.36	572	515
!	4	1684410	68691587	0.02	1373832	1373.8	3.03	273	343
				·		Annual	Totals	2153	2230
1958	1	1684410	68691587	0.02	1373832	1373.8	3.03	273	343
'	2	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	3	2357755	96151135	0.02	1923023	1923.0	4.24	382	343
	. 4	1684410	68691587	0.03	2060748	2060.7	4.54	409	343
						Annual	Totals	1445	1372
1959	1	1684410	68691587	0.04	2747663	2747.7	6.06	545	515
	2	471551	19230227	0.05	961511.4	961.5	2.12	191	
	2 3	471551	19230227	0.04	769209.1	769.2	1.70	153	
	4	336882	13738317	0.03	412149.5	412.1	0.91	82	
. .						Annual	Totals	970	-
1960	1	336882	13738317	0.03	343457.9	343.5	0.76	68	
	2	471551	19230227	0.04	769209.1	769.2	1.70	153	
1	3	471551	19230227	0.05	961511.4	961.5	2.12	191	
	4	336882	13738317	0.03	412149.5	412.1	0.91	82	
	<u> </u>					Annual	Totals	493	ļ.
	ļ				<u> </u>	Total for a	llugge	20351	19473
}		<u> </u>		<u> </u>	 	i otal for a	in years	20351	13413
			1	i		!	1 1 	<u>L</u> .	}

Notes:

- 1. Assumes "Winter" ventilation rates for 1st & 4th quarter.
- 2. Assumes "Summer" ventilation rates for 2nd & 3rd quarter.
- 3. Hg concentrations taken from "Wilcox" report, pg 110, with minor corrections by Susan Flack.
- 4. When process was shut down, ventilation was reduced to minimum as dictated by concentration level. It is estimated that the standby ventilation was 20% of the design rate

To: Susan M. Flack

ChemRisk

2870 Kalmia Avenue, Suite 308

Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 11/1/96

Pages including this cover page -- 1

Message:

Can handle files on floppy. Call me when you get here.



FAX

To:

Ernie Choat

Fax #:

423-482-2605

Subject:

Y-12 Ventilation Project

Date:

October 31, 1996

Pages:

1, including this cover sheet.

COMMENTS:

Hi Ernie!

I wanted to ask you two questions. (1) Could you give me your Word document(s) and Excel files on a diskette? I have to convert them to our software and format for an appendix for our report. I need the Excel files for the QA notebook where we have to provide documentation of all calculations. (2) I was able to calculate quarterly average air concentrations of mercury for Alpha-2 and Beta-4 for April 1955 through December 1959. Since you are over on hours, I was wondering if I could make a couple of Excel tables like you did for A-5 and A-4 to calculate the pounds of mercury emitted from the buildings, and then you could look them over and bless them.

I'll be in Oak Ridge at the Comfort Inn all next week.

Susan Flack

From the desk of...

Susan Flack Senior Associate Health Scientist MHES 2870 Kalmia Ave. Suite 308 Boulder, CO 80301-5915

> 303-449-8471 Fax: 303-939-8318



FAX

To:

Ernie Choat

Fax #:

423-483-6062

Subject:

Alpha 2 Building Air

Date:

February 5, 1997

Pages:

7, including this cover sheet.

COMMENTS:

Hi Ernie!

I found this memo in my piles of paper from Steve Wiley and I don't think I showed it to you. Would you take a quick look at it and see if it changes anything you've assumed about Alpha-2 building ventilation? Only call me back if it does.

Thanks!

Guean

From the desk of...

Susan Flack Senior Associate Health Scientist MHES 2870 Kalmia Ave. Suite 308 Boulder, CO 80301-5915

> 303-449-8471 Fax: 303-939-8318

To: Susan M. Flack

ChemRisk 2870 Kalmia Avenue, Suite 308 Boulder, CO 80301

Phone: 303 449 8471

Fax:303 939 8318

From: E. E. Choat (EEC)

Company: Environmental Engineering Consultants (EEC)

Phone: 615 483 6062

Fax:423 482 2605

Date: 1/20/97

Pages including this cover page -- 2

This is to transmit:

1. Revised Table 1, page 5 of building 9201-5 report.

The numbers in Table 1 that you questioned still make no sense to me. Since I was unable to determine the source of these numbers from spread sheet calculations. I have gone back to the drawings to revise table 1.

You will observe that "Contaminated Exh from Building" is still unequal to "Fresh Air Supply". The difference results from 157800 cfm of "uncontaminated" air that is exhausted from the Maintenance area.

Then: 1,526,610 + 157,800 = 1,644,410 which equals fresh air supply



To:

Ernie Choat

Fax #:

423-482-2605

Subject:

Change in A-5 ventilation

Date:

January 22, 1997

Pages:

5, including this cover sheet.

COMMENTS:

Hi! Thanks for checking the ventilation drawings for A-5. I got your table and revised the A-5 winter ventilation rate in 3 places: (1) the Sheet 1 calculation table of pounds released per quarter in the A-5 report; (2) a little summary table on p. 4 of the A-5 report; and (3) a little summary table on p. 8 of the A-4 report. It did not change anything in Table 4 of the A-5 report, which defines fan locations, winter air volumes, % of total exhaust volume, and exhaust point locations.

I'm sending you these revisions for your records- I don't expect you to recalculate any numbers. I also included a copy of my summary table for all air releases from all buildings FYI.

Thanks again!

Susan Flack

From the desk of...

Susan Flack Senior Associate Health Scientist MHES 2870 Kalmia Ave. Suite 308 Boulder, CO 80301-5915

> 303-449-8471 Fax: 303-939-8318

OFFICE

MEMO

To:

Samer Sururi (Irvine)

From:

Susan Flack (Alameda)

Subject:

Oak Ridge Task 2 Air Dispersion Modeling

Date:

January 23, 1997

I met with Ernie Choat last week in Oak Ridge. As a result of one of my questions, he made some changes to his winter ventilation volume for Building 9201-5 that changed his calculation of pounds of mercury emitted from A-5 per year. Therefore I had to change everything in the chain again. It didn't, however, change the winter volumes for the emissions sources from A-5. I am going to attempt to type a list of all the changes to the air dispersion modeling, including ones we already discussed in Alameda and a few more changes per Ernie. Note that the marked-up table I gave you a copy of in Alameda has been further changed (and I took back some of my suggested changes per your and Ernie's opinions), so don't rely on that. I have also attached (in email) the Excel file called 'airlbs.xls' for you to use as a source of the final estimates of pounds of mercury released from each facility for every applicable year. Hurrah!

1. For 9201-4 building, add emission sources to the roof for:

[591380 cfm (24%) for winter// 590240 cfm (13%) for summer] from 1st and 2nd floors- Ernie said this is a duct type source; assume 8 of them and the area for each one would be annual avg cfm/ 2200/ 8.

[428800 cfm (17%) for winter// 428880 (9%) for summer] from tray exhaust- Ernie said this is a centrifugal fan type source; assume 4 of them and the area for each one would be 107200/ 2200.

[104000 cfm (4%) for winter// 104000 cfm (2%) for summer] from roof exhausters- Ernie said this is a centrifugal fan type source; assume 4 of them and the area for each one would be 26000/2200.

References are Tables 4&5 (Building exhaust summaries for summer and winter) and Figure 3 (3rd floor plan) in Ernie's 9201-4 report.

2. Change elevations above ground level for S9201-41 thru -48, and S9201-51 thru -58, to 88', not 93'. Leave all of these fan diameters at 54" (Ernie said to pass along to you that all these fans had only one speed; to reduce flow they just had to turn some fans off.)

Ernie's Tables 4 and 5 should show the elevation above sea level for the 9201-4 roof sources to

Samir Sururi Page 2 January 23, 1997

be 1051' (roof level), not 1056. However, if they don't physically fit on the roof at 1051', the 4 roof exhausters and the 8 ducts from the 1st and 2nd floors could be placed on the lower roof at 1040' like they are in 9201-5 (see Figure 2 in Ernie's 9201-5 report). He doesn't have drawings that show these roof sources on 9201-4. Ernie followed a general rule of thumb for roof source elevations in all buildings except for the one case of the upper roof of 9201-4 (he said the elevation of the upper roof was 1051 + 5 = 1056). The general rule is to assume fan height above roof is 0 because we don't know the actual heights of any of these stacks/ducts and Ernie thinks it makes a difference of only a few feet anyway. (Note however that he put the wall fans in a space 8-9' down from the floor above.) So to be consistent, please change the roof elevations.

- Correct a math error in the S9201-55 thru -58; volume flow rate for each should be 3. 186000/4 = 46550 not 46200.
- Assume that the south and north wall louvers in 9201-5 above the east and west crane 4. bays (F9201-54, -56, -513, -515, -525, -527, -528, -530) are 40' wide x 15' high. It appears that you assumed two louvers were side by side on each wall above each crane bay; make the total width at each of the 4 locations 80' somehow.
- The elevation above ground level for S9201-59 thru -74 should be 67' not 72'. The 5. diameter of 9201-59 thru-62, and -67 thru -70, should be larger- assume 72" instead of 54".
- The elevation above ground level of F9204-41 thru -46 should be 65' (1061-6-990) 6. in the wall space that's halfway between the 1049' and 1061' levels) not 60.5'. The elevation above ground level of S9204-41 and -42 should be 71' (1061-990) not 76'. The drawing showing the basement grade and the first floor grade was misleading
- Ą. Add a building to the modeling, 9201-2.

I have attached a marked-up drawing and a handwritten table for this building. Ernie said again to divide the volume by the velocity to get the area, and therefore the diameter.

g. Correct two exhaust temperature errors.

S81-101exhaust temperature should be 200 F. S9401-11 (-12 see next item), -21, -31, and -32 exhaust temperatures should be 300 F.

Add a stack to the 9401-1 steam plant, and change the diameters of both of the two stacks.

I found photos and a drawing that show two stacks instead of one. (Add S9401-12 to S9401-11.) Make the diameter of S9401-11 = 6' instead of 12.5', and the diameter of S9401-12 = 8'. The rest

Samir Sururi Page 3 January 23, 1997

of the diameters stay the same.

The height of S81-101 should be 16' or 4.88 m, not 5.88 m. The height of S9401-31 and -32 should be 190', not 100'.



FAX

J N E E

To:

Samer Sururi

Fax #:

714-756-8460

Subject:

Task 2 Air Modeling

Date:

January 24, 1997

Pages:

8, including this cover sheet.

COMMENTS:

Too many already!

From the desk of...

Susan Flack Senior Associate Health Scientist MHES 2870 Kalmia Ave. Suite 308 Boulder, CO 80301-5915

> 303-449-8471 Fax: 303-939-8318

				_		-	\ \ \ \	2 6 C	さると	(28) /	\neg					•		**																	L'agnoration
は、マスペーサ	7	VOLUME FLOW RATE	\(\text{(cimit)} \)	✓ 35000							>	00092 >	00092 /	00092 /	00091 /	46550 -46200	i 1	46SSD 46200	46550 46200		1300				00009 >	₹ 00009 ✓		7 70200 17		→ 70200 H		V 143000 L1		V 143000 /J	Shoons Baloshard was hard to we have the constant of constant of the constan
4		TY	(md)	7000Z	2200	2200	220 D	2000	220 D	220D	220 D	面]			(Table)			\ 	22003		0 2200	2200	Ġ	ا م	1667 / Table 1667 /		2483/		2483		, 2248		2248	Saco, ctim from 124, 2nd floore 428, 800 from tray extrant 104, 000 from most extrantion
		DIAMETE R		4.51 54	547	54 2	541	54	547	547	547	54.	-54	-54	54	754	-54	, 54	₹ 24	12.5FT 6/	4.164/14	12.5FT	12.5FT 🟏		\ <u>8</u> 1	6.35 (81/		6 727		6' 72		4' 1081		4, 108	••
Ł.	SES	TEMPERATUR E	(u) (-1	308 243.15	1						>	88	(1991)	,					7	Troops	-1000	300	1,300°F	7,000:0	11293.151	1293.151	(900)	29515		293.15		293.15		21892	4-10cb
w/ 12/m	SOURCES	HEIĞH T		0 26 10	A O	0	1260 0	1280 0	186- 0	188° 0	0		0 93	0 -93	0 93	0 93	0 893	0 93	で お こ の	0 32,46/100	91- 1(88-6) 0	00/%-148/100	0 + 400	0 -4-4-00-190	33	0/23.167691		13.38 57	0	0 57	0	725 0	0	0 57/7	Page 1
	above sere	SOURCE BASE	ELEVALION	2296							->	, દાષ્							>		88.H)			57.9	990? (1061)	\									
		Y-UTM	(III)	3985468.79	3985484.94	3985501.08	3985517.23	3985416.30	3985432.45	3985448.60	3985464.74	3985336.40	3985352.55	3985368.69	746753.89 3985384.84	746697.08 3985283.91	3985300.06	3985316.21	3985332.35	3986023.46			3985306.16		3985191.05	3985204.88		3985393.65	3985394.81	3985395.96			3985400.16	3985403.90	
A X	Carl Standard	X-UTM		747019.55	747009.73	746999.91	746990.09	746933.27	746923.45	746913.63	746903.81	746783.36	746773.54	746763.71	746753.89	746697.08	746687.26	746677.44	746667.61	748020.91	747175.14	747083.59	746929.02	746962.56	746501.30	746524.04	746915.26	-			-	746936.94	746943.10	746949.25	
	- 35 -			187	186	185	184	183	182	181	180	E 179	E 178	C. 177	7.176	271	W 174	√ 173	V 171	146	✓ 135	/ 134	√ 133	J 132	8	7	124-	123 \$	127	\$ 171	-120-	\$ 611	4	117 \$	
_\		STACK I.D.		S9201-41	-	S9201-43	S9201-44	S9201-45	S9201-46	S9201-47	S9201-48	S9201-51		S9201 , 53	S9201-54			S9201-57	S9201-58		S81-101	S9401-21	S9401-31	(S) 401-32	S9204-41	S9204-42	-(F)201-41	F9201-431	F9201-42	F9201-432	F9201-43	F9201-44	F9201-45	F9201-46	
Xa.	Same trans	7		7-1-7-1-3-1-3-1-3-1-3-1-3-1-3-1-3-1-3-1-	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						> >	-		33	7	o a trive	CHINA STORY	S A CAR		たのまって		Const.	\$ 10 m	<i>\ \ \ \ \ \ \ \ \ \</i>	d	L E	() 1			×	***************************************				adalan

					HEIGH	HEIGH TEMPERATUR	DIAMETE		EXIT	NOTON	VOLUME FLOW
STACK I.D.		X-UTM	Y-UTM	SOURCE BASE	[戽	8	VE	VELOCITY	R/	RATE
		(m)	(m)	ELEVATION	(m)	(K)	(m)		(m/s)	၁)	(cfm)
					<u> </u>	(acol)					
F9201-47	116 5	746959.21	3985409.96	0		51.866	,9	725	2483		70200
F9201-433	4	746961.12	3985411.12	0							
F9201-48	114 <	746963.02	3985412.27	0	57,		, 9	72/	2483		70200
F9201-434	113 \$	746964.92	3985413.43	0	57	_		72/	2483		70200
F9201-49	112 5	746966.82	3985414.59	0	57			72/	. 2483		70200
F9201-410	S !!!	ı	747005.66 3985438.21	0	57		\$	72/	2483		70200
F9201-435	#	747007.56	3985439,37	0			,				
F9201-411	109	747009.46	3985440.52	0	22		e	72/	24831		70200
F9201-436	108 5	747011.36	3985441.68	0			2	72/	2483		70200
F9201-412	. 107 5	747013.26	3985442.84	0	57,		, "/	72/	2483		70200
F9201-413	5 901	747023.22	3985448.90	0.	57,		ā	108	2248		143000
F9201-414	\$	747029.38	3985452.64	0		4					
F9201-415	104 \$	747035.53	3985456.39	0	57	(2001)	Ġ,	108	2248		143000
F9201-416	103 €	747035.81	3985504.05	0	11.19 37		2.5	425	2339		22500
F9201-417	102 6	İΤ	747033.50 3985507.85	0	37,		_	42/	2339		22500
F9201-418	101	747031.19	3985511.65	0	37,			42/	2339		22500
F9201-419	100	747028.87	3985515.45	0	37		-3	427	62339	受	22500
F9201-420	<i>8</i> 9	747026.21	3985519.83	0 .	5.18 17	7,080	15	60 7	2292		45000
F9201-421	% %	747023.90	3985523.64	0	17	7	4	8	<u>ex</u> 2622)	(ex	45000
F9201-422	14	747008.10	3985541.04	0							
F9201-437	N 96	747006.20	3985539.88	0	n.36 57		,9	72 1	2483	\	70200
F9201-423	95 N	747004.30	3985538.72	0			_	72 /	2483	\	70200
F9201-438	2 8	747002.40	3985537.57	0				72 1	2483.		70200
F9201-424	93 2	747000.50	3985536.41	0	57,		1	72 1	(2483	英	70200
F9201-425	92 N	746986.42	3985537.12	0	57		91	7801	2248	/	143000
F9201-426	-16-	746980.26	_	0							
F9201-427	<u>ک</u> 06	746974.11	3985529.63	0	25		4,	7801	2248		143000
F9201-428	બ 68	746900.14	3985484.64	0	25	\ \ \	16	7 801	2248	>	143000
F9201-429	1	746893.98	3985480.89	0					(f	
F9201-430	87 N	746887.83	3985477.14	0	25	A /	16	108	(2248	XSV	143000
F9201,51	4	746679.06	3	0				_			
7483dm: 6-20		Jemmas =	337	5.5 0.1 5.5 6. 5.7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7	ું જ	2339 chn	43	> 3 2 dg.	Ø¥₹ U	could delete
3		,	gom o) -: -:	✓ Page 2	2	c	4	21.5	,	
•	•	きると	1			•	4 C C C				

2292 ch. 1-2 515 mg

Fried Page 2

Sweet !!!

2248 cho. 4-12 = 8 200

		- ;	I		·		1=	, ,	_	<u> </u>																					_		_
	VOLUME FLOW RATE,	(cfm)	:				00568 ~		✓ 89500											√ 45300		V 45300	•										
Kear	· EXIT VELOCITY	(m/s)		7	2 200	Sala Real	79		'n											個を		爾布	المستحد										
	DIAMETE .R	P			1		Br 15.2		4.5.4											26-15-2		7.5.20											
S	TEMPERATUR E	(K)				,	293.15		293.15								•			293.15		293.15											
SOURCES	H	(m)					13.42 771		77.0											777		77.											
Canada Mark	SOURCE BASE	ELEVATION			0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Area Kron	у-итм	(m)	300576176	3985261.20	3985263.58		3985264.02	3985267.77	3985271.51	3985277.57	3985278.73	3985279.88	3985281.04		3985305.82	3985306.98		3985309.29	3985310.45	3985316.51	3985320.25			3985375.46	3985379.27	3985383.07	3985387.44	746787.70 3985391.25	3985408.65	3985407.49	3985406.33	3985405.18	3985404.02
Stank Sprigar	х-итм	(m)	74669007	140000.97	746684.77	746686.67	746700.75	746706.90	746713.06	746723.02	746724.92	746726.82	746728.72	746730.62	746769.46	746771.36	746773.26	746775.16	746777.07	746787.03	746793.18	746799.34	746799.62	746797.30	746795.00	746792.68	746790.02	746787.70	746771.91	746770.01	746768.11	746766.21	746764.30
,		3	4	6 ¢	3 \$ -	\$	英国	l ' l	\$₩ 63	-29	to	\$	\$	-58	-23-	36	*	4.	-53-	SE 52	-15-	SE 50	-49	-48-	-46	-45	#	43	-42-	4	#	46	\$
	STACK I.D.		() E0201 (£21	F9201-351 F0201-55	F9201-532	F9201-53	F9201-54 6			_	F9201-533	F9201-58	F9201-534	F9201-59	F9201-510	F9201-535	F9201-511	F9201-536	F9201-512	F9201-513	F9201-514	F9201-515	F9201-516	F9201-517	F9201-518	F9201-519	F9201-520	F9201-521	F9201-522	F9201-537	F9201-523	F9201-538	F9201-524
- 						•	1920-	2	John -	2										- INVOL	18 Jan 1	<u>↑</u>											

bouver = mo velocity?

Q: why 2 on each Nand Swall? side by side? Page 3

Q: why 2 on each Nand Swall? side by side? Page 3

evene boy is as severe - diagram suggest boursing

						HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW	
	STACK I.D.		X-UTM	Y-UTM (m)	SOURCE BASE ELEVATION	ı (ii	ы <u>Я</u>	æ (E	VELOCITY (m/s)	RATE (cfm)	
									(G.III.)	(critis)	
Janna)	F9201,525	NE 37	746750.23	3985404.73	0	7/2	293.15	7.5	3000	V 45300	
	F9201-526	136	746744.07	746744.07 3985400.99	0						
72020 C	F9201-527	NF 35	746737.91	3985397.24	0	77	293.15	2,06	The state of the s	~ 45300	
Jana, 1	F9201-528	NE 34	746663.95		0	11	293.15	\$ ->		~ 89500	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	F9201-529		746657.79		0	87.\V		9 7 5 7 9	2037	~ arti	
John Jacob	F9201-530	NM 32	746651.63	3985344.75	0	7.2	/ 293.15	1 1/2 Sept		>	-) .
	V920444)	N 17	746541.31	3985232.83	0	0/21.6371	V V 293.15	1 21 136	• 2829	. 20000	I _s
 \.	V9204-42	91	746532.51	3985227.47	0	71	293.15		. 2829	\$ 20000	
- 3% 34 X	V9204-43	15	746523.29	3985221.87	0	11/	293.15	36	√ 3508	✓ 24800	
_ _ _ _	V9204 44	14	746514.20		0	71	293.15	98	• 2829	20000	
10	V9204-45	13	746504.99	3985210.73	0	71	293.15	36	√ 3508	~ 24800	
~ 5	V9204-46	12	746496.06	746496.06 3985205.30	0	71	293.15	36	• 2829	> 20000	
, A , , , , ,	V9204-47	11	746486.85	746486.85 3985199.69	0	71	293.15	36	√ 3508	✓ 24800	
_	V9204-48	10	746477.75	746477.75 3985194.16	0	71	293.15	36	. 2829	,	
	V9204-49	6	746468.54	746468.54 3985188.56	0	71	293.15	>	, 2829	,	4
San San		9 6	746489.9	3985184.1	0	10 4	65 🗸 293.15	09 / 12	. 2037	₹ 40000	I
Mary d		8 5	746512.7		0	201		09	. 2037	¥ 40000	
		ئ 4	746535.4	3985211.8	0			09	. 2037	V 40000	
	F9204,44		746519.9		0	5.09	59)	09	. 2037	× 40000	
	F9204-45	2 2	746497.2		0	5:09-	65	09	. 2037	× 40000	_
→	F9204-46	٦ 1	746474.4	-	0	-60.5	165 293.15	09 1	1 , 2037	V 40000	7
Now York	89201 59	3	746647.7	_	0	75	19	45- 15.4	1-el	75355	: 2
C AND TO	S9201-60	72	746657.52		0	es 45		1		75355	があれ
, C.	S9201-61	3	746667.34	3985287.94	0	- 1		_		75355	1247
1 × ×	S9201-62	7	746677.16	746677.16 3985271.80	0			>	\	75355	\supset
ط ب ر	S9201-63	NC/	746687.56	746687.56 3985344.49	0		293.15	4,		114223.13	· _
ð	S9201-64	MC	746697.38	746697.38 3985328.34	0	Ħ	293.15	Ţ	7	114223.13	3
	S9201-65	がら	746707.20	746707.20 3985312.19	0		293.15			114223.13	6 5 -
	S9201-66	NC	746717.03	746717.03 3985296.05	0		293.15	>		114223.13	} -
	S9201-67	3	746733.94	746733.94 3985372.71	0	12	293.15	۲. ک ۲. ۲	172	64267.5	~
	S9201-68	\overline{g}	746743.77	746743.77 3985356.56	0	72	293.15	1 24	42	64267.5	.ملا_

Page 4

Nothing for 9201-22

					HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW	
STACK I.D.		X-UTM		Y-UTM SOURCE BASE	Ľ	떮	æ	VELOCITY	RATE	
		(m)	(m)	ELEVATION	(m)	(K)	(m)	(s/m)	(cfm)	S.
z										0 0.
89201-69	29	746753.59	746753.59 3985340.41	0	73 64	6/ 293.15	1.51 472	78	64267.5	<u>_</u>
S9201-70	/ ショ	746763.41	746763.41 3985324.26	0	华		4	よっま	64267.5	_
S9201-71	W	746773.81	746773.81 3985396.96	0	42		54	,	31750	
S9201-72	w	746783.63	746783.63 3985380.81	0	77	293.15	54	,	31750	、 、 、 、 、 、 、 、 、 、 、 、 、 、
S9201,73	. · 9	746793.46	746793.46 3985364.66	0	7.1.	293.15	54	1	31750	18 mg
S9201-74	و <u>ان</u>	746803.27	746803.27 3985348.52	0	72	293.15	54		31750	: 3

Q.C.	Observat	tions
------	----------	-------

-	If my thing, didn't include some sources.
	no disping from (A-4) 75% roof (35% of total bldg) Not included
9201= A	A-50 louvers were bigger (with no volocity).
9202=B	miscours modernings of my sources.
	misitions moderatings of my sources. on ht. of sources For sight sources of proportionality.
having	for A-to and B-4. to vol. flow note not applied
	consistently.
- _M (3	186200:4=46550 B-40 do V sources go up or Loring?
	86200:4 = 46550 B-As do V sources go up or Loringo? Hey're shown on mob
	-> (A-2i) nothing included in modeling -
	-> (A-2) nothing included in modeling - reed to add 4.5 sources
	(81-10) temp is money who 200°F
ton	81-100 temp is wrong s/b 205°F ps suntiched Stale Ht. is 16', not 19.3'
be	Mert. 81-10 sna
	9401-12nd-2. (stm. plantsi)
	9401-15-2/temp is wrong 3/b 300°F 9401-3/ stack lit is 190', not 100'
ALMANIAN	7 9401-3/ stack lt is 190', not 100'
***************************************	Dto 2 thath
	P. Dyron Payer
	V The state of the
<u> </u>	Only 1955 modeled.
7,7	
, 14-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	

(le	news Questions
	· · · · · · · · · · · · · · · · · · ·
- 1/1	will somet model & sounds from center of woof?
1.9	Why con't model X pounds from jeenter of wof? Some sources in wall, so up, N and S needed. Why con't model X pounds from 3 sources (up, NS)?
	11 + 1 del X sounds from 3 sources (MO, MS)?
	projection make a pour of substitution would
	Why court model X pounds from 3 sources (up, NS)? ? 1 steps, volumes and velocities vonly. ft: ft3/min ft/min
	De line of the party is the
a,	If not include all 30 sources jorly 10, which
	the other 20 represent 35% of total bldg vortling
	is this a sig. ever:
	Does the underrepresentation of the area of a source
	with no velocity mobile & sig. differences?
3.	X lbs. released from a bldg. per yr. was calcid poly using total must ofm and aug bldg. an conce of folls. If all that exhaust ofm is not represented in the last of the represented in
	19 total using total sust ofm and dug bldg. In conco
20:16	of of the text exhaut of is not represented in
	the modeling then would the off-site su concs
	Tor 1? (not diluted as much >> 1)
<u> </u>	h howeld He have wall some emissions (with
	b. Would Hig from well some emissions (with velocity) het the gound sooner than mof emissions?
	Vacción de la constante de la
	Some vently, studies messured Hy conc. at the exhaust
Colly lexal 4	it with a I have after it that exhaust soints
1000	(1950) points, must plied by the common we multiplied bldg.
3.617 (A-4) 0.5-11 (B-4) 8	(1953) sig. conc. by total stag. CIM 10 esc. wis fa.
48 K A 2 1 - cfm Bldg	(1953) sug. conc. by total bldg. ctm to calc. lbs/d. 16/16/16 Exhaust pt concs were always . 2 35, ours were 4.1. (1954)
-cfm-Bldg	

					HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW
STACK I.D.		X-UTM	Y-UTM	SOURCE BASE	H	闰	×	VELOCITY	RATE
		(m)	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)
F9201-47	116	746959.21	3985409.96	0	57		72	2483	70200
F9201-433	115	746961.12	3985411.12	0					
F9201-48	114	746963.02	3985412.27	0	57		72	2483	70200
F9201-434	113	746964.92	3985413.43	0	22		72	2483	70200
F9201-49	112	746966.82	746966.82 3985414.59	0	57		72	2483	70200
F9201-410	111	747005.66	3985438.21	0	57		72	2483	70200
F9201-435	110	747007.56	3985439.37	0					
F9201-411	109	747009.46	747009.46 3985440.52	0	57		72	2483	70200
F9201-436	108	747011.36	3985441.68	0	22		72	2483	70200
F9201-412	107	747013.26	3985442.84	0	22		72	2483	70200
F9201-413	901	747023.22	747023.22 3985448.90	0	57		108	2248	143000
F9201-414	105	747029.38	3985452.64	0					
F9201-415	104	747035.53	3985456.39	0	57		108	2248	
F9201-416	103	747035.81	3985504.05	0			42	2339	22500
F9201-417	102	747033.50	3985507.85	0			42	2339	
F9201-418	101	747031.19	3985511.65	0	37		42	2339	22500
F9201-419	100	747028.87	3985515.45	0	37		42	2339	22500
F9201-420	66	747026.21	3985519.83	0	17		09	2292	45000
F9201-421	86	747023.90	3985523.64	0	17		09	2292	45000
F9201-422	16	747008.10	3985541.04	0					
F9201-437	96	747006.20	3985539.88	0	57		72	2483	70200
F9201-423	95	747004.30	3985538.72	0	57		72	2483	70200
F9201-438	94	747002.40	3985537.57	0			72	2483	70200
F9201-424	93	747000.50	3985536.41	0	57		72		70200
F9201-425	92	746986.42	3985537.12	0			108	2248	143000
F9201-426	91	746980.26	746980.26 3985533.38	0					
F9201-427	96	746974.11	746974.11 3985529.63	0			108	2248	143000
F9201-428	68	746900.14	746900.14 3985484.64	0	57		108		143000
F9201-429	88	746893.98		0					
F9201-430	87	746887.83 3985477	3985477.14	0	57		108	2248	143000
F9201-51	70	746679.06	3985260.11	0					

				,	HEIGH	HEIGH TEMPERATUR	DIAMETE	EXIT	VOLUME FLOW
STACK I.D.		х-итм	Y-UTM	SOURCE BASE	T	ম	æ	VELOCITY	RATE
		Œ	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)
F9201-531	69	746680.97	746680.97 3985261.26	0					
F9201-52	89	746682.87	3985262.42	0					
F9201-532	<i>L</i> 9	746684.77	3985263.58	0					
F9201-53	99	746686.67	3985264.73	0					
F9201-54	65	746700.75	3985264.02	0	77	293.15	06		89500
F9201-55	64	746706.90	3985267.77	0					
F9201-56	63	746713.06	3985271.51	. 0	77	293.15	06		89500
F9201-57	62	746723.02	3985277.57	0					
F9201-533	61	746724.92	3985278.73	0					
F9201-58	99	746726.82	3985279.88	0					
F9201-534	59	746728.72	3985281.04	0					
F9201-59	58	746730.62	3985282.20	0					
F9201-510	57	746769.46	3985305.82	0					
F9201-535	26	746771.36	746771.36 3985306.98	0					
F9201-511	55	746773.26	746773.26 3985308.14	0					
F9201-536	54	746775.16	3985309.29	0					
F9201-512	53	746777.07	746777.07 3985310.45	0					
F9201-513	52	746787.03	746787.03 3985316.51	0	77	293.15	06		45300
F9201-514	51	746793.18	3985320.25	0					
F9201-515	50	746799.34	3985324.00	0	77	293.15	06		45300
F9201-516	49	746799.62	3985371.66			•			
F9201-517	48	746797.30	3985375.46	0					
F9201-518	46	746795.00	3985379.27	0					
F9201-519	45	746792.68	3985383.07	0					
F9201-520	44	746790.02		0					
F9201-521	43	746787.70	3985391.25	0					
F9201-522	42	746771.91	3985408.65	0					
F9201-537	41	746770.01	3985407.49	0					
F9201-523	40	746768.11	3985406.3						
F9201-538	39	746766.21	3985405.1						
F9201-524	38	746764.30	3985404.02	0					

					HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW
STACK I.D.		X-UTM	Y-UTM	SOURCE BASE	H	田	æ	VELOCITY	RATE
		(m)	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)
			_						
F9201-525	37	746750.23		0	77	293.15	06		45300
F9201-526	36	746744.07	3985400.99	0					
F9201-527	35	746737.91	3985397.24	0	77	293.15	06		45300
F9201-528	34	746663.95	3985352.25	0	77	293.15	06		89500
F9201-529	.33	746657.79	3985348.50	0	37	293.15		2037	4000
F9201-530	32	746651.63	746651.63 3985344.75	0	77	293.15	06		89500
V9204-41	17	746541.31	3985232.83	0	71	293.15	36	2829	2000
V9204-42	16	746532.51	3985227.47	0	11	293.15	36	2829	2000
V9204-43	15	746523.29	3985221.87	0	71	293.15	36	3508	24800
V9204-44	14	746514.20	3985216.33	0	11	293.15	36	2829	. 20000
V9204-45	13	746504.99	3985210.73	0	11	293.15		3508	24800
V9204-46	12	746496.06	3985205.30	0	11/	293.15	36	2829	2000
V9204-47	Ξ	746486.85	3985199.69	0	71	293.15	36	3508	24800
V9204-48	10	746477.75	3985194.16	0	71	293.15	98	2829	2000
V9204-49	6	746468.54	3985188.56	0	71	293.15	36	2829	20000
F9204-41	9	746489.9	746489.9 3985184.1	0	60.5		09	2037	4000
F9204-42	S	746512.7	3985198	0	60.5		09	2037	4000
F9204-43	4	746535.4	3985211	0	60.5	293.15	09	2037	4000
F9204-44	3	746519.9	3985237	0	60.5	293.15	09	2037	4000
F9204-45	2	746497.2	_	0	60.5	293.15		2037	4000
F9204-46	-	746474.4	3985209	0	60.5	293.15	90	2037	40000
S9201-59		746647.7	3985320.24	0	72	293.15	54		75355
S9201-60		746657.52	746657.52 3985304.09	0	72	293.15	54		75355
S9201-61		746667.34	746667.34 3985287.94	0	72	293.15	54		75355
S9201-62		746677.16	746677.16 3985271.80	0	72	293.15	54		75355
S9201-63		746687.56	746687.56 3985344.49	0		293.15	108		114223.13
S9201-64		746697.38	746697.38 3985328.34	0	72	293.15	108		114223.13
S9201-65		746707.20	746707.20 3985312.19	0		293.15	108		114223.13
S9201-66		746717.03	746717.03 3985296.05	0	72	293.15	108		114223.13
S9201-67		746733.94	3985372.71	0					64267.5
S9201-68		746743.77	746743.77 3985356.56	0	72	293.15	54		64267.5


				HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW
STACK I.D.	MTU-X	Y-UTM	SOURCE BASE	T	ы	æ	VELOCITY	RATE
	(m)	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)
S9201-69	746753.5	746753.59 3985340.41	0	72	293.15	54		64267.5
S9201-70	746763.4	746763.41 3985324.26	0	72	293.15	54		64267.5
S9201-71	746773.8	746773.81 3985396.96	0	72	293.15	54		31750
S9201-72	746783.6	746783.63 3985380.81	0	72	293.15	54		31750
S9201-73	746793.4	746793.46 3985364.66	0	.72	\$1.865 .	54		31750
S9201-74	. 746803.2	746803.27 3985348.52	0	72	293.15	54		31750


RAUTHOUS SOURCE BASE T E R VELOCITY						HEIGH	HEIGH TEMPERATUR	DIAMETE	EXIT	VOLUME FLOW
187 747019,55 3985468,79 0 45° 26° 5° 5° 5° 5° 5° 5° 5°	STACK I.D.		X-UTM	Y-UTM	SOURCE BASE	П	Ħ	~	VELOCITY	RATE
187 747019.55 3985468.79 0 45° 200.7 200.7 200.7 200.9 200			(m)	(m)	ELEVATION	(m)	(K)	(III)	(m/s)	(cfm)
187 747019.55 3985408.879 0 95 2020.5 575 2020.6 55 525										
186 747009.73 3985484.94 0 185 747009.73 3985481.08 185 746099.09 3985317.23 184 746099.09 3985317.23 184 746090.38 3985341.24 187 746093.31 3985446.74 746093.81 3985346.74 746093.81 3985346.74 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985348.80 746097.81 3985336.16 746097.81 3985330.16 746097.81 3985330.16 746097.81 3985330.16 746097.81 3985330.16 746097.81 3985330.16 746097.81 3985330.10 746097.81 3987300.10 746097.81 3987300.10 746097.81 3987300.10 746097.81 3987300.10 746097.81 3987300.10 746097.81 388700.10 746097.81 388700.10 74609	S9201-4 t	187	747019.55	3985468.79	0	93'2	√	54%	2 Zer (35000
185 746999.91 3985301.08	S9201-42	186	747009.73	3985484.94	0	Ť	•-			
184 746990.00 3985517.23	S9201-4 3	185	746999.91	3985501.08						
183 746933.27 3985416.30	S9201-4 W	184	746990.09						-	
182 746923.45 3985432.45	S9201-4 &	183	746933.27	_						
181 746913.63 3985448.60	S9201-4 💪	182	746923.45							
180 746903.81 3985464.74 44 45 45 45 45 45 45	S9201-4 3	181	746913.63							
179 746783.36 3983336.40 43; 179 74678.36 3983336.40 43; 177 746678.31 3983388.89 44 44 746678.28 3983388.81 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 746677.44 398339.35 74667.61 398339.35 74667.61 398339.35 746697.80 398339.36 74667.81 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.36 74697.80 398339.30 7467.80 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80 398339.30 74697.80	S9201-4 #	180	746903.81			>		→)	→
178 746773.54 398338.65	S9201-5 /	179	746783.36	3985336.40		43;		Market !		761000
177 746763.71 3985368.69	S9201-5 2	178	746773.54	3985352.55		!				76000
176 74673.89 398384.84	S9201-5 3	177	746763.71	3985368.69						74000
175 746697.08 3985283.91 446677.44 3985300.06 446697.08 3985300.06 446697.26 3985300.06 446697.26 3985302.35 46667.61 3985302.35 46667.61 3985302.36 46667.61 3985305.36 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 3985306.16 46697.26 46697.26 3985306.16 46697.26 46	S9201-5 -\	176	746753.89	3985384.84				>		76000
174 746687.26 398530.06	S9201-5 S	175	746697.08	3985283.91		-				46200
173 74667.44 398316.21	S9201-5 6	174	746687.26	3985300.06				•		46000
171 746667.61 398532.35	と9201-5 ナ	173	746677.44	3985316.21			*			46200
146 748020.91 398023.46 700' Sec. 7 72.5' 135 747175.14 398329.55 0 5,484 200° 7 14' 17.5' 134 747083.59 3983285.07 100' Sec. 7 72.5' 12.5'	89201-5 %	171	746667.61	3985332.35		>	293.15			46200
135 747175.14 3985329.55 0 5 6 7 7 7 7 7 7 7 7 7	S9401-1(146	748020.91	3986023.46	•	1001	3000	12.51		
134 747083.59 3985385.07 100° 300° F 72.5° 132 746962.56 3985306.16 100° 300° F 75° 15° 166° F 66° F 75° 15° 166° F 66° F 746501.30 3985191.05 746501.30 3985191.05 746919.06 3985392.50 746919.06 3985393.65 524° 5243.15 746919.06 3985393.65 524° 5243.15 746922.86 3985395.95 524° 5243.15 746922.86 3985397.12 110 746922.86 3985397.12 524° 524	S81-10 (135	747175.14	3985329.55	0	S. 884		142		1300
132 746929.02 3985306.16 100° \$Coo° F 12° 12° 146962.56 3985326.57 100° \$Coo° F 15° 166° F 6° 15° 166° F 6° 166° F 16° F	S9401-2 ₁	134	747083.59	3985385.07		1001	3005	12.5'		
132 746962.56 3985326.57 100' 50 e" T 15' 1667 6' 17' 17 16' 16' 16' 16' 17 16' 16' 17 16' 16' 17 16' 17 16' 17 16' 17 16' 17 17 17 17 17 17 17 1	S9401-3 ₁	133	746929.02	3985306.16		1001	300°F	12.5'		
8 746501.30 3985191.05 76 703.17 314601.4 3985204.88 76 746524.04 3985204.88 766524.04 3985392.50 2463 <	S9401-32	132	746962.56	3985326.57		1001	3000	151		
7 746524.04 3985204.88 76 76524.04 3985204.88 76 77 76 76 77 76 77 76 77 76 77 76 77 76 77 76 77 76 77 76 77 76 77 76 77 76 77 77 77 77 77 77 77 77 77 77 77 77 77 7	S9204-4 i	8	746501.30	3985191.05		36,	13.1	3.18	1667	60000
124 746915.26 3985392.50	S9204-4 2	7	746524.04	3985204.88		36	43	811	1667	Sapeo
122 746919.06 3985392.65 574 293.75 72 2 4 8 3	E9201-4	124	746915.26	3985392.50						
122 746919.06 3985394.81	F9201-437	123	746917.16	3985393.65		725	293.15	75.	2483	30205
121 746920.96 3985395.96 ST' 293.15 T2 2483 120 746922.86 3985397.12 ST' 293.15 TOB' 2248 119 746943.10 3985403.90 0 57' 293.15 (08' 2248)	F9201-4 2	122	 746919.06	3985394.81						
120 746922.86 3985397.12	F9201-4 32	121	746920.96	-3985395.96	-	くたら	29.15	72.4	2483	70200
119 746936.94 3985396.41 S 24' 243.15 108' 72 48 118 746943.10 3985400.16 8 5 7' 243.15 108' 22 48 1	F9201-43	128	-746922:86	-3985397:12			,	*		.
118 746943.10 3985400.16 5 7' 293 15 108° 2248 1	F9201-4 4	119	746936.94	3985396.41		725	43.1	_ ~	2248	143000
117 746949.25 3985403.90 0 57 293 5 1086 2248	F9201-4 S	1	746943.10	3985400.16	A.					
	F9201-4 6	117	746949.25	3985403.90	Q.	145	29315	1080	2248	143000


					HEIGH	HEIGH TEMPERATUR DIAMETE	DIAMETE	EXIT	VOLUME FLOW	
STACK I.D.		х-итм	Y-UTM	SOURCE BASE	T .	Э.	~	VELOCITY	RATE	
		(II)	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)	₁
F9201-4 7	116	746959.21	746959.21 3985409.96	C'	1 + 2	,	、こさ、	2483	40200	<u> </u>
F9201-4-33	115	746961.12	746961.12-3985411.12	<u> </u>						_
F9201-4 &	114	746963.02	3985412.27		. たら		38 t	2463	corot	
F9201-4 3 1	113	746964.92	3985413.43		145		424	276.	30205	_
F9201-44	112	746966.82			145		+2:	2487	30200	
F9201-4 10	111	747005.66	3985438.21		ゾゲン		724	2 783	20205	
F9201-435	110	747007.56	747007.56_3985439.37							
F9201-411	109	747009.46	3985440.52		\			-		1
F9201-436	108	747011.36	3985441.68		>		Ą	_}	->	_
F9201-4/2	107	747013.26	3985442.84		57'		コン・スト	2483	70200	_
F9201-413	106	747023.22	3985448.90		1+5		108"	2248	143000	
F9201-4	105	747029.38	747029.38 3985452.64							
F9201-4 i s	104	747035.53	747035.53 3985456.39		125		.801	3248	143000	
F9201-4 /6	103	747035.81	3985504.05		33,		77.7	2339 8.	72500	
F9201-4 / 7	102	747033.50	747033.50 3985507.85		34,		12,	2334 Jon	29500	_
F9201-4 18	101	747031.19	747031.19 3985511.65		57,		724	233 4 80m	22500	
F9201-4 14	100	747028.87	747028.87 3985515.45	-	33,		,,2,	2339 YOM	22500	
F9201-420	66	747026.21	3985519.83	Q	14/	29315	\$ 0° 2	2292 APM	45000	T
F9201-4 LJ	86	747023.90	747023.90 3985523.64	a	رځ/		509	2252 don	45000	
F9201-472		747008-10	747008-10 3985541:04	-	,					
F9201-437	96	747006.20	3985539.88	-	125		ナマナ	2463	のつれの大路	1
F9201-42.3	95	747004.30			_				70,00	
F9201-43 &	94	747002.40			۲			٠;	क् ० २०६	T
F9201-4 2 4	93	747000.50			521		72,	2483	70200	Т
F9201-4 25	92∗	746986.42	3985537.12		125		10801	2248	148,000	
E9201-426	91	746980.26	3985533.38	•			*** ** * * *			
F9201-422	≯06	746974.11	3985529.63		745		1080	2248	143,000	
F9201-428	i 68	746900.14	3985484.64		145		(08	2248	143,000	ſ
F9201-424	-88	746893.98	746893.98 3985480.89	ν. <u> </u>		•			ŧ	Ť
F9201-430	87.	746887.83	746887.83 3985477.14	3	571	À	106	2298	143000	7
F9201-5 \	70	746679.06	746679.06 3985260.11	ŀ						٦


				HEIGH	HEIGH TEMPERATUR	DIAMETE	EXIT	VOLUME FLOW
STACK I.D.	X-UTM	Y-UTM	SOURCE BASE	H	田	æ	VELOCITY	RATE
	(m)	(m)	ELEVATION	(m)	(K)	(m)	(m/s)	(cfm)
F9201-5 34 69	746680.97	3985261.26						
F9201-52 68	746682.87	3985262.42						
F9201-534 67	746684.77	3985263.58						
F9201-5 3 66	746686.67							
F9201-5 4 65	746700.75	_		77.	243 15	905	•	89.500
F9201-5 ≤ 64	746706.90	3985267.77						
F9201-5 & 63	746713.06			144	293.15	900		65500
F9201-5 7 62	746723.02							
F9201-53 5 61	746724.92	746724.92 3985278.73						
F9201-5 8 60	746726.82	746726.82 3985279.88						
F9201-5 3-7 59	746728.72	746728.72 3985281.04						
F9201-54 58	746730.62	746730.62 3985282.20						
F9201-510 57	746769.46	746769.46 3985305.82						
F9201-5 35 56	746771.36	746771.36 3985306.98						
F9201-5 / / 55	746773.26	746773.26 3985308.14						
F9201-53¢ 54	746775.16							
F9201-5 12 53	746777.07							
F9201-5 13 52	746787.03	3985316.5		144	293.15	40,		45300
F9201-514 51	746793.18	_						
F9201-5 , s 50	746799.34			7,7	293.15	40è		75200
F9201-5;6 49	746799.62	3985371.66						
F9201-5 / 4 48	746797.30	3985375.46						
F9201-5 / \$ 46	746795.00	3985379.27						
F9201-5 / 9 45	746792.68	3985383.07						
F9201-520 44	746790.02	3985387.44						
F9201-521 43	746787.70	746787.70 3985391.25						
F9201-522 42	746771.91							
F9201-537 41	746770.01	3985407,4						
F9201-523 40	746768.11	3985406.3						
F9201-536 39	746766.21	3985405.1						
F9201-524 38	746764.30	3985404.02						


			_	 T		<u>~</u>	1	工	<u>></u>	<u>-</u>	 						>	I				<u>,</u>	>	
VOLUME FLOW	RATE (cfm)		453,00		4 500	89.000	7		3000	00000	20000	2000	146000	30000	00316	20003	20000	40,000	-				>	
EXIT	VELOCITY (m/s)						27.6	20021	2 4 6	2000	3000	2000	3078	282	2002	287.9	2824	4. 5.00	2				>	
DIAMETE	8 (1)	(mm)	1	70	405	207	76	00	40	36%	+							120	H // S	+		\\ \-\-	*	
HEIGH TEMPERATUR DIAMETE	B	(4)	1, 1,	293.13			-> !	295.18		29315		+						1	243.13	-			\	
нетсн	T ((m)		74		+	7	47	44	3),	+		+	-	-	-			66.5	+	+	+	*	
	SOURCE BASE	ELEVATION		0																				5
-	Y-UTM	(m)		3985404.73	3985400.99	3985397.24	3985352.25	746657.79 3985348.50	746651.63 3985344.75	746541.31 3985232.83	746532.51 3985227.47	746523.29 3985221.87	746514.20 3985216.33	746504.99 3985210.73	746496.06 3985205.30	746486.85 3985199.69	746477.75 3985194.16	m	3	3985198				3985209.6
-	X-UTM	(m)		746750.23 3985404.73	746744.07 3985400.99	746737.91 3985397.24	746663.95 3985352.25	746657.79	746651.63	746541.31	746532.51	746523.29	746514.20	746504.99	746496.06	746486.85	746477.75	746468.54	746489.9	746512.7	746535.4	746519.9	746497.2	746474.4
				37	36	35	34	33	32	17	16	15	14	13	12	=	10	6	9	S	4	3	2	1
	STACK I.D.			F9201-5 26	F9201-5	F9201-509	F9201-5-0	F0201-576	F9201-5	V9204-4 /	V9204-4 '2,	V9204-4 8	V9204-4	V9204-4	V9204-4 /	V9204-4 7	V9204-4 &	V9204-4 A	F9204-4	F9204-4 7	F9204-4 2	F9204-4	F9204-4 <	F9204-4 (2



























-

1



STACK I.D.		FRACTION OF MERCURY	MERCURY E	MISSION
	VOLUME FLOW RATE	EMITTED FROM EACH SOURCE		
	(cfm)	(unitless)	lb/yr	g/s
TOTAL MERCURY EMISSI	ONE EDOM 0201 4 EOD T	HE VEAD 1055 (Ib/sm)	9280.00	
TOTAL MERCURY EMISSI	UNS FROM 9201-4 FOR 1	HE TEAK 1955 (ID/yr)	9280.00	
S9201-41	35000	0.01353	125,56054	0.00181
S9201-42	35000	0.01353	125.56054	0.00181
S9201-43	35000	0.01353	125.56054	0.00181
S9201-43	35000	0.01353	125.56054	0.00181
S9201-44 S9201-45	35000	0.01353	125.56054	0.00181
S9201-45	35000	0.01353	125.56054	0.00181
S9201-40	35000	0.01353	125.56054	0.00181
S9201-47	35000	0.01353	125.56054	0.00181
				·
F9201-44	143000	0.05528	513.00448	0.00738
F9201-46	143000	0.05528	513.00448	0.00738
F9201-47	70200	0.02714	251.83857	0.00362
F9201-48	70200	0.02714	251.83857	0.00362
F9201-49	70200	0.02714	251.83857	0.00362
F9201-410	70200	0.02714	251.83857	0.00362
F9201-411	70200	0.02714	251.83857	0.00362
F9201-412	70200	0.02714	251.83857	0.00362
F9201-413	143000	0.05528	513.00448	0.00738
F9201-415	143000	0.05528	513.00448	0.00738
F9201-416	22500	0.00870	80.71749	0.00116
F9201-417	22500	0.00870	80.71749	0.00116
F9201-418	22500	0.00870	80.71749	0.00116
F9201-419	22500	0.00870	80.71749	0.00116
F9201-420	45000	0.01740	161.43498	0.00232
F9201-421	45000	0.01740	161.43498	0.00232
F9201-423	70200	0.02714	251.83857	0.00362
F9201-424	70200	0.02714	251.83857	0.00362
F9201-425	143000	0.05528	513.00448	0.00738
F9201-427	143000	0.05528	513.00448	0.00738
F9201-428	143000	0.05528	513.00448	0.00738
F9201-430	143000	0.05528	513.00448	0.00738
F9201-431	70200	0.02714	251.83857	0.00362
F9201-431 F9201-432	70200	0.02714	251.83857	0.00362
199701-434	70200	0.02714	251.83857	0.00362
F9201-436	70200	0.02714	251.83857	0.00362
F9201-437	70200	0.02714	251.83857	0.00362
F9201-438	70200	0.02714	251.83857	0.00362
TOTAL FLOW RATE (cfm)	2586800			
TOTAL MERCURY EMISSI	ONS FROM 9201-5 FOR T	HE YEAR 1955 (lb/yr)	9212.00	
S9201-51	76000	0.03438	316.73794	0.00456
	76000	0.03438	316.73794	0.00456
S9201-52	76000	0.03438	316.73794	0.00456
S9201-53				
S9201-54	76000	0.03438	316.73794	0.00456
S9201-55	46200	0.02090	192.54333	0.00277
S9201-56	46200	0.02090	192.54333	0.00277
S9201-57	46200	0.02090	192.54333	0.00277

STACK I.D.		FRACTION OF MERCURY	MERCURY E	MISSION
	VOLUME FLOW RATE	EMITTED FROM EACH SOURCE		
	(cfm)	(unitless)	lb/yr	g/s
S9201-559	75355	0.03409	314.04983	0.00452
S9201-560	75355	0.03409	314.04983	0.00452
	75355	0.03409	314.04983	0.00452
S9201-561	75355	0.03409	314.04983	0.00432
S9201-562	114223.13	0.03409	476.03682	0.00432
S9201-563		0.05168	476.03682	0.00685
S9201-564	114223.13	0.05168	476.03682	0.00685
S9201-565	114223.13	0.05168	476.03682	0.00685
S9201-566	114223.13		267.84152	
S9201-567	64267.5	0.02908		0.00385
S9201-568	64267.5	0.02908	267.84152	0.00385
S9201-569	64267.5	0.02908	267.84152	0.00385
S9201-570	64267.5	0.02908	267.84152	0.00385
S9201-571	31750	0.01436	132.32144	0.00190
S9201-572	31750	0.01436	132.32144	0.00190
S9201-573	31750	0.01436	132.32144	0.00190
S9201-574	31750	0.01436	132.32144	0.00190
S9201-58	46200	0.02090	192.54333	0.00277
F9201-54	89500	0.04049	373.00060	0.00536
F9201-56	89500	0.04049	373.00060	0.00536
F9201-513	45300	0.02049	188.79248	0.00272
F9201-515	45300	0.02049	188.79248	0.00272
F9201-525	45300	0.02049	188.79248	0.00272
F9201-527	45300	0.02049	188.79248	0.00272
F9201-528	89500	0.04049	373.00060	0.00536
F9201-529	40000	0.01810	166.70418	0.00240
F9201-530	89500	0.04049	373.00060	0.00536
TOTAL FLOW RATE (cfm)	2210382.52			
TOTAL MERCURY EMISSIO	NS FROM STEAM PLANTS	5 1 & 2 FOR THE YEA <u>R 1955 (lb/yr)</u>		77
S9401-11 (Steam Plant 1)*		NA	38.5	0.00055
S9401-21 (Steam Plant 2)*		NA	38.5	0.00055
* The emissions for the steam p	lant are assumed to be equal i			
TOTAL MERCURY EMISSI	ON FROM 81-10 FOR TH	E YEAR 1955 (lb/vr)	0.00	
S81-101	1300	NA	0.00	0.00
TOTAL MERCURY EMISSI	ONS FROM STEAM PLAN	NT 3 FOR THE YEAR 1955 (lb/yr)		0.00
			0.00	0.00
S9401-31		NA NA	0.00	0.00
S9401-32		NA	0.00	0.00
TOTAL MERCURY EMISS	ON FROM 9204-4 FOR TH	IE YEAR 1955 (lb/yr)	2767.00	
00004.41	60000	0.10823	299.45887	0.00431
S9204-41				0.00431
S9204-42	60000	0.10823	299.45887	0.00431

STACK I.D.		FRACTION OF MERCURY	MERCURY E	MISSION
	VOLUME FLOW RATE	EMITTED FROM EACH SOURCE		
	(cfm)	(unitless)	lb/yr	g/s
V9204-41	20000	0.03608	99.81962	0.00144
V9204-42	20000	0.03608	99.81962	0.00144
V9204-43	24800	0.04473	123.77633	0.00178
V9204-44	20000	0.03608	99.81962	0.00144
V9204-45	24800	0.04473	123.77633	0.00178
V9204-46	20000	0.03608	99.81962	0.00144
V9204-47	24800	0.04473	123.77633	0.00178
V9204-48	20000	0.03608	99.81962	0.00144
V9204-49	20000	0.03608	99.81962	0.00144
F9204-41	40000	0.07215	199.63925	0.00287
F9204-42	40000	0.07215	199.63925	0.00287
F9204-43	40000	0.07215	199.63925	0.00287
F9204-44	40000	0.07215	199.63925	0.00287
F9204-45	40000	0.07215	199.63925	0.00287
F9204-46	40000	0.07215	199.63925	0.00287
TOTAL FLOW RATE (cfm)	554400			
Notes:				
(1)		ed on information provided by Earnie Choa	ts and on enginee	ering
		ty of operations and fan sizes.		
		d = Volume flow rate / Total volume flow r		
(3)	Mercury Emission = Fractio	n of mercury emitted * Total mercury emis	sions	

STACK I.D.		FRACTION OF MERCURY	MERCURY E	MISSION
	VOLUME FLOW RATE	EMITTED FROM EACH SOURCE		1,11001011
	(cfm)	(unitless)	lb/yr	g/s
TOTAL MERCURY EMISSI	ONS FROM 9201-4 FOR T	HE YEAR 1955 (lb/yr)	9280.00	
S9201-41	35000	0.01353	125.56054	0.00181
S9201-42	35000	0.01353	125.56054	0.00181
S9201-43	35000	0.01353	125.56054	0.00181
S9201-44	35000	0.01353	125.56054	0.00181
S9201-45	35000	0.01353	125.56054	0.00181
S9201-46	35000	0.01353	125.56054	0.00181
S9201-47	35000	0.01353	125.56054	0.00181
S9201-48	35000	0.01353	125.56054	0.00181
F9201-44	143000	0.05528	513.00448	0.00738
F9201-46	143000	0.05528	513.00448	0.00738
F9201-47	70200	0.02714	251.83857	0.00362
F9201-48	70200	0.02714	251.83857	0.00362
F9201-49	70200	0.02714	251.83857	0.00362
F9201-410	70200	0.02714	251.83857	0.00362
F9201-411	70200	0.02714	251.83857	0.00362
F9201-412	70200	0.02714	251.83857	0.00362
F9201-413	143000	0.05528	513.00448	0.00738
F9201-415	143000	0.05528	513.00448	0.00738
F9201-416	22500	0.00870	80.71749	0.00116
F9201-417	22500	0.00870	80.71749	0.00116
F9201-418	22500	0.00870	80.71749	0.00116
F9201-419	22500	0.00870	80.71749	0.00116
F9201-420	45000	0.01740	161.43498	0.00232
F9201-421	45000	0.01740	161.43498	0.00232
F9201-423	70200	0.02714	251.83857	0.00362
F9201-424	70200	0.02714	251.83857	0.00362
F9201-425	143000	0.05528	513.00448	0.00738
F9201-427	143000	0.05528	513.00448	0.00738
F9201-428	143000	0.05528	513.00448	0.00738
F9201-430	143000	0.05528	513.00448	0.00738
F9201-431	70200	0.02714	251.83857	0.00362
F9201-432	70200	0.02714	251.83857	0.00362
F9201-434	70200	0.02714	251.83857	0.00362
F9201-436	70200	0.02714	251.83857	0.00362
F9201-437	70200	0.02714	251.83857	0.00362
F9201-438	70200	0.02714	251.83857	0.00362
TOTAL FLOW RATE (cfm)	2586800			
TOTAL MERCURY EMISSI	ONS FROM 9201-5 FOR T	HE YEAR 1955 (lb/yr)	9212.00	
S9201-51	76000	0.03438	316.73794	0.00456
S9201-51	76000	0.03438	316.73794	0.00456
S9201-52 S9201-53	76000	0.03438	316.73794	0.00456
S9201-53	76000	0.03438	316.73794	0.00456
S9201-55	46200	0.03438	192.54333	0.00430
S9201-55	46200	0.02090	192.54333	0.00277
S9201-56	46200	0.02090	192.54333	0.00277
37201-37	40200	0.02070	174,34333	0.00277

STACK I.D.	YOU UME ELOW DATE	FRACTION OF MERCURY	MERCURY	EMISSION
	VOLUME FLOW RATE (cfm)	EMITTED FROM EACH SOURCE	ļ	
	(CIII)	(unitless)	lb/yr	g/s
S9201-559	75355	0.03409	314.04983	0.00452
S9201-560	75355	0.03409	314.04983	0.00452
S9201-561	75355	0.03409	314.04983	0.00452
S9201-562	75355	0.03409	314.04983	0.00452
S9201-563	114223.13	0.05168	476.03682	0.00432
S9201-564	114223.13	0.05168	476.03682	0.00685
S9201-565	114223.13	0.05168	476.03682	0.00685
S9201-566	114223.13	0.05168	476.03682	0.00685
S9201-567	64267.5	0.02908	267.84152	0.00385
S9201-568	64267.5	0.02908	267.84152	
S9201-569	64267.5	0.02908		0.00385
S9201-570	64267.5	0.02908	267.84152	0.00385
S9201-571	31750		267.84152	0.00385
S9201-572	31750	0.01436 0.01436	132.32144	0.00190
S9201-572 S9201-573	31750	The state of the s	132.32144	0.00190
S9201-574	31750	0.01436	132.32144	0.00190
S9201-58		0.01436	132.32144	0.00190
F9201-54	46200 89500	0.02090	192.54333	0.00277
F9201-56		0.04049	373.00060	0.00536
	89500	0.04049	373.00060	0.00536
F9201-513	45300	0.02049	188.79248	0.00272
F9201-515	45300	0.02049	188.79248	0.00272
F9201-525	45300	0.02049	188.79248	0.00272
F9201-527	45300	0.02049	188.79248	0.00272
F9201-528	89500	0.04049	373.00060	0.00536
F9201-529	40000	0.01810	166.70418	0.00240
F9201-530	89500	0.04049	373.00060	0.00536
TOTAL FLOW RATE (cfm)	2210382.52			
TOTAL MERCURY EMISSION	NS FROM STEAM PLANTS	1 & 2 FOR THE YEAR 1955 (lb/yr)		77
S9401-11 (Steam Plant 1)*		NA	38.5	0.00055
S9401-21 (Steam Plant 2)*	-	NA	38.5	0.00055
* The emissions for the steam plant	ant are assumed to be equal for	or steam plant 1 & 2		0,0000
TOTAL MERCURY EMISSION	ON FROM 81-10 FOR THE	YEAR 1955 (lb/yr)	0.00	
601.101				
S81-101	1300	NA	0.00	0.00
TOTAL MERCURY EMISSION	ONS FROM STEAM PLAN	T 3 FOR THE YEAR 1955 (lb/yr)		0.00
S9401-31		NA	0.00	0.00
S9401-32		NA NA	0.00	0.00
		IVA	0.00	0.00
TOTAL MERCURY EMISSIO	ON FROM 9204-4 FOR THI	E YEAR 1955 (lb/yr)	2767.00	
S9204-41	60000	0.10823	299.45887	0.00431
S9204-42	60000	0.10823	299.45887	0.00431
		0.10023	422,42001	0.00431

STACK I.D.		FRACTION OF MERCURY	MERCURY E	MISSION
	VOLUME FLOW RATE	EMITTED FROM EACH SOURCE		
	(cfm)	(unitless)	lb/yr	g/s
V9204-41	20000	0.03608	99.81962	0.00144
V9204-42	20000	0.03608	99.81962	0.00144
V9204-43	24800	0.04473	123.77633	0.00178
V9204-44	20000	0.03608	99.81962	0.00144
V9204-45	24800	0.04473	123.77633	0.00178
V9204-46	20000	0.03608	99.81962	0.00144
V9204-47	24800	0.04473	123.77633	0.00178
V9204-48	20000	0.03608	99.81962	0.00144
V9204-49	20000	0.03608	99.81962	0.00144
F9204-41	40000	0.07215	199.63925	0.00287
F9204-42	40000	0.07215	199.63925	0.00287
F9204-43	40000	0.07215	199.63925	0.00287
F9204-44	40000	0.07215	199.63925	0.00287
F9204-45	40000	0.07215	199.63925	0.00287
F9204-46	40000	0.07215	199.63925	0.00287
TOTAL FLOW RATE (cfm)	554400			

Notes:				<u> </u>
(1)	l	ed on information provided by Earnie Choa	ts and on enginee	ring
		ty of operations and fan sizes.		
		I = Volume flow rate / Total volume flow r		
(3)	Mercury Emission = Fractio	n of mercury emitted * Total mercury emis	sions	